

#### SITE INFORMATION

*SURVEY DA	TE: December 5, 20	12 *ADDRESS:	30242 Greenfield Road								
*SURVEY	*COUNTY:	Clay									
	*CITY:	Beresford									
LOCATION DESCRI	PTION: Vermillion,	from the intersection of Sou	th Dakota	Highv	vay 5	50 bi-	pass	and			
University Road, North 15 miles to 303 <sup>rd</sup> Street, turn right (East) about 3 miles to Greenfield road, turn											
Left (North) about 3	/4 mile on the right (E	ast) side									
LEGAL DESCRIPTION	ON: S ½, NW ¼, 3	5 – 95 – 51 Glenwood Twp.									
			Evale Kay & Geanelle Mae								
*QUARTER 1:	OWNER NAME:										
*QUARTER 2:		OWNER ADDRESS:	1208 E 38 <sup>th</sup>								
*TOWNSHIP: _	Glenwood	OWNER CITY:	Sioux Falls								
*RANGE: _	51	OWNER STATE:	South Dakota								
*SECTION:	35	OWNER ZIP:	57105-60	24							
ACRES: _	79.37	QUAD NAME:									
OWNER CODE 1:	Р										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGNI	FICANCE										
	DEGIGTED NA	DECIOTED MANE									
*DC											
*DOE DAT	-	MULTIPLE PR	OPERTY	NAME	: _						
REASON INELIGIBI	-E:										
			C A 7	reco	DV.						
NOMINIATION	SICNII	CATEGORY:									
NOMINATION		SIGNIFICANCE LEVEL 1: N S L SIGNIFICANCE LEVEL 2: N S L									
	E LISTED: NUMBER:		FICANCE			IN	3	L			
	TRATING: C or N		ERIA 1: A		_	D					
THE TORIO DISTRIC	PERIOD:	• • • • • • • • • • • • • • • • • • • •	ERIA 1. A								
	i Likiob		ERIA 3: A								
			ERIA 4: A								
		OKIIL	-NA 7. F	, D	J	0					
SIGNIFICANCE NOT	ES:										


#### STRUCTURE DETAILS



SHPO ID:											
*PROPERTY NAME:											
OTHER NAME:											
CURRENT FUNCTION:	Storage		FOUND	ATION:	Poured concrete foundation						
CURRENT SUBFUNCTION:	Storage		ROOF MAT	ERIAL:	Steel roofing over cedar shingles						
HISTORIC FUNCTION:	Livestock barn		ROOF S	HAPE:	Gambrel roof						
HISTORIC SUBFUNCTION:	Hay and grain storage		STRUCTURAL SY	STEM:	Balloon framing						
			\$	STYLE:	Gambrel roof barn						
OCCUPIED:	No			TYPE:	Livestock barn						
	Yes with			,,,,,,	2x4 studs with 1x6 #106 drop siding and ½"x6" cedar						
ACCESSIBLE:	permission		V	VALLS:	lap siding						
STORIES:	2	SI	GNIFICANT PERSON:	ı	Herman Westburg						
*DATE OF CONSTRUCTION:			TURAL AFFILIATION:	-	?						
ALTERED/MOVED NOTES: Original site. Parts of the horse stalls have been removed. Roof covered steel roofing. Original 1x6 #1x6 drop siding has been covered with ½"x6" cedar lap siding.											
	-										
INTERIOR NOTES: Has two	rows of 4x6 posts	s, with 6	x6 for a beam. 2x8 flo	or joists	for hayloft floor.						
Six milk cow stanchions with feed troughs, granary and calf pen are still in place. Horse stalls have been converted into pens, but some evidence is still visible. Granary extends from first floor up through hayloft floor and 4'-6" into hayloft.											
OTHER NOTES: 2x4 stud w		drop si	ding and ½"x6" cedar	lap sidi	ng added later. 2x4						
rafters with 2x4 bracing from center of lower rafter down to bottom of wall in hayloft and 2x4 brace at											
hip on each rafter, 2' O. C Windows are 9"x12" four light. Small metal cupola.											
-			-								
*PHYSICAL NOTES: Barn is	s in very good cor	ndition.									
*UTM ZONE:			*RESTRICTED	): Y o	r N						
*UTM EASTING:											
*UTM NORTHING:											



#### SKETCH MAP







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 5, 2012

**ROLL NUMBER:** PHOTO NUMBER:

First floor, looking East, six milk cow stanchions and feed trough on North

CAMERA DIRECTION: wall



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 5, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: granary in NW corner

First floor, looking West,





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 5, 2012

**ROLL NUMBER:** PHOTO NUMBER:

First floor, looking SW, calf pen and stairs in SW

CAMERA DIRECTION: corner



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 5, 2012

**ROLL NUMBER:** PHOTO NUMBER:

6

Hayloft, looking SE, 2x4lower bracing from rafters down to wall at

CAMERA DIRECTION: floor level





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 5, 2012** 

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking SE, 2x4

CAMERA DIRECTION: bracing at hip



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone **December 5, 2012** 

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking North, two 2x6 bracing on gable end walls, note grain bin extending through

CAMERA DIRECTION: hayloft floor.





© Farm & Home Publishers, Ltd. 23 CLAY CO., SD



#### **HISTORY**

This farm located in the S ½ of the NW ¼ in Section 35, Glenwood Township, Clay County was homesteaded by Steven Roubertson.

The 1894 Clay County Atlas lists P. Brannan as the owner.

The 1901 Clay County Atlas lists Martha Westberg as the owner.

The 1912 and 1924 Clay County Atlas lists Herman Westberg as the owner. It is very likely that Herman Westberg built or had this barn built.

The 1937 Clay County Atlas lists A. E. Odeen as the owner.

The 1948 Clay County Atlas lists Anna Odeen as the owner.

The 1956 Clay County Atlas lists Win Abraham as the owner.

