

#### **SITE INFORMATION**


*SURVEY DATE: May 23, 201	2 *ADDRESS:	Vacant, S	SW 1/2	of S	Sec. 2	2, Riv	erside/		
*SURVEYOR: Jim Stone	*COUNTY:								
<u> </u>		Wakonda	a						
	OII I.	- Wakona	<u>и</u>						
LOCATION DESCRIPTION: From th									
Dakota highway 19, North 13 miles or									
parking lot walk SE back into the tree	s about 300 yards. Weathered I	oarn blends	righ	t into	the the	land	scape.		
LEGAL DESCRIPTION: S ½ SW ¼ E									
W 235' of S 120' N 285' EXC the W 50	' SW ¼ & EXC Lots H1 & H2 2 -	- 94 – 52 P	leasa	ant V	alley	Twp	)		
*QUARTER 1: <u>SW 1/4</u>	=	Hubert Gregoire Trust							
*QUARTER 2:	OWNER ADDRESS:	46078 305 <sup>th</sup> Street							
*TOWNSHIP: Pleasant Valley	OWNER CITY:	Wakonda							
*RANGE: <u>52</u>	OWNER STATE:	South Dakota							
*SECTION: 2	OWNER ZIP:	57073							
ACRES: 73.55	_ QUAD NAME:								
OWNER CODE 1: P									
OWNER CODE 2: F S L P									
OWNER CODE 3: F S L P									
HISTORIC SIGNIFICANCE									
*DOE:	REGISTER NAME:								
*DOE DATE:	MULTIPLE PR	MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE:									
		CAT	EGO!	RY:					
NOMINATION STATUS:	SIGNI	SIGNIFICANCE LEVEL 1: N S L							
DATE LISTED:	SIGNI	FICANCE L	EVEI	<b>_ 2</b> :	N	S	L		
REFERENCE NUMBER:									
HISTORIC DISTRICT RATING: C of		ERIA 1: A	В	С	D				
PERIOD:		ERIA 2: A							
		ERIA 3: A							
		ERIA 4: A							
	O	-IVIA 7. A							
SIGNIFICANCE NOTES:									
SIGNIFICANCE NOTES:									



STRUCTURE DETAILS										
SHPO ID:										
*PROPERTY NAME:			•							
OTHER NAME:										
0 111211 111 1112										
<b>CURRENT FUNCTION:</b>	Vacant		FOUNDA	TION:	Poured concrete					
<b>CURRENT SUBFUNCTION:</b>			ROOF MATE	RIAL:	Cedar shingles					
HISTORIC FUNCTION:	Livestock barn		ROOF SI	HAPE:	Gambrel					
<b>HISTORIC SUBFUNCTION:</b>	Hay and grain storage		STRUCTURAL SYS	STEM:	Balloon framing					
			S	TYLE:	Gambrel roof barn					
OCCUPIED:	Yes			TYPE:	Livestock barn					
					2x6, sheathing and					
ACCESSIBLE:	Yes		W	ALLS:	½"x6" cedar siding					
0700150		_	NONES ANT DED CON							
STORIES:	<del></del>		SIGNIFICANT PERSON:	H						
*DATE OF CONSTRUCTION:	1915 to 1925	CU	LTURAL AFFILIATION:		?					
ALTERED/MOVED NOTES: _	Appears to be o	original	site. All of stanchions a	nd hors	se stalls have been					
removed.										
INTERIOR NOTES: 6x8 posts 9'-6" O. C. and 6x6 beam in 8' from the East wall. Two 2x4's for posts										
9'- 6" O.C. and two 2x4's for a beam in 4' from the West wall. 2x8 floor joists. Two 6'x8' granaries in the										
NW corner. Appears to have a granary above in the hayloft, but not enough is left to be sure.										
OTHER NOTES: 2x6 stud walls 15' high on the East and West walls. 2x6 stud walls on the gable ends.										
horizontal sheathing with ½"x6" cedar lap siding. Rafters are 2x6 with 2x6 bracing, modified braced										
rafter. 8"x10" four light windows over 8"x10" four light windows, double hung for ventilation. Metal										
cupola. Walk doors on the gable ends and, 8' sliding door on the East wall.										
*PHYSICAL NOTES: Barn is in very poor condition. Roof has been leaking and some of the floor joists										
are rotted completely through					•					



#### **SKETCH MAP**







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May23, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May 237, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NE, SW corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May 23, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SE, NW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: May 23, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SW, NE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 23, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking South, 6x8 posts & 6x6

CAMERA DIRECTION: beam



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 23, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking North, (2) 2x4's post & (2) 2x4's beam, granaries in NW

CAMERA DIRECTION: corner






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 23, 2012

**ROLL NUMBER:** PHOTO NUMBER:

Hayloft, looking North,





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 23, 2012


**ROLL NUMBER:** PHOTO NUMBER:

CAMERA DIRECTION: hayloft door

Hayloft, Looking South,

\* = REQUIRED FIELD





PLEASANT VALLEY TOWNSHIP SECTION 2

County of Clay 13
 SECTION 6
 Wolfswinkel, Sandra 8
 SECTION 8

Peterson, Sterling 6
 Knudson, Dennis 6

SECTION 18 1. Schweb SECTION 19

1. Rohrer, Larry 6 2. Mews, Michael 5 SECTION 23

1. Huot, Clifford 11 SECTION 26
1. Sample Jr, James 10

SECTION 29

1. Pleasant Valley
Lutheran Church 5 Woehl, SECTION 31 r. Richard 10

1. Dimond, Patricia 8
2. American State Bank 8
3. Wibben, Cristeen 12
SECTION 36
1. Christensen, Scott 6

@ Farm & Home Publishers, Ltd.

30

CLAY CO., SD



### **History**

This farm located in the SW  $\frac{1}{4}$  of the SW1/4 of Section 2, Pleasant Valley Township, Clay County was homesteaded by Jesse Fischer.

The 1894, 1901 and 1912 Clay County Atlas lists Jorgen Nelson as the owner.

The 124, 1937, 1948 and 1956 Clay County Atlas lists H. P. Nelson as the owner.

