

SITE INFORMATION


*SURVEY D	5, 2012	*ADDRESS:	: 30857 463rd Ave.								
*SURVEYOR: Jim Stone				*COUNTY:	Clay						
				*CITY:	Vermillion						
LOCATION DESCRIPTION: Vermillion, from the intersection of South Dakota Highway 50 bi-pass and											
South Dakota Highway 19, North 8 miles to 309 th Street, turn right (East) about 1/2 mile to 463 rd Ave.,									. .,		
turn left (North) about ½ mile on the left (West) side.											
LEGAL DESCRIPT	ION: Johi	nson's /	Addition, SE ½	4, 35 – 94 – 52 F	Pleasant	t Val	ley T	wp.			
*QUARTER 1:	SE 1/4			OWNER NAME: Cristeen Wibben							
*QUARTER 2:				WNER ADDRESS: 30857 463 rd Ave.							
	Pleasant Va	allev		OWNER CITY:							
*RANGE:	52		c	WNER STATE:						_	
*SECTION:	35			OWNER ZIP:							
ACRES:	12.38			QUAD NAME:							
OWNER CODE 1:	P										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGN	IIFICANCE										
				REGISTER NA	ME.						
*DOE DATE:				MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE:				WOLIN LETIK	OI LIXI	1 14/	~!VI L	' —			
KEZIOON IIVEEIOIE											
					C	ATE	GOF	RY:			
NOMINATION STATUS:				SIGNIFICANCE LEVEL 1: N S L							
DA	DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L							
REFERENCI	E NUMBER:										
HISTORIC DISTRIC	CT RATING:	C or	NC	CRITE	RIA 1:	Α	В	С	D		
	PERIOD:			CRITE	RIA 2:	Α	В	С	D		
					RIA 3:						
				CRITE	RIA 4:	Α	В	С	D		
CICNIFICANCE NO	TEC.										
SIGNIFICANCE NOTES:											

STRUCTURE DETAILS



SHPO ID:										
*PROPERTY NAME:										
OTHER NAME:										
CURRENT FUNCTION:	Calving and cattl	e FOUNDATION								
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Steel roofing over cedar shingles							
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE	: Gothic round							
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM	Balloon framing							
		STYLE	Wisconsin dairy : barn							
OCCUPIED:	Yes	TYPE	: Livestock barn							
	Yes with		2x6 studs with 1x10 sheathing and							
ACCESSIBLE:	permission	WALLS	: steel siding							
STORIES:	2	SIGNIFICANT PERSON:	J. F. Hickson							
*DATE OF CONSTRUCTION:		CULTURAL AFFILIATION:	?							
ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions or horse stalls has										
been removed. Walls on first floor are lined. 4x4 posts have been added for lambing pens. Roof has										
been covered with steel roofing. 24' x 30' lean-to addition added to the West side at a later date.										
INTERIOR NOTES: Has fou	r rows of 4x6 posts	s, with 6x6's for a beams and a shor	t beam with one post							
for the access to hayloft. Also a 2x4 wall with solid sheathing in the center of barn from the North wall										
South 12'. Double 2x6 floor joists that run East to West.										
OTHER NOTES: 2x6 stud v	valls with 1x10 she	athing and embossed brick steel sid	ding. Rafters are 1x4's							
five ply thick and 2' O. C. and a rafter, site built from 3 plies of 1x12 x 8'-6" cedar, 8' O. C.										
2x6 brace from top of wall de	own to hayloft floo	r, 8' O. C. 2x6 studs and bracing, 6x	6 posts and beams							
Two long 2x6 braces 10' O.C.	. from center of Eas	12' walls on the gable ends and rafte st gable end wall down to the haylof our light over 8"x10" four light in eac	t floor. Windows are							
*PHYSICAL NOTES: Barn i	s in fair to good co	ondition.								
*UTM ZONE:		*RESTRICTED: Y	or N							
			J. 14							
*UTM EASTING:										
*UTM NORTHING:										









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 16, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: December 16, 2012 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: December 16, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: December 16, 2012

PHOTO NUMBER: 4

First floor, looking NE, 4x6 posts, 6x6 beam and camera double 2x6 floor joists.





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 16, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SE, posts and beams and 4x4 posts added recently

CAMERA DIRECTION: for lambing pens.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 16, 2012

ROLL NUMBER: PHOTO NUMBER:

6

First floor, looking SW, 4x6 posts and 6x6 beam, note short 6x6 beam

CAMERA DIRECTION: under top 6x6





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 16 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SE, 5 ply 1x4 rafters 2' O. C. and 3 ply 1x12 cedar rafters 8'

CAMERA DIRECTION: O. C.




PHOTOGRAPHER: _

Jim Stone DATE OF PHOTO: December 16, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, rafters, 1x6 roof sheathing and 2x6 bracing from top of wall CAMERA DIRECTION: down to hayloft floor.





CLAY CO., SD



HISTORY

This farm located in the SE ¼ of Section 35, Pleasant Valley Township, Clay County was homesteaded by Daniel Cookley

The 1894, 1901, 1912 and 1924 Clay County Atlas lists J. F. Hickson as the owner. This barn would have been built during this time and most likely in the 1920's.

The 1937, 1948 and 1956 Clay County Atlas lists Thos. Host as the owner.

