


""SITE INFORMATION					
*SURVEY DATE: July 23,	2013 *ADDRESS:	30752 Bluff Road			
*SURVEYOR: Jim Stor		Clay			
	*CITY:	Volin			
LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50, West about 8 miles to Meckling					
and 456th Ave, turn right (North) about 4-3/4 miles to Bluff Road, turn left (West) about 3-1/2 miles, on the					
right (North) side.					
LEGAL DESCRIPTION: W ½, NE ¼, 29 – 94 – 53 Bethel Twp.					
*QUARTER 1: NE 1/4	OWNER NAME:	Robert E. & Anna M. Johnson			
*QUARTER 2:	OWNER ADDRESS:				
*TOWNSHIP: Bethel	OWNER CITY:				
*RANGE: 53	OWNER STATE:	South Dakota			
*SECTION: 29	OWNER ZIP:	57072			
ACRES: 77.07	QUAD NAME:				
OWNER CODE 1: P					
OWNER CODE 2:					
OWNER CODE 3:					
HISTORIC SIGNIFICANCE					
*DOE:	REGISTER NA	REGISTER NAME:			
*DOE DATE.		MULTIPLE PROPERTY NAME:			
REASON INELIGIBLE:					
		CATEGORY:			
NOMINATION STATUS:	SIGNII	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGNII	FICANCE LEVEL 2: N S L			
REFERENCE NUMBER:					
HISTORIC DISTRICT RATING: C or	NC CRITE	RIA1: A B C D			
PERIOD:	CRITE	RIA 2: A B C D			
	CRITE	RIA 3: A B C D			
	CRITE	RIA4: A B C D			
SIGNIFICANCE NOTES:					


#### STRUCTURE DETAILS



SHPO ID:					
*PROPERTY NAME:					
OTHER NAME:					
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete		
			Asphalt shingles over		
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:			
HISTORIC FUNCTION:	Horse barn	ROOF SHAPE:			
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing		
		STYLE:	Gable roof bank barn		
OCCUPIED:	Yes	TYPE:	Horse barn		
	Yes with		2x6 studs, 1x8 shiplap & embossed		
ACCESSIBLE:	permission	WALLS:	brick steel siding		
7.00_00	poninicononi				
STORIES:	2	SIGNIFICANT PERSON:	J. H. Tennant		
*DATE OF CONSTRUCTION:		_	?		
			•		
ALTERED/MOVED NOTES: Original site. Roof has been shingled over cedar shingles with asphalt					
shingles. 24' x 56' open front pole barn added on to the East side recently.					
INTERIOR NOTES: One row of 6x6 posts and 6x6 beam and one row of (2) 2x6's with a 2x6 plate support t					
The 2x8 joists for the hayloft floor. One 3/4 double horse stall and a walk alley next to the West wall and					
four double horse stalls East to East wall. Feed alley between mangers and North wall. 2x6 brace from rafters down to the floor 8' O. C. and a 1x6 brace on rafters at the peak 2' O. C.					
OTHER NOTES: The first floor North and South walls are 8"x 8" poured concrete. All the other walls are					
2x6 stud walls, with 1x8 shiplap and embossed brick steel siding, including all four walls in the hayloft.					
The rafters are 2x6's. The windows in the first floor are 10" x 12" three light cellar sash at the top of the					
walls. The other windows are 8" x 10" four light windows.					
*PHYSICAL NOTES: Barn is in good condition.					
	<u> </u>				
*******		*PEOTDIOTED Y	N		
*UTM ZONE:			Or N		
*UTM EASTING:					
*UTM NORTHING:					











PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013 **ROLL NUMBER:** 

**PHOTO NUMBER:** 

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: \_\_\_\_\_\_
DATE OF PHOTO:

Jim Stone July 23, 2013 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: \_\_\_\_ DATE OF PHOTO: Jim Stone July 23, 2013 ROLL NUMBER: PHOTO NUMBER:

\_\_\_\_\_

\_ \_\_\_

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

5

First floor, looking NE, 6x6 post, 6x6 beam, 2x8 joists, double horse

**CAMERA DIRECTION:** stalls



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking North, 3/4 horse stall at West

CAMERA DIRECTION: end.





PHOTOGRAPHER: Jim Stone

DATE OF PHOTO: July 23, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking SE, 2x6 brace from rafter down

CAMERA DIRECTION: to floor, 8' O. C.



PHOTOGRAPHER: Jim Stone


DATE OF PHOTO: July 23, 2013

**ROLL NUMBER:** PHOTO NUMBER:

Hayloft, looking NE, 2x6 rafters and 1x6 bracing

CAMERA DIRECTION: at the peak, 2' O. C.





Farm & Home Publishers, Ltd.

CLAY CO., SD



### **HISTORY**

This farm located in the NE ¼ of Section 29, Bethel Township, Clay County was homesteaded by James Lennant. (May have been mis-spelled)

The 1894, 1901 and 1912 Clay County Atlas lists J. H. tenant as the owner.

The 1924, 1937 and 1948 Clay County Atlas lists Edwin C. Johnson as the owner.

The 1956 Clay County Atlas lists L. B. Johnson as the owner.

