

#### SITE INFORMATION

*SURVEY DATE: February 16	, <u>2013</u> *ADDRESS:	45971 309 <sup>th</sup> Street						
*SURVEYOR: Jim Stone	*COUNTY:	Clay						
	*CITY:	Vermillion						
LOCATION DESCRIPTION: From Ve	rmillion, the intersection of Sou	ıth Dakot	ta High	way	50 bi	-pas	s and	
South Dakota Highway 19, (North) 8 miles to 309 <sup>th</sup> Street, turn left (West), 3 miles, on left (South) side								
	•							
LEGAL DESCRIPTION: E 700' of N 9	975' of W ½ of Lot 2, NE ¼, 5 –	93 <b>–</b> 52 S	Spirit M	ound	wT t	p.		
							_	
*QUARTER 1: NE 1/4	OWNER NAME:	Tim Seep						
*QUARTER 2:	OWNER ADDRESS:	45971 309 <sup>th</sup> Street						
*TOWNSHIP: Spirit Mound	OWNER CITY:	Vermillion						
*RANGE: <u>52</u>	OWNER STATE:	South Dakota						
*SECTION: 5	OWNER ZIP:	57069						
ACRES: <u>16</u>	QUAD NAME:							
OWNER CODE 1: P								
OWNER CODE 2:								
OWNER CODE 3:								
HISTORIC SIGNIFICANCE								
HISTORIC SIGNII IGANGE								
*DOE:								
*DOE DATE:	MULTIPLE PR	MULTIPLE PROPERTY NAME:						
REASON INELIGIBLE:								
		CATEGORY:						
			LEVE	L 1:	N	S	L	
DATE LISTED:	SIGNII	SIGNIFICANCE LEVEL 2: N S L						
REFERENCE NUMBER:								
HISTORIC DISTRICT RATING: C or		RIA 1:						
PERIOD:		RIA 2:						
		RIA 3:						
	CRITE	RIA 4:	A B	С	D			
				_	_	_		
SIGNIFICANCE NOTES: Oral History note. This farm location was stage coach and mail stop before the								
railroad came to this area.								


#### STRUCTURE DETAILS



SHPO ID:									
*PROPERTY NAME:									
OTHER NAME:									
<b>CURRENT FUNCTION:</b>	Horse barn	FOUNDATION	l: Poured concrete						
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE	: Gable						
HISTORIC SUBFUNCTION:	Hay & grain storage	STRUCTURAL SYSTEM	Balloon framing						
		STYLE	: Gable roof barn						
OCCUPIED:	Yes	TYPE	: Livestock barn						
	Yes with		2x6 studs, 1x6						
ACCESSIBLE:	permission	WALLS:	#106 drop siding						
STORIES:	<del></del>		J. P Knudson						
*DATE OF CONSTRUCTION:	About 1920	CULTURAL AFFILIATION:	?						
ALTERED/MOVED NOTES: Original site. Any evidence of horse stalls and milk cow stanchions has									
been removed. Granaries appear to have been added later and extended into hayloft. 14' x 32' lean-to									
on the West side may have be	en added later.								
INTERIOR NOTES: Has two	rows of 4x6 nosts a	nd a 6x6 for a heam. The floor in	ists for the havloft						
INTERIOR NOTES: Has two rows of 4x6 posts and a 6x6 for a beam. The floor joists for the hayloft floor are 2x8's. A 2x6 solid wall divides the South 16' from the North 16'. Two 9' x 8' granaries have been									
added on the East side and on the West side in the North part of the barn. These extend into the hayloft.									
OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding and 2x4 stud walls in the lean-to with 1x6									
#106 drop siding. The rafters are 2x6's, with two rows of 4x4 posts 8' O. C. and a 2x6 beam supporting the center of the rafters. 2x6 ceiling joists in lean-to for bracing. Window are 8"x10" four light.									
Three lighting rods are still on the ridge of the roof.									
*PHYSICAL NOTES: Barn is in fair condition. Needs some siding repair, windows replaced and some									
	s iii iaii condition. N	eeus some sidnig repair, window	s replaced and some						
doors repaired or replaced.									
*UTM ZONE:			or N						
*UTM EASTING:									
*UTM NORTHING:									

\_









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 16, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 16, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 16, 2013 PHOTO NUMBER:

PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: \_\_ DATE OF PHOTO:

Jim Stone February 16, 2013 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 16, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NE, solid 2x6 stud wall dividing South 16' from North 16'. 4x6 post with CAMERA DIRECTION: 6x6 beam & 2x8 joists.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 16, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking SW, granaries along West

CAMERA DIRECTION: wall.





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: February 16, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking North, granaries extending into

CAMERA DIRECTION: hayloft.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone February 16, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking NE, 4x4 posts and 2x6 beam supporting rafters. **Granary extended into** 

CAMERA DIRECTION: hayloft.





SPIRIT MOUND TOWNSHIP

- SECTION 23 McDonald, Ben 31284 Emidal Mile 21289
- 2 Freidel, Mike 31288 3 A6292
- 4 Wood, Robert 46296

© Farm & Home Publishers, Ltd.

37

CLAY CO., SD



### **HISTORY**

This farm located in the NE ¼ of Section 5, Spirit Mound Township, Clay County was homesteaded by James H. Woodworth.

The 1894 and 1901 Clay County Atlas lists Jacob Johnson as the owner. (The NE ¼ of the NE1/4 of Sec 5 was homesteaded by Osmond Mortvedt and owned by B. J. Mortvedt in 1894).

1912, 1924 and 1937 Clay County Atlas lists J. P. Knudson as the owner.

1948 Clay county Atlas lists Hazel Emme as the owner.

1956 Clay County Atlas lists Carel Emme as the owner.

