


SITE INFORMA	TION											
*SURVEY DAT	TE: August 1	2, 2013	*ADDRESS:	30538	457 th A	ve.						
*SURVEYO	OR: Jim Ston	е	*COUNTY:	Clay								
			*CITY:	Wakor	nda							
LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and												
South Dakota Highway 19, North about 11 miles to 306th Street, turn left (West) about 5 miles to 457th Ave.,												
turn right, (North) about 3/4 mile, on the right (East) side.												
LEGAL DESCRIPTION: E 391' of Anderson tract 1, E 1/2, NW 1/4, 13 – 94 – 53 Bethel Twp.												
							0.1.					
*QUARTER 1: NW 1/4			OWNER NAME:	Miranda Halverson & Jeremy R NAME: Lindula								
*QUARTER 2:		owi	NER ADDRESS:	30538 457 th Ave.								
*TOWNSHIP:	Bethel OWNE			Wakon	da							
*RANGE: _	53	OWNER STATE:	South D	Dakota								
*SECTION: _	13		OWNER ZIP:	57073								
ACRES: _	4.99		QUAD NAME:									
OWNER CODE 1:	P											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNII	FICANCE											
*DOE:			REGISTER NAME:									
*DOE DATE:			MULTIPLE PR	OPERTY	NAME	: _						
REASON INELIGIBL	.E:											
					. ====	5 1/						
NOMBATION	07.47.10		CATEGORY:									
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L SIGNIFICANCE LEVEL 2: N S L									
			SIGNI	FICANCE	LEVE	L 2:	N	S	L			
	NUMBER:		ODITE	-DIA 4		_	_					
HISTORIC DISTRICT		_		ERIA 1:								
	PERIOD:			ERIA 2:								
				ERIA 3: ERIA 4:								
			CRITE	ERIA 4:	А В	C	D					
SIGNIFICANCE NOTES:												
CICITII ICANGE NOT												

STRUCTURE DETAILS



SHPO ID:									
*PROPERTY NAME: OTHER NAME:									
OTTER NAME.									
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete						
CURRENT SUBFUNCTION:	Vacant	ROOF MATERIAL:	Cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable roof						
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Gable roof barn						
OCCUPIED:	No	TYPE:	Livestock barn						
ACCESSIBLE:	?	WALLS:	2x6 studs, 1x6 #106 drop siding and steel roofing						
STORIES		SIGNIFICANT PERSON:	J. W. Jacobson						
*DATE OF CONSTRUCTION	Very early : <u>1900's</u>	CULTURAL AFFILIATION:	Danish						
ALTERED/MOVED NOTES: Original site. All evidence of milk cow stanchions and horse stalls has been									
removed. All but the North wall has been covered with 1-1/4" x 26" galvanized corrugated steel which has									
been applied horizontally. The North wall is covered about up to 8' high.									
INTERIOR NOTES: Two rov	vs of double 2x6 p	posts with (2) 2x6's for a beam on one	row and (2) 2x4 for a						
beam on the other row, to support 2x6 joists for hayloft floor. The wall between the original barn and the									
East lean-to is an open double 2x6 stud wall, with studs 4' O. C. Evidence may suggest milk cow stalls on West side.									
OTHER NOTES: 2x6 stud v	valls with 1x8 #106	drop siding and horizontal steel roof	ing. Rafters are 2x6's						
with 2x4 brace from top of wall in hayloft down to floor, 8' O. C. Windows are 8" x10" four light. No cupola.									
Lean-to on the North appears to have been built at the same time as the barn. All of the 2x6 studs and 2x6									
	osts and roof shea	athing are rough sawn cottonwood.							
*PHYSICAL NOTES: Barn is *UTM EASTING: *UTM NORTHING:	in poor condition.	*RESTRICTED: Y o	r N						









PHOTOGRAPHER:

Jim Stone

DATE OF PHOTO: August 12, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013 **ROLL NUMBER:**

PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: August 12, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: August 12, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013

ROLL NUMBER: PHOTO NUMBER:

Looking NE, East wall between barn and East lean-to, double 2x6 stud open wall, 4' O. C.,

CAMERA DIRECTION: extends up into hayloft.



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

August 12, 2013

ROLL NUMBER: PHOTO NUMBER:

6

First floor, looking NE, might be evidence of milk cow stalls on West

CAMERA DIRECTION: side.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013

ROLL NUMBER: PHOTO NUMBER:

7 Hayloft, looking SE, 2x6 rafters, 2x4 brace, 8' O. C., double 2x6 stud wall, 4' O. C. extending into

CAMERA DIRECTION: hayloft.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone August 12, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, 2x6 rafters, double 2x6 stud wall and North gable

CAMERA DIRECTION: wall.





CLAY CO., SI



History

This farm located in the NW ¼ of Section 13, Bethel Township, Clay County was homesteaded by A. C. Christopherson.

The 1894 Clay County Atlas lists A. C. Christopherson as the owner.

The 1901 Clay County Atlas lists J. W. Jacobson as the owner.

The 1912 and 1924 Clay County Atlas lists John Anderson as the owner.

The 1937 Clay county atlas lists Mary & John Anderson as the owners and W. B. Roberts as the operator (renter).

The 1948 Clay County Atlas lists Mary Anderson as the owner.

The 1956 Clay County Atlas lists F. G. Anderson as the owner.

The Following Is From The

Wakonda, S. D. Centennial Book 1885 – 1985

James W. and Karen Jacobson family

James Jacobson and Karen (Carrie) Madsen (daughter of Nels and Martha Madsen) were married at Sioux City on Nov. 8, 1873 by Pastor E. Arveson.

James was born April 15, 1894 (?) at Wakonda and died Sept. 28, 1911 at Chicago, Ill. Karen was born in Demark and became an American citizen June 15, 1871 at Sioux City, Iowa. They owned the farm now occupied by Don Lyso.

The Jacobson's had five children; Ella, Louie, George, Mary and Elizabeth all were born in Sioux City. They also raised a daughter of Mrs. Jacobson's sister Caroline Clara Hansen Wendt.

