

SITE INFORMATION


*SURVEY DATE: Decen	*ADDRESS: 4826 East So. Dak. Highway 50						y 50		
*SURVEYOR: Jim S	tone	*COUNTY: Clay							
	*CITY: Vermillion								
LOCATION DESCRIPTION: Fr	om Vermillion, South	Dakota Highway	50, East	t about	2-1/2	2 mile	es, o	n the	
left (North) side.									
LEGAL DESCRIPTION: S ½,	, W ½, NE 1/4, 15 – 9	2 – 51 Fairview T	wp.						
*QUARTER 1: NE 1/4	-	Richard V. Sorensen Trust							
*QUARTER 2:	OW	-	4826 East So. Dak. Highway 50						
*TOWNSHIP: Fairview		OWNER CITY:							
*RANGE: <u>51</u>		-	South Dakota						
*SECTION: 15		OWNER ZIP:							
ACRES: <u>37.66</u>		QUAD NAME:							
OWNER CODE 1: P									
OWNER CODE 2:									
OWNER CODE 3:									
HISTORIC SIGNIFICANCE									
		DECISTED NA	ME.						
*DOE DATE		MILL TIPLE PROPERTY MANE							
· · · · · · · · · · · · · · · · · · ·			OPERIT	NAIVIE	-				
REASON INELIGIBLE:									
			CA	TEGO	DV.				
NOMINATION STATUS:		CATEGORY: SIGNIFICANCE LEVEL 1: N S L							
DATE LISTED:									
REFERENCE NUMBER:		O.C.III	10711102			•	Ū	_	
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	ΔR	C	D			
			RIA 2:						
			RIA 3:						
			RIA 4:						
		JL	 • •	· •	•	_			
SIGNIFICANCE NOTES:									

STRUCTURE DETAILS



SHPO ID:										
*PROPERTY NAME:										
OTHER NAME:										
CURRENT FUNCTION:	Storage		FOUNDA	TION:	Poured concrete foundation					
CURRENT SUBFUNCTION:	Storage		ROOF MATERIAL:		Steel roofing over cedar shingles					
HISTORIC FUNCTION:	Livestock barn ROOF SHA				-					
HISTORIC SUBFUNCTION:	Hay storage STRUCTURAL SYSTEM:				Balloon framing					
	nay oronago				Gable roof barn					
OCCUPIED:	Yes			Livestock barn 2x6 studs with 1x6						
ACCESSIDI F.	Yes with		1 47	AL I C.	#106 drop siding					
ACCESSIBLE:	permission		VV.	ALLS:	and steel siding					
STORIES:	2	S	SIGNIFICANT PERSON:	James Brady / Lyman IFICANT PERSON: Burgess						
*DATE OF CONSTRUCTION:	1885 to 1900	CU	LTURAL AFFILIATION:		?					
ALTERED/MOVED NOTES:	Original site. A	ny evid	ence of milk cow stanch	nions o	r horse stalls has					
been removed. Drawing show	ws layout of milk c	ow sta	nchions from remodel i	า 1950':	s as per the present					
owner. Steel roofing has bee	n installed on roof	f and si	dewalls. Overhang and	all exp	osed wood is					
covered with steel trim. The	only visible wood	now is	the 8"x10" four light win	ndows.	Large 6' x 4'					
wood cupola has been remov	ed.									
INTERIOR NOTES: Has two	rows of 6x6 posts	s, with (6x6 for a beam and a po	st and a	a short beam in the					
SW corner to support floor j	oists where the st	airs is	ocated. Also has two 6	x6 bea	ms perpendicular					
under existing 6x6 beams. T	his may have beer	n part o	of the remodel in the 195	i0's.						
OTHER NOTES: 2x6 stud w	alls with 1x6 #106	drop s	iding covered with red p	painted	steel roofing.					
Rafters are 2x6's with sheathing, cedar shingles and steel roofing. Walls are lined with 1x8 shiplap										
inside on the first floor. Wind	lows are 8"x19" fo	our ligh	t.							
*PHYSICAL NOTES: Barn is	s in very good con	ndition.								
			*RESTRICTED:	ΥO	r N					
*UTM EASTING:										
*UTM NORTHING:										









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 6, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December65, 2012 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone December 6, 2012 ROLL NUMBER: PHOTO NUMBER:

TO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone December 6, 2012 ROLL NUMBER:

PHOTO NUMBER:

4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 6, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, 6x6 posts and 6x6 beams running both

CAMERA DIRECTION: directions



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 6, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SE, 6x6 posts and 6x6

CAMERA DIRECTION: beams





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 6, 2012**

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, 2x6 rafters, 4x4 posts and 4x4 beam supporting

CAMERA DIRECTION: center of rafters.



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone


December 6, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SE, 2x6 bracing from rafters down to the wall at the

CAMERA DIRECTION: floor level, 4' O.C.







HISTORY

This farm located in the S ½ of the W ½ of the NE ¼, of Section 15, Fairview Township, Clay County was homesteaded by James Brady.

The 1894 Clay County Atlas lists W. H. Beede as the owner

The 1901 and 1912 Clay County Atlas lists Lyman Burgess as the owner.

The 1924 Clay County atlas lists Joseph Bruyer as the owner.

The 1937 Clay County atlas lists T. Delaurier as the owner.

The 1948 Clay County atlas lists Clive Hancock as the owner

The 1956 Clay County atlas lists Louis Bruyer as the owner.

