


SITE INFORMATION

*SURVEY DATE: <u>June 6</u>	*ADDRESS:	5: 45307 300 th Street									
*SURVEYOR: _Jim St	*COUNTY:	Clay									
		*CITY: Wakonda									
LOCATION DESCRIPTION: Fro											
Dakota Highway 19, 15 miles North to 302 nd Street, turn left (West, 9 miles to 453 rd Ave, turn right (North)											
2 miles to 300 th Street, turn right and about 100 yards, turn right (South) into farm. Also has a lane off											
453 rd Ave.											
LEGAL DESCRIPTION: W ½ NW ¼, 20 – 95 – 53 Star Twp.											
*QUARTER 1: NW 1/4	c	OWNER NAME: James N				elson					
*QUARTER 2:		-	45307 300 th Street								
*TOWNSHIP: Star		OWNER CITY: Wakonda									
*RANGE: 53		OWNER STATE: S									
*SECTION: 20		OWNER ZIP: 57073									
ACRES: 40.89		QUAD NAME:									
OWNER CODE 1: P								_			
OWNER CODE 2: F S L	P										
OWNER CODE 3: F S L	P										
LISTORIC SIGNIFICANCE											
HISTORIC SIGNIFICANCE											
		REGISTER NAME:									
*DOE DATE:	MULTIPLE PRO	OPERTY NA	AME:								
REASON INELIGIBLE:											
		CATEGORY:									
NOMINATION STATUS: _	SIGNIFICANCE LEVEL 1: N S L										
DATE LISTED: _		SIGNIF	ICANCE LI	EVEL	2:	N	S	L			
REFERENCE NUMBER: _				_	_	_					
HISTORIC DISTRICT RATING:			RIA 1: A								
PERIOD: _			RIA 2: A								
			RIA 3: A								
		CRITE	RIA 4: A	В	C	D					
SIGNIFICANCE NOTES.											
SIGNIFICANCE NOTES:											



STRUCTURE DETAILS									
SHPO ID:									
*PROPERTY NAME:		_							
OTHER NAME:									
5 111 <u>=11 111 1111</u>									
CURRENT FUNCTION:	Storage	_ FOUNDAT	ION:	Poured concrete					
CURRENT SUBFUNCTION:		ROOF MATER	1Δ1 -	Steel over cedar					
HISTORIC FUNCTION:	Livestock barn	ROOF SH		Gambrel					
			STRUCTURAL SYSTEM:						
HISTORIC SUBFUNCTION:	nay and grain Storage								
	•		•	Gambrel roof barn					
OCCUPIED:	Yes	Т	YPE:	Livestock barn					
	Yes with			2x6, with diagonal sheathing and					
ACCESSIBLE:		WA	LLS:	siding					
STORIES:	2	SIGNIFICANT PERSON: _		ert Christian Nelson C. Nelson					
*DATE OF CONSTRUCTION:	? Cl	JLTURAL AFFILIATION:		Danish					
ALTERED/MOVED NOTES: Original site. Roof and walls have been covered with steel roofing. Horse stalls have been removed. Doors have been removed and replaced with steel walk doors.									
INTERIOR NOTES: 6x6 posts, with (3) 2x8's for a beam. Beams run North to South, 11' from the West wall and 9' from the East wall leaving an 8' center alley. 2x8 floor joists. 2x6 walls 13'- 6" high with									
diagonal sheathing and 2x6 vabove to roof line.	walls 18 ⁷ high with diago	nal sheathing on gable en	d wall	ls with 2x6 studs					
OTHER NOTES: 2x6 rafters	with 2x6 bracing. A mo	dified Shawver truss 8' O.0	C. with	n a 4x4 to support					
the hip. Two angled braces o	n the North gable wall a	nd one angled brace on th	e Sou	th gable wall in the					
hayloft. 9"x12" six light wind	ows on first floor and ha	ayloft.							
		_							
*PHYSICAL NOTES: Barn is	s in very good condition	. Poured concrete founda	tion is	exposed about 2'					
to the North end and about 3'									









PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: June 6, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking SE, NW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 6, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO: June 6, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

First floor, milk cow

CAMERA DIRECTION: _stanchions in SW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: posts and beam

First floor, looking East,



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, bottom of truss bracing

CAMERA DIRECTION: on North gable end wall





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North,

CAMERA DIRECTION: 2x6 rafter bracing.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: June 6, 2012

ROLL NUMBER:

PHOTO NUMBER:

Hayloft, looking North,

lower 2x6 rafter and wall

CAMERA DIRECTION: bracing.





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, triangle bracing for gable

CAMERA DIRECTION: end wall





CLAY CO., SD



HISTORY

This farm, located in the W ½ of the NW ¼, Section 20, Star Township, Clay County was homesteaded by James H. Dwyer.

The 1894 Clay County Atlas lists M. Dwyer as the owner.

The 1901 and 1912 Clay County Atlas lists Margaret Dwyer as the owner.

The 1924 Clay County Atlas lists Andrew Hansen as the owner.

The 1937 Clay County Atlas lists W. Carr as the owner.

The 1948 and 1956 Clay County Atlas lists A. C. Nelson as the owner.