

SITE INFORMATION

*SURVEY DATE: _____ *SURVEYOR:

<u>May 10, 2013</u> Jim Stone *ADDRESS: 29735 SD 19

*COUNTY: Clay

*CITY: Centerville

LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 19 – 3/4 miles, on the left (West) side.

LEGAL DESCRIPTION: Lots 1 & 2, Exc Lots H 1 & H 2 & Exc. .98 A for Road, 3-95-52 Riverside Twp.

| *QUARTER 1: | SE 1/4 | | OWNER NAME: | Eric N. | . & N | lelis | sa A | . Buc | :kenł | berg | |
|--------------------|-----------|----|--------------------|---------|--------|-------|------|-------|-------|------|--|
| *QUARTER 2: | | OW | NER ADDRESS: | 29735 | SD 1 | 9 | | | | | |
| *TOWNSHIP: | Riverside | | OWNER CITY: | Center | rville | • | | | | | |
| *RANGE: | 52 | | OWNER STATE: | South | Dak | ota | | | | | |
| *SECTION: | 3 | | OWNER ZIP: | 57014 | | | | | | | |
| ACRES: | 149.41 | | QUAD NAME: | | | | | | | | |
| OWNER CODE 1: | Р | | | | | | | | | | |
| OWNER CODE 2: | | | | | | | | | | | |
| OWNER CODE 3: | | | | | | | | | | | |
| | | | | | | | | | | | |
| HISTORIC SIGN | | | | | | | | | | | |
| HISTORIC SIGN | | | | | | | | | | | |
| *DOE: | | | REGISTER NAME: | | | | | | | | |
| *DOE DATE: | | | | | Y NA | ME: | | | | | |
| REASON INELIGIB | LE: | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | - | | | | | | | |
| NOMINATION STATUS: | | | | FICANC | | | | | - | L | |
| DATE LISTED: | | | SIGNI | FICANC | ELE | EVEL | . 2: | Ν | S | L | |
| REFERENCE | NUMBER: | | | | | | | | | | |
| HISTORIC DISTRIC | | | | ERIA 1: | | _ | - | _ | | | |
| | PERIOD: | | - | ERIA 2: | | | - | | | | |
| | | | - | ERIA 3: | | | - | | | | |
| | | | CRITE | ERIA 4: | Α | В | С | D | | | |
| | | | | | | | | | | | |
| SIGNIFICANCE NOT | res: | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

STRUCTURE DETAILS

* = REQUIRED FIELD



| SHPO ID: | | | | | | |
|------------------------|----------------------|-----------------------|----------------|--------------------------------------|--|--|
| *PROPERTY NAME: | | | | | | |
| OTHER NAME: | | | | | | |
| | | | | | | |
| CURRENT FUNCTION: | Storage | FOUNDA | FOUNDATION: | | | |
| | • | | | Steel roofing over cedar shingles | | |
| CURRENT SUBFUNCTION: | Storage | ROOF MATE | ROOF MATERIAL: | | | |
| HISTORIC FUNCTION: | Horse barn | ROOF SH | IAPE: | Gothic round | | |
| HISTORIC SUBFUNCTION: | Hay and grain storag | e STRUCTURAL SYS | TEM: | Balloon framing | | |
| | | | | Gothic round roof | | |
| | | ST | TYLE: | barn | | |
| OCCUPIED: | Yes | 1 | TYPE: | Livestock barn | | |
| | | | | 2x6 studs, 1x10 | | |
| | | | | horizontal sheathing, | | |
| | Yes with | | | 1/2"x6" cedar lap | | |
| ACCESSIBLE: | permission | WALLS: | | siding | | |
| | | | | | | |
| STORIES: | 2 | SIGNIFICANT PERSON: | Ja | ames T. Payson | | |
| *DATE OF CONSTRUCTION: | Early 1920's | CULTURAL AFFILIATION: | | Danish | | |

ALTERED/MOVED NOTES: Original site. Some of the mangers in the horse stalls have been removed. Steel roofing installed on the roof. Cedar shingles removed and spaces between spaced roof sheathing filled with 2" wide boards before installing steel roofing.


INTERIOR NOTES: <u>The original barn has two rows of 4x6 posts and 4x6 for a beam. The floor joists are</u> 2x8's for the hayloft floor. 8' x 8' granary in SE corner, 5' x8' tack room and stairs to hayloft in the NE corner are still in place. The granary has been remodeled into a shop.


OTHER NOTES: 2x6 stud walls. 1x10 horizontal sheathing and ½"x 6" cedar lap siding. Rafters are site built from 7 plies of ³/₄" x 2-1/4" cedar, making a rafter 2-1/4" wide and 5-3/4" thick. Very ornate metal cupola from about 1900 to 1925. Windows are 9" x 12" four light.

*PHYSICAL NOTES: Barn is in good condition.

*UTM ZONE: ______ *RESTRICTED: Y or N *UTM EASTING: ______ *UTM NORTHING: _____







* = REQUIRED FIELD





PHOTOGRAPHER:Jim StoneROLL NUMBEDATE OF PHOTO:May 10, 2013PHOTO NUMBE

 ROLL NUMBER:

 PHOTO NUMBER:

 1

 CAMERA DIRECTION:

 Looking NE, SW corner




PHOTO NUMBER: 2 CAMERA DIRECTION: Looking NW, SE corner










PHOTOGRAPHER: Jim Stone DATE OF PHOTO: May 10, 2013

ROLL NUMBER: PHOTO NUMBER:

5 First floor, looking NW, 4x6 posts 4x6 beams 2x8 CAMERA DIRECTION: floor joists







PHOTOGRAPHER: Jim Stone DATE OF PHOTO: May 10, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NW, 1x6 bracing from rafter down to floor, 4' O, C,

7

CAMERA DIRECTION: to floor, 4' O. C.



 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 May 10, 2013
 PHOTO NUMBER:
 8

8 Hayloft, looking NW, 1x6 bracing on center of rafters 2' O. C., note verticle bracing on gable

CAMERA DIRECTION: end.






PHOTOGRAPHER: ____ DATE OF PHOTO: Jim Stone May 10, 2013 ROLL NUMBER: PHOTO NUMBER:

9 Hayloft, looking West up to peak, 5" wooden roller mounted on a 1" steel rod for hay track rope, this is usually a wooden block with a steel or wood pulley.

CAMERA DIRECTION: wood pulley.





© Farm & Home Publishers, Ltd.

35

CLAY CO., SE



HISTORY

This farm located in the NE ¼ of Section 3, Riverside Township, Clay County was homesteaded by Cyrus C. Stevens.

The 1894 Clay county Atlas lists C. C. Stevens as the owner.

The 1901 Clay county Atlas lists Tenas J Gunderson as the owner.

The 1912, 1924 and 1937 lists James T. Payson as the owner.

The 1948 and 1956 Clay county Atlas lists D. C. Johnson as the owner.