


```SITE INFORM	<u>ATION</u>										
*SURVEY DA	2013	*ADDRESS:	45450 299th Street								
*SURVEYOR: Jim Stone		е	*COUNTY:	Clay							
					Vermillion						
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and											
South Dakota Highway 19, North 6 miles to 311th Street, turn left (West) about 1/2 mile, turn left (South)											
about ¼ mile on the right (West) side.											
LEGAL DESCRIPTION: Lot 1, Cleland Subdivision, NE ¼, 15 – 93 – 52 Spirit Mound Twp.											
*QUARTER 1:	NE 1/4		OWNER NAME: James C. & Jennifer L. Katrenak								
*QUARTER 2:		OWN	NER ADDRESS:	31125 462 nd Ave.							
*TOWNSHIP:	Spirit Mound		OWNER CITY:	Vermillion							
*RANGE:	52		OWNER STATE: South Dakota								
*SECTION:	15		OWNER ZIP:	57069							
ACRES:	10.30		QUAD NAME:								
OWNER CODE 1:	Р										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGN	<b>IFICANCE</b>										
*DOE:			REGISTER NAME:								
*DOE DATE:			MULTIPLE PROPERTY NAME:								
REASON INELIGIBLE:											
			CATEGORY:								
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:			SIGNI	FICANCE	LEVEL	2:	N	S	L		
	NUMBER:										
HISTORIC DISTRIC				RIA 1: A							
	PERIOD:			RIA 2: A							
				RIA 3: A							
			CRITE	RIA 4: A	ь	C	D				
SIGNIFICANCE NOTES:											
	- = <b>- ·</b>										

#### STRUCTURE DETAILS



SHPO ID:		_									
*PROPERTY NAME:											
OTHER NAME:											
<b>CURRENT FUNCTION:</b>	Calving barn	_ FOUNDATION:	Poured concrete								
<b>CURRENT SUBFUNCTION:</b>	Storage	ROOF MATERIAL:	Cedar shingles								
HISTORIC FUNCTION:	Horse barn	ROOF SHAPE:	Gable roof								
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing								
		STYLE:	Gable roof barn								
OCCUPIED:	Yes	TYPE:	Livestock barn								
			2x6 studs, diagonal								
	Yes with		sheathing & ½"x6"								
ACCESSIBLE:	permission	WALLS:	cedar lap siding								
STORIES:	2	SIGNIFICANT PERSON:	Jasper Hixson								
*DATE OF CONSTRUCTION:		ILTURAL AFFILIATION:	?								
DATE OF CONCINCIONAL	10 (00113		•								
ALTERED/MOVED NOTES: Original site. All evidence of horse stalls and milk cow stanchions has been											
<del></del>											
removed. 13' x 36' lean-to added on the East side. Lean-to has 1-1/4"x 26" corrugated, galvanized steel											
roofing added over cedar shingles on lean-to. The North and East walls of the lean-to have the same steel roofing applied vertically over 1x6 #106 drop siding. Metal cupola is gone.											
rooting applied vertically ove	r 1x6 #106 arop slaing.	metal cupola is gone.									
INTERIOR NOTES: Two row	s of 6x6 posts, and (3) 2	x8's for a beam support the 2x	8 joists for the hayloft								
Floor. 6'-6 x 9' granary and feed room is still in the NW corner. 6' x 10' granary still in place in the NW											
corner of the hayloft.											
OTHER NOTES: 2x6 stud walls, diagonal sheathing and ½"x6" cedar lap siding on all four walls of											
original barn. 2x6 stud walls and 1x6 #106 drop siding on lean-to. Rafters are 2x6's with a 2x6 brace											
supporting the center of rafters 6' O. C. Windows are 8" x 10" four light on the first floor and 9"x 12" four											
light over 9"x 12" four light in the hayloft.											
Barn i	s in good condition. Nec	eds new roof and some siding r	eplaced. East lean-to								
*PHYSICAL NOTES: needs											
*UTM ZONF·		*RESTRICTED: Y o	r N								
*UTM EASTING:		<del></del>									
*UTM NORTHING:											









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 29, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 29, 2013 **ROLL NUMBER:** 

PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner

* = REQUIRED FIELD





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 29, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: June 29, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: ____
DATE OF PHOTO:

Jim Stone June 29, 2013 ROLL NUMBER: PHOTO NUMBER:

5

First floor, looking SE, 6x6 post, (3) 2x8's beam, 2x8 joists, box stalls on East wall.

CAMERA DIRECTION: East wall.



PHOTOGRAPHER: ____ DATE OF PHOTO: Jim Stone June 29, 2013 ROLL NUMBER: PHOTO NUMBER:

6

First floor, looking NW, box stalls on West wall, stairs, granary and feed

CAMERA DIRECTION: room in NW corner.





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 29, 2013

**ROLL NUMBER:** PHOTO NUMBER:

Hayloft, looking NW, 2x6 rafters, 2x6 brace supporting center of

CAMERA DIRECTION: rafter, 6' O. C.



PHOTOGRAPHER: Jim Stone

DATE OF PHOTO: June 29, 2013

**ROLL NUMBER:** PHOTO NUMBER:

Hayloft, looking NE, 2x6 rafters and 2x6 support for center of rafters, 6' O.

CAMERA DIRECTION: C.






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 29, 2013

**PHOTO NUMBER:** 

Hayloft, looking North, North gable wall and hayloft door, note CAMERA DIRECTION: diagonal sheathing.







#### **HISTORY**

This farm located in the NE ¼ of Section 15, Spirit Mound Township, Clay County was homesteaded by Joseph Hixson.

The 1894 Clay County Atlas lists Casper Hixson as the owner.

The 1901 and 1912 Clay County Atlas lists Jasper Hixson as the owner.

The 1924, Clay County Atlas lists Walter I. Cleland as the owner.

The 1937, 1948 and 1956 Clay County Atlas lists W. L. Cleland as the owner.