

#### SITE INFORMATION

\*SURVEY DATE: Aug. 14, 2012

\*ADDRESS: 30362 Greenfield Road \*COUNTY: Clay

\*SURVEYOR: Jim Stone

\*CITY: Beresford

LOCATION DESCRIPTION: South Dakota Highway 50, East two miles to Greenfield Road, turn left (North), 14-1/2 miles to 304<sup>th</sup> Street, about ½ mile on North, on the right (East) side.

LEGAL DESCRIPTION: SW 1/4, 2 – 94 – 51 Garfield Twp.

*QUARTER 1:	SW 1/4	OWNER NAME:	Jay &	Clec	o Cla	rk				
*QUARTER 2:		OWNER ADDRESS:	200 W.	. Cla	ıtk					
*TOWNSHIP:	Garfield	OWNER CITY:	Alcest	er						
*RANGE:	51	OWNER STATE:	South	Dak						
*SECTION:	2	OWNER ZIP:								
ACRES:	157.96	QUAD NAME:								
OWNER CODE 1:	Р									
<b>OWNER CODE 2:</b>										
OWNER CODE 3:										
HISTORIC SIGNI	FICANCE									
*D0	DE:	REGISTER N	AME:							
*DOE DA	ГЕ:		OPERT	Y N/	AME:	<u> </u>				
			~			<b>.</b>				
	I CTATUC.	SIGNI	FICANC					S	L	
			FICANC					-	_	
			FICANC			. 2.	IN	3	L	
	NUMBER: TRATING: C or N		ERIA 1:	Δ	R	С	П			
	PERIOD:		ERIA 2:			-				
	· Entrop:		ERIA 3:			-				
			ERIA 4:							
SIGNIFICANCE NOT	TES:									
STRUCTURE DE	TAUS									
* = REQUIRED F	IELD									1



SHPO ID:		_	
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Livestock	FOUNDATION:	Native stone with mortar
CURRENT SUBFUNCTION:	Straw and grain storage	ROOF MATERIAL:	Some steel over cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Western feeder barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x4, sheathing & ½"x 8" cedar lap siding (shorts)
STORIES:		SIGNIFICANT PERSON:Ja	y & Cleo Clark
*DATE OF CONSTRUCTION:	<u>?</u> CU	LTURAL AFFILIATION:	?

ALTERED/MOVED NOTES: Original site. All stalls and milk cow stanchions have been removed. Some of the foundation has been repaired with poured concrete.

INTERIOR NOTES: <u>Has two rows 4x6 posts and a 4x6 for a beam. 2x6 floor joists. 6'x8' granary and a</u> 7' x 8' milk room are still in place. All evidence of any stalls or stanchions is gone.

OTHER NOTES: <u>Windows were 4"x24" four light</u>. Walls are 2x4 with sheathing and ½"x8" cedar lap lap siding in 3' lengths (referred to as shorts and is cheaper). Rafters are 2x6 with no bracing. The North side is covered with corrugated galv. steel. The South side is cedar shingles. There is some corrugated galv. steel to repair places on the walls.


\*PHYSICAL NOTES: <u>Barn is in fair condition. The roof is not leaking yet. Needs roof re-roofed and</u> repairs on doors and some windows.


*11714 20115-		V er N
*UTM ZONE:	*RESTRICTED:	Y OF N
*UTM EASTING:		
*UTM NORTHING:		
-		

\* = REQUIRED FIELD













 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 Aug. 14, 2012
 PHOTO NUMBER:
 1

 CAMERA DIRECTION:
 Looking NE, SW corner





PHOTOGRAPHER: Jim Stone Aug. 14, 2012 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER:

2 CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER:Jim StoneDATE OF PHOTO:Aug. 14, 2012

ROLL NUMBER: \_ PHOTO NUMBER: \_ CAMERA DIRECTION:

3	
Looking SW, NE corner	





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 Aug. 14, 2012
 PHOTO NUMBER:
 4

 CAMERA DIRECTION:
 Looking SE, NW corner





PHOTOGRAPHER:Jim StoneDATE OF PHOTO:Aug. 14, 2012

 ROLL NUMBER:

 PHOTO NUMBER:

 5

 First floor, South lean-to,

 CAMERA DIRECTION:





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: Aug. 14, 2012 ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 6 First floor, main barn, looking South, granary CAMERA DIRECTION: and milk room






PHOTOGRAPHER: Jim Stone DATE OF PHOTO: Aug. 14, 2012 ROLL NUMBER: \_\_\_\_ PHOTO NUMBER: \_\_\_\_ Fir loc

CAMERA DIRECTION: NW corner

First floor, main barn, looking NW, granary in NW corner

7





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 Aug. 14, 2012
 PHOTO NUMBER:
 8

 Hayloft, looking NE, no
 CAMERA DIRECTION:
 rafter bracing

\* = REQUIRED FIELD



464th AVE UNIVERS			NOOD TWP.		
	466th AVE		■C K Carlson Woltjer 30332 30337 ■	469th AVE	St Hanser 46975
Charles	5 BGordon R	4	3	2	1
304th ST	Johnson 30372	Nick Oyen ∎30396	Terry Jensen Gary 46718 Carlson # #46730	Clark 30362	Jeff Brosz 3038
C M Thedorff 46469 / Todd M		■ Merie Christensen 30404	Alden Lundquist 46733	M Schurch 30433 <b>u</b>	■ 30438
johnson 30437 7 Berg ₩ 30451	Ordand 8	9	10	NEWDALE ST	Ave 12
	Sternguist 30472 Dennis OConnell 46504 30485	$\sum_{i=1}^{n}$			■Kendai Frick 30474
305th ST	■K Dennis Hansen Johnson ■ 30512 30521		5		Charles Jensen 30514
Ryan Bear 11 30535 18	17	16	Roland Gylfe 30534 15	■Randall jensen 30540 14	30536 Ave 3
Brickson Bricks		Rolf	46776 St =	] ]ason Taylor Jensen <u>4</u> 6820 468 <u>8</u> 6	
Hickson W46426	Hansen Ölsom #46502 #465.64	Lundquist 46664 46636 46677 St		10620 10880	3
UN S Lindstrom 30624	Richa 46501	S St	M Doug Hamersma Hays 46741 46767		
19	20 Craig Nelson 30641	21	22	23	24
	Marlon Olson 30692 Spile ##48534		Brian Jensen 46750 46782 St m m	Kendal Swee ∎46836 (†	Roge 46904 Jense ∎St ■4695
Jerry 46449 Scott Whelchel St 30717	307th ST WRichard Lind 30720	Mike Zwier ■30724		S Kevin S Kevin Cobert Cobert 000 46837 m∞ ₩	
Hansen Hansen 46415 30	MARSHALL TOWN ST	James Danielson 30750 28	<u>s</u> . 27		25
	¥ ₩ 5 3 46582 Stm	■Marvin Christensen 30766	s 27 Hein 30768 Jens Nagiestad 46776 <b>1</b>	M M Saur Saur 46878 Arlin 46880	Eric Alexander ■46926
308th ST	Craig Jensen 30835 ■		Curtis	Don ■ Jensen ■Reid 46825 Jensen 46829	
42 8158	Ballinger 30839 32	33 Larry Larson 30869 =	Curtis Fickbohm 30836 34	35	Lamie Jens 30834 36

PRAIRIE CENTER TWP.



# HISTORY

This farm located in the SW ¼ of Section 2, Garfield Township, Clay County was homesteaded by Pol A. Olson.

The 1894 Clay County Atlas lists Pol Anders Olson as the owner.

The 1901 Clay County Atlas lists Charles R. Clark as the owner and a life lease to Pol Anders Olson..

The 1912 and 1924 Clay County Atlas lists Christine Clark as the owner.

The 1937 Clay County Atlas lists G. Clark as the owner.

The 1894 and 1956 Clay County Atlas lists C. D. Clark as the owner.