

"SITE INFORMATION				
*SURVEY DATE: June 21, 2013	*ADDRESS: 29778 455 <sup>th</sup> Ave.			
*SURVEYOR: Jim Stone	*COUNTY: Clay			
	*CITY: Wakonda			
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and				
South Dakota Highway 19, North 15 miles to 302 <sup>nd</sup> Street, turn left (West) about 7 miles to 455 <sup>th</sup> Ave., turn				
right (North) 4-1/4 miles, on the right (East) side.				
LEGAL DESCRIPTION: Stockland tract 1, W ½, SW ¼, 3 – 95 – 53 Star Twp.				
*QUARTER 1:SW 1/4	OWNER NAME: Wesley E. Stockland			
*QUARTER 2:OV	VNER ADDRESS: 29778 455 <sup>th</sup> Ave.			
*TOWNSHIP: Star	OWNER CITY: Wakonda			
*RANGE:53	OWNER STATE: South Dakota			
*SECTION:3	OWNER ZIP: 57073			
ACRES: <u>8.63</u>	QUAD NAME:			
OWNER CODE 1: P				
OWNER CODE 2:				
OWNER CODE 3:				
HISTORIC SIGNIFICANCE				
*DOE:	REGISTER NAME:			
*DOE DATE:	MULTIPLE PROPERTY NAME:			
DEACON INCLICIBLE.				
REASON INELIGIBLE:	-			
	CATEGORY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:				
REFERENCE NUMBER:	Olonii Ioanoe Eevee 2. N O E			
HISTORIC DISTRICT RATING: C or NC	CRITERIA 1: A B C D			
PERIOD:				
. I.N	CRITERIA 3: A B C D			
	CRITERIA 4: A B C D			
	CHILIDAN A D O D			
SIGNIFICANCE NOTES:				


#### STRUCTURE DETAILS




SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
<b>CURRENT FUNCTION:</b>	Shop	FOUNDATIO	N: Poured concrete	
	Storage and sheep		Steel roofing over	
CURRENT SUBFUNCTION:	barn	ROOF MATERIA		
	Livestock barn	•	PE: Gable roof	
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTE		
		STYL	.E: Western feeder barn	
OCCUPIED:	Yes	TYP	PE: Livestock barn	
ACCESSIBLE:	Yes with permission	WALLS:	4x6 and 2x6 studs, 1x6 #106 drop siding	
ACCESSIBLE.	permission	WALLS.	1x0 #100 drop siding	
STORIES:	2 5	SIGNIFICANT PERSON:	Jens C. Jensen	
*DATE OF CONSTRUCTION:	<del></del>	LTURAL AFFILIATION:	Danish	
DATE OF CONSTRUCTION.	Early 1900 S CO	LIURAL AFFILIATION.	Dallisli	
ALTERED/MOVED NOTES: Original site. All evidence of horse stalls and or milk cow stanchions has				
<del>-</del>				
been removed. Steel roofing has been installed over cedar shingles on the roof. Two lean-to's have				
been added later. North lean-to has been rebuilt, pole barn construction with steel sides and roof. Original				
barn has hayloft floor removed and a ceiling at 16'. Walls and ceiling have been insulated and lined with steel roofing for a shop. 20' x 16' fold up door installed in the West gable end wall. South lean-to also				
insulated and lined.				
		<u>-</u> .		
INTERIOR NOTES: All posts, beams and floor joists have been removed. The gutters are still in place so it appears that the South side and the North side of the original barn was for milk cow stanchions. There				
was a granary and a milk room in the NW corner, as per the owner.				
mas a granary and a minimos		<u></u>		
OTHER NOTES: 4x6 studs 2' O. C. with 1x6 #106 drop siding on all four walls of the original barn.				
2x6 rafters. Steel roofing over cedar shingles on original barn and steel roofing on the lean-to's.				
Windows are 8"x 10" four light. The South lean-to has 2x6 studs with 1x6 #106 drop siding.				
Trindows die 6 x 10 10di ligi	ii. The Couli lean to ha	5 ZXO StudS With TXO #100 u	nop slamg.	
*PHYSICAL NOTES: Barn is	s in good condition			
THISICAL NOTES. Bailli	s in good condition.			
			or N	
*UTM EASTING:				
*UTM NORTHING:				




#### SKETCH MAP









**PHOTOGR** 





PHOTOGRAPHER: June 21, 2013 DATE OF PHOTO:

**ROLL NUMBER:** PHOTO NUMBER:

CAMERA DIRECTION:

Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 21, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: June 21, 2013 PHOTO NUMBER:
CAMERA DIRECTION: Looking SE, NW corner






PHOTOGRAPHER: \_\_\_\_ DATE OF PHOTO: Jim Stone June 21, 2013 ROLL NUMBER: PHOTO NUMBER:

5

First floor, South lean-to, looking NW, lined and insulated for shop.

CAMERA DIRECTION: insulated for shop.



PHOTOGRAPHER: \_\_ DATE OF PHOTO:


Jim Stone June 21, 2013 ROLL NUMBER: PHOTO NUMBER:

6

First floor, original barn, looking SE, 16' high ceiling for shop and

**CAMERA DIRECTION:** machinery storage.





© Farm & Home Publishers, Ltd. 39 CLAY CO., SD



#### **HISTORY**

This farm located in the SW ¼ of Section 3, Star Township, Clay County was homesteaded by Patrick Kilbride.

The 1894 and 1901 Clay County Atlas lists Patrick Kilbride as the owner.

The 1912 Clay County Atlas lists John Kilbride as the owner.

The 1924 and 1937 Clay County Atlas lists Jens C. Jensen as the owner.

The 1948 and 1956 Clay County Atlas lists G. O. Jensen as the owner.

