


SITE INFORMATION				
*SURVEY DATE: August 12,	2013 *ADDRESS: 30533 457 <sup>th</sup> Ave.			
*SURVEYOR:Jim Stone	*COUNTY: Clay			
	*CITY: Wakonda			
LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and				
South Dakota Highway 19, North about 11 miles to 306th Street, turn left (West) about 5 miles to 457th Ave.,				
turn right, (North) about 3/4 mile, on the left (West) side.				
LEGAL DESCRIPTION: SE 1/4, NE 1/4, 14 – 94 – 53 Bethel Twp.				
*QUARTER 1: <u>NE 1/4</u>	OWNER NAME: Donald H. & Janice D. Lyso			
*QUARTER 2:	OWNER ADDRESS: 30520 458th Ave.			
*TOWNSHIP: Bethel	OWNER CITY: Wakonda			
*RANGE:53	OWNER STATE: South Dakota			
*SECTION:14	OWNER ZIP: <u>57073</u>			
ACRES: 40.24	QUAD NAME:			
OWNER CODE 1: P				
OWNER CODE 2:				
OWNER CODE 3:				
LISTODIC SIGNIFICANCE				
HISTORIC SIGNIFICANCE				
*DOE: REGISTER NAME:				
*DOE DATE:	MULTIPLE PROPERTY NAME:			
REASON INELIGIBLE:				
	CATEGORY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L			
REFERENCE NUMBER:				
HISTORIC DISTRICT RATING: C or N	IC CRITERIA 1: A B C D			
PERIOD:	CRITERIA 2: A B C D			
	CRITERIA 3: A B C D			
	CRITERIA 4: A B C D			
SIGNIFICANCE NOTES:				

#### STRUCTURE DETAILS



SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete	
CURRENT CURFUNCTION.	Vocant	DOOF MATERIAL	Asphalt shingles over	
CURRENT SUBFUNCTION:	Vacant	ROOF MATERIAL:		
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE	-	
HISTORIC SUBFUNCTION:	Hay & grain storage	STRUCTURAL SYSTEM		
			Gambrel roof barn	
OCCUPIED:	No	TYPE	Livestock barn	
			2x6 studs, 1x8 #106 drop siding and	
	Yes with		½"x6" cedar lap	
ACCESSIBLE:	permission	WALLS:	siding	
STORIES:	2	SIGNIFICANT PERSON:	Jen W. Jacobson	
*DATE OF CONSTRUCTION:	Early 1900's	CULTURAL AFFILIATION:	?	
ALTERED/MOVED NOTES: Original site. Roof covered with asphalt shingles over cedar shingles. All				
evidence of milk cow stanchions and horse stalls has been removed. Original 1x8 #106 drop siding				
covered with ½"x6" cedar lap siding later.				
· •				
INTERIOR NOTES: Two rows of 4x6 posts with 4x6's for beams support 2x 8 joists for hayloft floor.				
8' x8' granary still in the SW corner. One row 4x4 posts, 8' O. C., with 4x4 beam supporting 2x6 floor joists,				
4' O. C., in North lean-to.				
OTHER NOTES: 2x6 stud walls with 1x8 #1x6 drop siding and ½"x6" cedar lap siding. Rafters are 2x6's				
with 2x6 bracing at the roof hip. A 2x6 brace from the center of lower rafter down to hayloft wall at the				
floor level. This bracing is 2' O. C., which is very unusual. Windows were 8" x10" four light over 8"x 10"				
four light, double hung. No cupola. 14' x 32' lean-to on the North appears to have been built at the same				
time as the barn. 2x6 studs, 2x6 rafters and bracing, 2x8 floor joists, 4x6 posts and roof sheathing are all rough sawn cottonwood.				
*PHYSICAL				
	n fair condition.	*RESTRICTED: Y	or N	
*UTM EASTING:				
*UTM NORTHING:				









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013

**ROLL NUMBER:** PHOTO NUMBER: CAMERA DIRECTION:

Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013 **ROLL NUMBER:** 

**PHOTO NUMBER:** 

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: August 12, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: August 12, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Looking SE in North lean-to, 4x4 posts and 4x4 beam supporting 2x6 rafters, 4' O. C. for

CAMERA DIRECTION: hayloft.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NE, 4x6 posts, 4x6 beam and 2x8 floor joists, bottom of posts seems moved to the South for some

CAMERA DIRECTION: unknown reason.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 12, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking SW, 4x6 posts, 4x6 beam, 2x8 floor joists, note granary

CAMERA DIRECTION: in SW corner.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: August 12, 2013 PHOTOGRAPHER:

ROLL NUMBER: **PHOTO NUMBER:** 

Hayloft, looking SW, 2x6 rafters with a 2x6 brace down to floor on each rafter, 2' O. C., very

**CAMERA DIRECTION: unusual** 





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: August 12, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking SW, 2x6 brace on rafters at the

CAMERA DIRECTION: roof hip.

PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: August 12, 2013


**ROLL NUMBER:** 

**PHOTO NUMBER:** 

Hayloft, looking NW, open stud wall to ceiling

CAMERA DIRECTION: above North lean-to.





CLAY CO., SI



### **History**

This farm located in the NE  $\frac{1}{4}$  of Section 14, Bethel Township, Clay County was homesteaded by Jens W. Jacobson .

The 1894, 1901 and 1912 Clay County Atlas lists Jens W. Jacobson as the owner.

The 1924 Clay County Atlas lists Ferdinand Hansen as the owner.

The 1937, 1948 and 1956 Clay County Atlas lists T. Ellison as the owner.