


SITE INFORMATION

*SURVEY DATE: March 2	3, 2012 *ADDRESS	S: 45438 Timber Road			
*SURVEYOR: Jim Stor	ne *COUNTY	: Clay			
	*CITY	7: Meckling			
	-	kota Highway 50 about 1 mile, turn le			
(South) on South Dakota highway	19, turn right (West) on Timber Ro	oad about 8 miles, on the right (North	h)		
side.					
LEGAL DECORIDEDAN E 1/ OW	1/ F 0.000 -f.W.000! 0 .00 . 5	50. Namura Tura			
LEGAL DESCRIPTION: E 1/2 SW	1/4, Exc. S 693' of W 300', 9 – 92 – 5	53, Norway Twp.			
*QUARTER 1: SW 1/4	OWNER NAME:	Marianne Jepsen			
*QUARTER 2:	OWNER ADDRESS:	45438 Timber Road			
*TOWNSHIP: Norway					
*RANGE: <u>52-53 W</u>		OWNER STATE: South Dakota			
*SECTION: 9	OWNER ZIP:				
ACRES: 114	QUAD NAME:	:			
OWNER CODE 1: P					
OWNER CODE 2: F S L F					
OWNER CODE 3: F S L F	•				
HISTORIC SIGNIFICANCE					
*DOE:	REGISTER N	IAME:			
*DOE DATE:		MULTIPLE PROPERTY NAME:			
REASON INELIGIBLE:					
		CATEGORY:			
NOMINATION STATUS:	SIGN	IIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGN	IIFICANCE LEVEL 2: N S L			
REFERENCE NUMBER:					
HISTORIC DISTRICT RATING: C	or NC CRIT	TERIA 1: A B C D			
PERIOD:		TERIA 2: A B C D			
		TERIA 3: A B C D			
	CRIT	TERIA 4: A B C D			
SIGNIFICANCE NOTES.					
SIGNIFICANCE NOTES:					



STRUCTURE DETAILS						
SHPO ID:						
*PROPERTY NAME:						
OTHER NAME:						
O THER TO MINE.						
CURRENT FUNCTION:	Hogs and shee	p FOUNDATION:	Poured concrete			
CURRENT SUBFUNCTION:		ROOF MATERIAL:	Steel over cedar			
HISTORIC FUNCTION:	Livestock	ROOF SHAPE:				
HISTORIC SUBFUNCTION:		STRUCTURAL SYSTEM:				
			Gambrel roof			
OCCUPIED:	Yes		Livestock			
0000.125.	Yes with	2.	2x6, sheathing&			
ACCESSIBLE:	permission	WALLS:	1x6 #106 siding			
STORIES:	2	SIGNIFICANT PERSON:	Jepsen			
*DATE OF CONSTRUCTION:	?	CULTURAL AFFILIATION:	Danish			
ALTERED/MOVED NOTES: Moved to this site in 19 Owners do not know where the barn came						
from or who lived here then or when this barn was moved. Roof covered with steel roofing. Horse stalls						
and stanchions have been removed. Two rows 6x6 beams, but the posts have been removed. Three 6x6						
posts in the center with 6x6 beam out and under original beams to support floor. Has been remodeled						
into a hog farrowing barn with slatted floor. 12' lean-to added to the south side						
INTERIOR NOTES:						
2ve etud w	alle 12' high with	shoothing 8 1v6 pattern #106 siding	Ove raftore with Ove			
2x6 stud walls 12' high with sheathing & 1x6 pattern #106 siding. 2x6 rafters with 2x6 OTHER NOTES: bracing,						
³ / ₄ " sheathing, cedar shingles and steel roofing. Braced rafted system. 9"x12" four light windows.						
		-				
*PHYSICAL NOTES: Barn is in good condition.						









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 23, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 23, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking SW, NE corner





PHOTOGRAPHER: DATE OF PHOTO: March 23, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner



PHOTOGRAPHER: Jim Stone

DATE OF PHOTO: March 23, 2012

ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: braced rafter system


Hayloft, looking NW,





PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: March 23, 2012 PHOTO NUMBER: 5
Hayloft, looking SW
CAMERA DIRECTION: braced rafter system







HISTORY

This farm located in the E $\frac{1}{2}$ of the SW $\frac{1}{4}$ of Section 9, Norway Township, Clay County was homesteaded by Lewis Anderson.

The 1894, 1901 and 1912 Clay County Atlas lists T. S. Myron as the owner.

The 1924 Clay County Atlas lists Christ Nelson as the owner.

The 1937 Clay County Atlas lists M. Anderson as the owner.

The 1948 and 1956 Clay County Atlas lists Magnus P. Jepsen as the owner.