

"SITE INFORM	ATION							
*SURVEY D	ATE: July 26,	2013 *ADDRESS:	5: 46008 310 th Street					
*SURVE	YOR: Jim Stor	ne *COUNTY:	Clay					
		*CITY:	Vermillion					
LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and								
South Dakota Highway 19, North about 8 miles to 310 th Street, turn left (West) about 2-1/2 miles follow								
310 th Street, it will have two corners, on the right (North) side.								
LEGAL DESCRIPTION: W ½, SW ¼ Exc W 330' of N 396' of SW ¼, SW 1/4, 4 – 93 – 52 Spirit Mound								
Twp.								
*QUARTER 1:	SW 1/4	OWNER NAME:	OWNER NAME: Kurt T. & Margaret E. Amundson					
*QUARTER 2:		OWNER ADDRESS:	46003					
*TOWNSHIP:	Spirit Mound	OWNER CITY:	OWNER CITY: Vermillion					
*RANGE:	52	OWNER STATE: South Dakota						
*SECTION:	4	OWNER ZIP:	57069					
ACRES:	75.01	QUAD NAME:						
OWNER CODE 1:	Р							
OWNER CODE 2:								
OWNER CODE 3:								
HISTORIC SIGNIFICANCE								
HISTORIC SIGNII ICANCE								
_			REGISTER NAME:					
*DOE DA	-	MULTIPLE PR	MULTIPLE PROPERTY NAME:					
REASON INELIGIBLE:								
			CATEGORY:					
	N STATUS:		SIGNIFICANCE LEVEL 1: N S L					
DATE LISTED:			FICANCE LEVEL 2: N S L					
	E NUMBER:							
HISTORIC DISTRICT RATING: C or NC			RIA 1: A B C D					
	PERIOD:		ERIA 2: A B C D					
			RIA 3: A B C D					
		CRITE	ERIA 4: A B C D					
CIONIFICANCE NOTES.								
SIGNIFICANCE NOTES:								


STRUCTURE DETAILS




SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Calving barn	FOUNDATI	ON:	Native stone with some mortar & poured concrete			
	Machinery storage		Steel roofing over				
CURRENT SUBFUNCTION:	and straw storage	_ ROOF MATER		cedar shingles			
HISTORIC FUNCTION:	Livestock barn	_ ROOF SHA	PE:	Gambrel roof			
HISTORIC SUBFUNCTION:	Hay and grain storage	_ STRUCTURAL SYST	EM:	Balloon framing			
		STY	LE:	Gambrel roof barn			
OCCUPIED:	No	TY	PE:	Livestock barn			
ACCESSIBLE:	Yes with permission	WALLS:		2x6 studs, 1x6 #106 drop siding and ½"x6" cedar lap siding and steel roofing.			
STORIES:	2	SIGNIFICANT PERSON:		John F. Knudson			
*DATE OF CONSTRUCTION:		JLTURAL AFFILIATION:		Norwegian			
ALTERED/MOVED NOTES: Original site. Most evidence of horse stalls or milk cow stanchions has been							
removed. 12' x 26' of hayloft floor raised to 14' at the North end of center alley for machinery storage.							
12' x 14' opening added on North wall. 12' x 36' pole barn lean-to added on the East side. Poured concrete							
has been added on the out side to hold old native rock foundation. Owner did not know if there ever was							
any mortar between the rocks. Roof and sidewalls covered with steel roofing Except the North wall.							
INTERIOR NOTES: Two rows of 6x6 posts and 6x6 beams and one row of 4x6 posts and 6x6 beams to							
support hayloft floor The hayloft floor joists are 2x8's. Double 2x6 posts, 12' O. C. support roof hip. Two 1x6's brace roof hip. One 2x10 brace from top of wall in the hayloft down to the floor 8' O. C.							
OTHER NOTES: 2x6 stud walls, 1x6 #106 drop siding with ½"x 6" cedar lap siding over old siding and							
now steel roofing over all but the North wall. Rafters are 2x6's. Windows are 8" x10"four light. There are							
painted stencils on the inside of original 1x6 # 106 drop siding. "Buy your lumber of (?) Fullerton Lumber Co. Vermillion, So. Dak." Owner says that there is the same stencil on a floor joist but we could not find it.							
*PHYSICAL NOTES: Barn is in good condition.							
*UTM ZONE: *UTM EASTING: *UTM NORTHING:			Υo	r N			
	· · · · · · · · · · · · · · · · · · ·						




SKETCH MAP



SOUTH ELEVATION







PHOTOGR





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





Jim Stone PHOTOGRAPHER: July 26, 2013 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: **DATE OF PHOTO:**

Jim Stone July 26, 2013 **ROLL NUMBER:**

PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: July 26, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, 4x6 post with a 2x6 on each side, 6x6 beam, 2x8 joists and part of a double horse stall on

CAMERA DIRECTION: West side.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 26, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SE, 6x6 posts, 6x6 beam on the East side where milk

CAMERA DIRECTION: cow stanchions were.





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 26, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NW, double 2x6 posts, 12' O.

CAMERA DIRECTION: C. supporting roof hip.



PHOTOGRAPHER: Jim Stone DATE OF PHOTO:

July 26, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft. looking SE, double 2x6 posts supporting roof hip, (2) 1x6's bracing rafters at

CAMERA DIRECTION: the hip.





PHOTOGRAPHER: ___ DATE OF PHOTO: ___

Jim Stone July 26, 2013 ROLL NUMBER: PHOTO NUMBER:

Ç

Hayloft, looking West, painted stencil,
Buy Your Lumber of(?)
Fullerton Lumber Co.

CAMERA DIRECTION: Vermillion, So. Dak.



PHOTOGRAPHER: _ DATE OF PHOTO:


Jim Stone July 26, 2013 ROLL NUMBER: PHOTO NUMBER:

10

Hayloft, old ½ round wood window from the South gable end peak, was replaced with a ½ round vinyl louver.

CAMERA DIRECTION: round vinyl louver.







HISTORY

This farm located in the SW ¼ of Section 4, Spirit Mound Township, Clay County was homesteaded by Wesley C. Wadsworth.

The 1894 Clay County Atlas lists Jacob A. Johnson as the owner.

The 1901 Clay County Atlas lists John F. Knudson as the owner.

The 1937 Clay County Atlas lists Federal Land Bank, Omaha as the owner and J. Campbell & H. Nelson as the operators (renters).

The 1948 Clay County Atlas lists Howard Yusten as the owner.

The 1956 Clay County Atlas lists L. O. Christianson as the owner.

