


SITE INFORMATION						
*SURVEY DATE: November 18,	2013 *ADDRESS: 46428 314 th Street					
*SURVEYOR:Jim Stone	*COUNTY: Clay					
	*CITY: Vermillion					
LOCATION DESCRIPTION: From Vermillion, from Intersection of South Dakota Highway 50 bi-pass and						
University Road, (North) about 3 miles to 314th Street, turn right (East) about 1/4 mile, on the left (North)						
side.						
LEGAL DESCRIPTION: _E 425' of W 1,753' of S 860', SW ¼, 30 – 93 – 51 Prairie Center Twp.						
*QUARTER 1:SW 1/4	OWNER NAME: Patrick John Manning					
*QUARTER 2:	OWNER ADDRESS: 26440 Ridge Place					
*TOWNSHIP: Prairie Center	OWNER CITY: Vermillion					
*RANGE: <u>51</u>	OWNER STATE: So. Dak.					
*SECTION:	OWNER ZIP: <u>57069</u>					
ACRES: 8.40	QUAD NAME:					
OWNER CODE 1: P						
OWNER CODE 2:						
OWNER CODE 3:						
HISTORIC SIGNIFICANCE						
*DOE:	REGISTER NAME:					
*DOE DATE:	MULTIPLE PROPERTY NAME.					
REASON INELIGIBLE:						
	CATEGORY:					
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L					
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L					
REFERENCE NUMBER:						
HISTORIC DISTRICT RATING: C or NC	CRITERIA 1: A B C D					
PERIOD:						
. E.NOD.	CRITERIA 3: A B C D					
	CRITERIA 4: A B C D					
	OMILMAT. A B C D					
SIGNIFICANCE NOTES:						
SIGNIFICANCE NOTES:						

STRUCTURE DETAILS




SHPO ID:		<u>-</u>			
*PROPERTY NAME:					
OTHER NAME:					
CURRENT FUNCTION:	Storage	FOUNDA	TION:	Poured concrete	
		-	-	Steel roofing over	
CURRENT SUBFUNCTION:	Storage	ROOF MATE	RIAL:	cedar shingles	
HISTORIC FUNCTION:	Livestock barn	ROOF SH	HAPE:	Gambrel roof	
HISTORIC SUBFUNCTION:	Hay & grain storage	STRUCTURAL SYS	STEM:	Balloon framing	
		S	TYLE:	Gambrel roof barn	
OCCUPIED:	No	•	TYPE:	Livestock barn	
			-	2x6 studs, 1x10	
	Yes with			shiplap and steel	
ACCESSIBLE:	permission	WALLS:	-	roofing.	
STORIES:		SIGNIFICANT PERSON:	Jol	hn Hendricks	
*DATE OF CONSTRUCTION:	1915 to 1925 CU	ILTURAL AFFILIATION:		?	
ALTERED/MOVED NOTES: Original site. Most of the horse stalls have been removed on the East side					
but enough evidence remains to show that (5) double and (1) single horse stalls were along the East wall.					
Two cow stalls remain at the South end on the West side and evidence suggests that there were stalls					
from the South wall to the North wall. Roof has been covered with steel roofing over the cedar shingles.					
The walls have been covered with steel roofing and it appears that the siding was removed.					
INTERIOR NOTES. Two of the double have stelle and two of the will now stelle are atill in place					
INTERIOR NOTES: Two of the double horse stalls and two of the milk cow stalls are still in place.					
Two granaries in the center at the North end and a tack room in the center at the South end are still in					
place. Three rows of 6x6 posts and 6x6 beams run North to South. The East row has (3) 2x6's for a beam. Floor joists are 2x10's.					
OTHER NOTES: 2x6 stud walls with 1x10 shiplap and steel roofing. Rafters are 2x6's with two rows of					
6x6 posts supporting a triple 2x6 plate at the roof hip. Windows are replaced with a 1 light thermo pane in an aluminum frame. They have dividers between the glass to look like 10"x 12" four light windows.					
<u> </u>					
Two windows in the South Wall of the hayloft are taller and have dividers to look like 8 light windows. Metal cupola still on the roof.					
*PHYSICAL					
	in good condition.	*RESTRICTED:	Y oı	r N	
*UTM EASTING:					
*UTM NORTHING:					







SKETCH MAP



SOUTH ELEVATION

PHOTOGR





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 18, 2013

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION:

Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

November 18, 2013

ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner






PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 18, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 18, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 18, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE at double horse stalls on

CAMERA DIRECTION: West side



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 18, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW, 6x6 posts, 6x6 beam, 2x10 floor joists, two granaries in the center at

CAMERA DIRECTION: the North end





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 18, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, West side, looking South, cow stalls along the East wall of the West side, only two of CAMERA DIRECTION: these stalls remain.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 18, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, 2x6 rafters and 6x6 posts and triple 2x6's for a plate to support the roof

CAMERA DIRECTION: hip.





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: November 18, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, 2x6 rafters and 6x6 posts and triple 2x6's for a plate all support the roof

CAMERA DIRECTION: hip.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone November 18, 2013

ROLL NUMBER: **PHOTO NUMBER:**

Hayloft, looking South, South gable end and

CAMERA DIRECTION: hayloft door.





© Farm & Home Publishers, Ltd.

33

CLAY CO., SD





History

This farm located in the SW ¼ of Section 30, Prairie Center Township, Clay County was homesteaded by John Hendricks.

The 1894, 1901 and 1912 Clay County Atlas lists John Hendricks as the owner

The 1924 Clay County Atlas lists M. S. Hendricks as the owner.

The 1937 Clay County Atlas lists W. H. Beede as the owner and G. Hendricks as the operator (renter).

The 1948 Clay County Atlas lists E. C. Barton as the owner.

The 1956 Clay County Atlas lists Helen Sill as the owner.

