

<u>Site</u>	INF	<u>ORM/</u>	<u>NOITA</u>

*SURVEY DA	ATE: <u>M</u>	arch 20	, 2013	*ADDRESS:	29750 467 th Ave						
*SURVEY	OR: Ji	m Stone	е	*COUNTY:	Clay						
	·			*CITY:	Beresford						
					'						
LOCATION DESCR	IPTION: F	rom Ver	million, South	Dakota Highway	/ 50 Eas	st 2 r	niles	to C	Greer	nfield	Road,
turn left (North) 18	miles, on the	e left (W	est) side.								
LEGAL DESCRIPTION	ON: <u>SW 1/4</u>	4, NE ¼,	3 - 95 - 51 G	lenwood Twp.							
*OUADTED 4.	NIT 4/4			NAVAIED NAME.	Manal	– also,	l l	a .a al			
*QUARTER 1:	NE 1/4				Marc Edward Landeen						
*QUARTER 2:	01		OVVN	ER ADDRESS:							
*TOWNSHIP:	Glenwood	1			Beresford						
*RANGE:	51		O		South Dakota						
*SECTION:	3			OWNER ZIP:							
ACRES:	159.70			QUAD NAME:							
OWNER CODE 1: OWNER CODE 2:	Р										
OWNER CODE 3:											
HISTORIC SIGN	<u>IFICANCE</u>										
*D(OE:			REGISTER NA	ME:						
*DOE: *DOE DATE:				MULTIPLE PR	OPERT	ΥN	AME:				
REASON INELIGIBLE:											
					C	CATE	GOF	RY:			
NOMINATION STATUS:				SIGNIFICANCE LEVEL 1: N S L							
DA	ΓE LISTED:			SIGNI	IFICANCE LEVEL 2: N S L			L			
REFERENCE	NUMBER:										
HISTORIC DISTRIC	T RATING:	C or	NC	CRITE	ERIA 1:	Α	В	С	D		
	PERIOD:			CRITE	RIA 2:	Α	В	С	D		
				CRITE	RIA 3:	Α	В	С	D		
				CRITE	RIA 4:	Α	В	С	D		
SIGNIFICANCE NO	TES:										


STRUCTURE DETAILS




SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Winter cattle barn	FOUNDATION:					
CURRENT SUBFUNCTION:	Vocant	DOOF MATERIAL.	Steel over cedar shingles				
	Vacant						
HISTORIC FUNCTION:	Dairy barn	ROOF SHAPE:					
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:					
000115155			Gable roof barn				
OCCUPIED:	No	IYPE:	Livestock barn 2x6 studs, 1x10				
			sheathing and 26"				
	Yes with		horizontal steel				
ACCESSIBLE:	permission	WALLS:	roofing				
STORIES:			John Norling				
*DATE OF CONSTRUCTION:	Early 1900's	CULTURAL AFFILIATION:	Swedish				
ALTERED/MOVED NOTES: _	Original site. Any ev	vidence of horse stalls and milk co	w stanchions has				
been removed. Was a gambre	el roof barn with lear	n-to on the south. In the 1950's ba	rn was remodeled.				
		tch gable roof. Lean-to added on					
		of the East wall and the milk room cupola was installed on new roof.	were built with 8"				
Concrete blocks about that th	ne. Original metal t	cupola was ilistalled off flew root.					
INTERIOR NOTES: The orig	inal barn has two rov	ws of 6x6 posts and 6x6 for a bean	n. The posts have				
been removed and replaced with 3" steel pipe posts when it was remodeled for swine. The floor joists							
for the hayloft floor are 2x8's							
OTHER NOTES: 2x4 stud walls with 1x8 diagonal sheathing on all four walls and steel roofing over							
the sheathing. Rafters are 2x6's. Hayloft has no stairs to access, so no details of rafter bracing							
or pictures were possible. Windows are 8"x10" four light.							
*PHYSICAL NOTES: Barn is	s in poor condition.	North lean-to is falling down.					
*UTM ZONE:		*RESTRICTED: Y	or N				
			Vi 14				
*UTM EASTING:							
*UTM NORTHING:							



SKETCH MAP







PHOTOGR





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 20, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: March 20, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 20, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: March 20, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 15, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking into CAMERA DIRECTION: milk room.



PHOTOGRAPHER: DATE OF PHOTO:


March 20, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking West in main barn, walls lined and any evidence of stalls or stanchions

CAMERA DIRECTION: removed.







HISTORY

This farm, located in the SW ¼ of Section 3, Glenwood Township, Clay County was homesteaded by John Norling.

The 1894, 1901 and 1912 Clay County Atlas lists John Norling as the owner.

The 1912, 1924, 1937, 1948 and 1956 Clay County Atlas lists Maude Landeen as the owner. The 1937 Clay County Atlas lists E. C. Landeen as the operator.

The following is from

The Beresford Centennial Book 1884 - 1984

John And Anna Norling

John Norling was born in 1843 in Gnarp Parish, Halsingland, Sweden and came to Allamahee County in 1869. In 1870 he came to Clay County and homesteaded in Glenwood township. John was a bachelor for many years, but about 1885 he married a widow, Anna Dahlin Anderson. Anna had two children, George and Amelia.

John and Anna had three children: Joseph, born in 1886, Maude, 1887 and Arthur, 1889. They were married for five years when Anna died of a ruptured Appendix. John was left with the task of raising five children, ranging in age from 12 to one year. John died on the homestead in 1922.

Joseph married Clara Thompson. They farmed across the road from the Norling homestead.

Maude married Edwin Landeen. They lived on the Norling Homestead and the farm is home to fourth generation descendants, Roy Landeens widow, Joann, and children Kristy and Marc.

Arthur was married twice to two sisters, Mable and Amy. They were daughters of John and Helen Anderson Bergquist, Swedish immigrants. The first wife, Mable, died and in 1927, he married Amy.



Arthur and Amy had five children. A daughter died in infancy. The living children are John, Art Jr., Charles and Richard.

The Art Norling family lived on the farm directly north of the Norling homestead which Art owned and operated. Mrs. Richard (Annadell) Norling now resides there.