


""SITE INFORMATION									
*SURVEY DATE: July	<i>,</i> 18, 2013	*ADDRESS:	45242 300th Street						
	Stone	*COUNTY:	Clay						
		- *CITY:							
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and									
South Dakota Highway 19, North 15 miles to 302 nd Street, turn left (West) about 10miles to 452 th Ave., turn									
right (North) 2 miles to 300st Street, turn right (East) about ¼ mile, on the left (North) side.									
LEGAL DESCRIPTION: S ½, S ½, Lots 1 & 2, SW ¼, 18 – 95 – 53 Star Twp.									
			Clark V. Christer	nsan					
*QUARTER 1: SW1/4		OWNER NAME:	CD-Virgil E. Chri		n Est	ate			
*QUARTER 2:	OWI	NER ADDRESS:	45238 300 th Street						
*TOWNSHIP: Star		OWNER CITY:	Wakonda						
*RANGE:53		OWNER STATE:	South Dakota						
*SECTION: 18		OWNER ZIP:	57073						
ACRES: 38.20		QUAD NAME:							
OWNER CODE 1: P									
OWNER CODE 2:									
OWNER CODE 3:									
HISTORIC SIGNIFICANCE									
*DOE:		REGISTER NAME:							
*DOE DATE:		MULTIPLE PR	OPERTY NAME:						
REASON INELIGIBLE:									
			CATEGOR	/ :					
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N S L							
DATE LISTED:		SIGNII	FICANCE LEVEL	2: N	S	L			
REFERENCE NUMBER:									
HISTORIC DISTRICT RATING: (_	RIA1: A B	_					
PERIOD:			RIA 2: A B						
			RIA 3: A B						
		CRITE	RIA 4: A B	C D					
SIGNIFICANCE NOTES:									

STRUCTURE DETAILS



SHPO ID:								
*PROPERTY NAME:								
OTHER NAME:								
			Native stone with					
CURRENT FUNCTION:	Storage	FOUNDATION:	poured concrete					
			Asphalt shingles over					
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	cedar shingles					
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel roof					
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing					
		STYLE:	Gambrel roof barn					
OCCUPIED:	Yes	TYPE:	Livestock barn					
			2x6 studs, 1x8 #106 drop siding and					
	Yes with		½"x6" cedar lap					
ACCESSIBLE:	permission	WALLS:	siding					
STORIES:	S	IGNIFICANT PERSON:J	ohn & James Griffin					
*DATE OF CONSTRUCTION:	1919 CUI	TURAL AFFILIATION:	?					
ALTERED/MOVED NOTES:	Original site. Original ba	arn built about 1890 burned do	own in 1918 or 1919.					
This barn was built about 1919 on the original foundation. However the new barn is 36' wide and the old								
barn was 56' wide. It is not known what the old barn looked like and if it had a 20' lean-to on the South								
side. The old foundation on the South side, is still in place. Most of the horse stalls and milk cow								
stanchions have been removed. Asphalt shingles have been applied over cedar shingles on the roof. The								
2x6 solid wall has been partial removed and double 2x6 posts and 6x6 posts support double 2x6 plate now.								
INTERIOR NOTES: One row of 4x6 posts, and 4x6 beam, one row of 6x6 posts and (3) 2x8's for a beam								
and a 2x6 solid wall supporting the 2x10 joists for the hayloft floor. Two rows of 6x6 posts and a 6x6 beam								
support the hip in the hayloft. These posts are 14' – 12' – 14' O.C.								
OTHER NOTES: 2x6 stud walls and 2x8 stud walls on the gable ends, with 1x8 diagonal sheathing on all								
four walls with ½"x6" cedar lap siding. Rafters are 2x6's with (2) 1x6's bracing on the hips. Windows were								
8"x10" four light over 8"x10" four light and are two windows wide on the first floor. Very ornate cupola								
from the 19-teens.								
	s in poor condition. Roo	f is leaking had						
5.5/12 113 125. Daill 1	5 poor condition. Roo	. io iouning budi						
·		*RESTRICTED: Y	or N					
*UTM EASTING:								
*UTM NORTHING:								









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 18, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 18, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 18, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July18, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: July 18, 2013

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

5

First floor, looking SE, 6x6 post, (3) 2x8's beam, 2x10 floor joists, note diagonal sheathing on

CAMERA DIRECTION: wall.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 18, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, solid 2x6 wall that has been removed, 6x6 and (3)2x6's posts have been

CAMERA DIRECTION: placed at random.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 18, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, 6x6 post, 6x6 beam

CAMERA DIRECTION: supporting hip.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 18, 2013

ROLL NUMBER: PHOTO NUMBER:

8

Hayloft, looking NW, (2) 1x6 bracing on 2x6

CAMERA DIRECTION: rafters at the hip.






Jim Stone PHOTOGRAPHER: July 18, 2013 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, East gable end wall, note 2x8 studs with plate and 2x6 studs above, diagonal sheathing and hayloft

CAMERA DIRECTION: door.







HISTORY

This farm located in the SW ¼ of Section 18, Star Township, Clay County was homesteaded by John Patrick.

The 1894 and 1901 Clay County Atlas lists M. D. Thompson as the owner.

The 1912 Clay County Atlas lists John and James Griffin as the owners.

The 1924 Clay county Atlas lists Jacob M. Mikkelson as the owner.

The 1937 Clay County Atlas lists J. M. & L. Mikkelson as the owners.

The 1948 and 1956 Clay County Atlas lists Jacob M. Mikkelson as the owner.