

SITE INFORMATION

*SURVEY DATE: Octob	per 30, 2012	*ADDRESS: <u>30474 469th Ave.</u>								
*SURVEYOR: _Jim S	tone	*COUNTY:	: Clay							
		*CITY:	Beresf	ord						
LOCATION DESCRIPTION: Fr	rom Vermillion South	Dakota Highway :	50 East a	about 2	2 mile	es to	Gree	enfield		
Road, turn left, (North) 13-1/2 miles to 305 th Street, Turn right (East) 1mile to 469 th Ave., turn left (North)										
about 1/4 mile on the right (East)	side.									
LEGAL DESCRIPTION: SW 1/4	, 12 – 94 – 51 Garfiel	d Twp.								
*011407504 004444										
*QUARTER 1: SW 1/4	_	Margaret Frick								
*QUARTER 2:		OWNER ADDRESS:								
*TOWNSHIP: Garfield		OWNER CITY:								
*RANGE: <u>51</u>		WNER STATE:		akota						
*SECTION: 12		OWNER ZIP:								
ACRES: <u>160.18</u> OWNER CODE 1: P		QUAD NAME: _								
OWNER CODE 1: P										
OWNER CODE 3:										
OWNER CODE 3.										
<u> </u>										
HISTORIC SIGNIFICANCE										
*DOE:		REGISTER NAME:								
*DOE DATE.		MULTIPLE PRO	OPERTY	NAME	:					
REASON INELIGIBLE:										
			CA	TEGO	RY:					
NOMINATION STATUS:		SIGNIF	ICANCE	LEVE	L 1:	N	S	L		
DATE LISTED:		SIGNIF	ICANCE	LEVE	L 2 :	N	S	L		
REFERENCE NUMBER:										
HISTORIC DISTRICT RATING:	C or NC	CRITEI	RIA 1:	А В	С	D				
PERIOD:		CRITEI	RIA 2:	А В	С	D				
		CRITE	RIA 3:	А В	С	D				
		CRITEI	RIA 4:	A B	С	D				
SIGNIFICANCE NOTES:										


STRUCTURE DETAILS



SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Storage		FOUNDATION		foundation		
	•			Ptd. steel roofing over cedar			
CURRENT SUBFUNCTION:	Storage		ROOF MATERIAL				
HISTORIC FUNCTION:			ROOF SHAPE				
HISTORIC SUBFUNCTION:	Hay and grain storage		STRUCTURAL SYSTEM				
			STYLE	E: Gambrel roof barn			
OCCUPIED:	Yes		TYPE				
ACCESSIBLE:	Yes with permission WALLS			2x6 stud with sheathing ½"x6" S: cedar lap siding	sheathing ½"x6"		
7.00200.022.	pormiodion		***************************************	or occur in ordining			
STORIES:	2	9	SIGNIFICANT PERSON:				
*DATE OF CONSTRUCTION:	1919 CULTURAL AFFILIATION:			?			
DATE OF CONCINCOTION.	1313	00	ETORAL ATTILIATION.	· · · · · · · · · · · · · · · · · · ·			
ALTERED/MOVED NOTES:	Original site	Horse st	alls have been removed. Ro	oof has been covered			
with painted steel roofing.	Original Site: 1	10130 31	and have been removed. The	or mas been devered			
with painted Steel rooming.							
INTERIOR NOTES: _Has two	rows of 6x6 post	ts with 6	x6 for a beam. 2x10 floor joi	ists. 2x6 stud wall with	1		
1x8 shiplap divides East 14' f	rom the rest of th	ne barn.	This area still has four milk	stanchions on the			
North wall and four on the So SW corner. Metal cupola.	uth wall. Granar	y still in	the NE corner of main barn.	Tack room still in the			
OTHER NOTES: 2x6 stud w	alls, with sheathi	ng and 1	∕₂"x6" cedar lap siding. Raft	ers are 2x6's with			
sheathing and cedar shingles	and steel roofin	g. Two	6x6 posts support hip on eac	ch side in hayloft.			
Posts are 14' - 12' - 14' O.C.	There is a 6x6 ra	after beh	ind each post. Two 2x8's bi	race the bottom of each	h		
6x6 rafter down to the bottom light on first floor and 8"x10" ventilation.							
*PHYSICAL NOTES: Barn is	s very good cond	lition. H	as been well maintained.				
*LITM ZONE.			*DESTRICTED: V	or N			
*UTM ZONE:				OI IN			
*UTM EASTING:							
*UTM NORTHING:							



SKETCH MAP







PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 30, 2012 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 30, 2012 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 30, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 30, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 30, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, East 14', looking North, four milk



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 30, 2012

ROLL NUMBER: PHOTO NUMBER:

6

First floor, looking West, posts, beam and tack CAMERA DIRECTION: room in SW corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 30, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking East, posts, beam and granary in NE corner of main

CAMERA DIRECTION: barn



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 30, 2012 **ROLL NUMBER:**

PHOTO NUMBER:

Hayloft, looking East,

6x6 posts and 6x6 beam CAMERA DIRECTION: supporting hip of roof






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 30, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: 10' Granary in hayloft

Hayloft, looking SW, 10'x





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 30, 2012


ROLL NUMBER: PHOTO NUMBER:

10

Hayloft, looking East, 6x6 rafter behind 6x6 posts and two 2x8 braces from bottom of rafter down to bottom of post and down to floor

CAMERA DIRECTION: joists





© Farm & Home Publishers, Ltd.

21

CLAY CO., SE



HISTORY

This farm located in the SW ¼ of Section 12, Garfield Township, Clay County was homesteaded by Andrew Lundberg.

The 1894, 1901 and 1912 Clay County Atlas lists Andrew Lundberg as the owner.

The 1894, 1901 and 1912 Clay County Atlas lists Andrew Lundberg as the owner.

The 1924 Clay County Atlas lists Security State Bank Beresford as the owner.

The 1937 Clay County Atlas lists J. E. Frick as the owner.

The 1948 Clay County Atlas lists K. Joseph Frick as the owner.