

#### SITE INFORMATION


*SURVEY DATE: Octob	*ADDRESS:	SS: 469o4 307th Street						
*SURVEYOR: _Jim S	Stone	*COUNTY: Clay						
		 *CITY:	Beresford					
LOCATION DESCRIPTION: Fi	rom Vermillion, Sout	h Dakota Highway	/ 50, East	2 mile	s to	Gree	nfield	d Road,
turn left (North) 10-1/2 miles to	· · · · · · · · · · · · · · · · · · ·							
Street.	, <u> </u>	,						
LEGAL DESCRIPTION: W ½,	SW ½, 24 – 94 – 51	Garfield Twp.						
	,	•						
*QUARTER 1:SW 1/4	OWNER NAME:	Roger L. & Sharon L. Jensen						
*QUARTER 2:	VNER ADDRESS:	46958 307 <sup>th</sup> Street						
*TOWNSHIP: <u>Garfield</u>		OWNER CITY: Beresford						
*RANGE:51		OWNER STATE: South Dakota						
*SECTION:24		OWNER ZIP: 57004						
ACRES: <u>160</u>		QUAD NAME:						
OWNER CODE 1: P								
OWNER CODE 2:								
OWNER CODE 3:								
HISTORIC SIGNIFICANCE								
HISTORIC SIGNIFICANCE								
*DOE:								
*DOE DATE:	MULTIPLE PR	OPERTY	NAME	: <u> </u>				
REASON INELIGIBLE:								
		CATEGORY:						
NOMINATION STATUS:								
		SIGNII	FICANCE	LEVE	L 2:	N	S	L
REFERENCE NUMBER:								
HISTORIC DISTRICT RATING:			RIA 1:					
PERIOD:			RIA 2:					
			RIA 3:					
		CRITE	RIA 4:	A B	С	D		
SIGNIFICANCE NOTES:								

#### STRUCTURE DETAILS




SHPO ID:					
*PROPERTY NAME:					
OTHER NAME:					
CURRENT FUNCTION:	Horse barn	FOUNDATION:	Native rock with sand and lime mortar		
oomen ononom	110100 54111	i companioni	Steel roofing over		
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	cedar shingles		
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable		
HISTORIC SUBFUNCTION:	UBFUNCTION: <u>Hay and grain storage</u> STRUCTURA		Balloon framing		
		STYLE:	Gable roof barn		
OCCUPIED:	Yes	TYPE:	Livestock barn		
ACCESSIBLE:	Yes with permission	WALLS:	2x6 studs with sheathing and 1x6 #106 drop siding.		
CTODICO.	2	CONTENT DEDOOM:	I I avantus -		
STORIES: *DATE OF CONSTRUCTION:		SIGNIFICANT PERSON:L. LTURAL AFFILIATION:	J. Lorentzen  Danish		
DATE OF CONSTRUCTION.	1000 10 1090	LIURAL AFFILIATION.	DailiSii		
re-mortared with Portland cer		oncrete blocks) 8 feet high. F	oundation has been		
	4x4 beams in the North	vith 4x6 for beams in south enend of the main barn. Any evi			
		x6 #106 drop siding. Floor jois	oto ara 2v0'a Baftara		
		e walls in the hayloft to hold the			
		e wans in the haylort to hold the k8's, 4x4's, 4x6's, 6x6's, wall s			
sheathing is rough sawn cott			neathing and root		
		e of the doors and windows ne	ed repair. Native		
rock foundation needs some		iiio aooio alia willaows lic	on repair rative		
	The second secon				
*IITM 70NE:		*RESTRICTED: Y o	or N		
		NLSINICIED. I (	/i 1 <b>4</b>		
*UTM EASTING:					







#### SKETCH MAP



SOUTH ELEVATION





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 19, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: October 19, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 19, 2012 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 19, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 19, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, center of barn, looking North, milk

CAMERA DIRECTION: cow stalls



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October19, 2012 Jim Stone

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, center of

barn, looking North, CAMERA DIRECTION: where horse stalls were.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 19, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, South end of East lean-to, hay feed

CAMERA DIRECTION: rack



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 19, 2012

**ROLL NUMBER:** PHOTO NUMBER:

8

First floor, North end of East lean-to, note sheathing lower diagonal

CAMERA DIRECTION: upper horizontal





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 19, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft from West addition, looking in to

CAMERA DIRECTION: main hayloft.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 19, 2012


**ROLL NUMBER: PHOTO NUMBER:** 

10

Hayloft, looking NE, rafters, North gable end and one of the 3/4" steel

CAMERA DIRECTION: \_tie rods







#### **HISTORY**

This farm located in the W ½ of the SW ¼ in Section 24, Garfield Township, Clay County was homesteaded by Lorenz J. Lorenzen.

The 1894 and 1901 Clay County Atlas lists Lorenz J. Lorenzen as the owner.

The 1912 and 1924 Clay County Atlas lists Jens N. Jessen as the owner.

The 1937 Clay County Atlas lists A. G. Jensen as the owner and J. W. Jensen as the operator (renter).

The 1948 and 1956 Clay County Atlas lists N. H. Jensen as the owner.

Land was homesteaded by L. J. Lorentzen. He was listed as the owner in the 1901 Clay County Atlas. L. J. Lorentzen built the barn and some of the out buildings that still stand today.

Jens N. Jessen was listed as the owner of this farm in the 1912 Clay County Atlas.

