

#### SITE INFORMATION

*SURVEY DA	ATE: Octol	*ADDRESS	S: 46824 Burbank Road									
*SURVEY	*COUNTY	: Clay	Clay									
				*CITY	: Burb	ank						
LOCATION DESCR	PTION: F	rom int	ersection of	Main Street and I	Dakota S	tree	t in V	erm/	illion	. Soı	uth	
LOCATION DESCRIPTION: <u>From intersection of Main Street and Dakota Street in Vermillion, South</u> About ¼ mile to Burbank Road, turn left (East), fallow This road about 5 miles, turn Left (North) at												
address 46824 Bur	bank Road,	long dr	ive way.									
LEGAL DESCRIPTION	ON: <u>NE 1/4</u>	, SW ¼,	26 – 92 – 51	Fairview Twp.								
*QUARTER 1:	SW 1/4			OWNER NAME: Kevin L. & Laury J. Cusick								
*QUARTER 2:	011 1/4		OW		: 46824 Burbank road							
*TOWNSHIP:	Fairview			OWNER CITY:	Rurbank							
*RANGE:	51			OWNER STATE:	South Dakota							
*SECTION:	26				57010							
ACRES:	40.05			QUAD NAME:								
OWNER CODE 1:	P			QUAD NAME.	-							
OWNER CODE 2:	•											
OWNER CODE 3:												
OWNER CODE 3.												
HISTORIC SIGN	<u>IFICANCE</u>											
*DOE:				REGISTER NAME:								
*DOE DATE:					ROPERT	Y N	AME:	:				
REASON INELIGIBLE:												
				CATEGORY:								
NOMINATIO		SIGNIFICANCE LEVEL 1: N S L										
DATE LISTED:					IFICANO	E LE	EVEL	2:	N	S	L	
REFERENCE	NUMBER:											
HISTORIC DISTRIC	T RATING:	C or	NC	CRIT	ERIA 1:	Α	В	С	D			
	PERIOD:			CRIT	ERIA 2:	Α	В	С	D			
					ERIA 3:	Α	В	С	D			
				CRIT	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NO.	TEQ.											
SIGNIFICANCE NO	I LJ.											


### STRUCTURE DETAILS

<sup>\* =</sup> REQUIRED FIELD



SHPO ID:		_									
*PROPERTY NAME:											
OTHER NAME:											
CURRENT FUNCTION:	Shop	FOUNDATION:	Poured concrete foundation								
GONNENT FORGITON.	Chiop		Steel roofing over								
CURRENT SUBFUNCTION:	Storage	_ ROOF MATERIAL:									
HISTORIC FUNCTION:	Livestock barn	_ ROOF SHAPE:	Gambrel								
HISTORIC SUBFUNCTION:	Hay storage	_ STRUCTURAL SYSTEM:	Balloon framing								
		STYLE:	Gambrel roof barn								
OCCUPIED:	OCCUPIED: Yes TYPE										
ACCESSIBLE:	Yes with permission	WALLS:	2x6 stud with 1x6 #106 drop siding and steel roofing								
STORIES:	2	SIGNIFICANT PERSON:	Lee Cusick								
*DATE OF CONSTRUCTION:	? CI	JLTURAL AFFILIATION:	?								
ALTERED/MOVED NOTES:  Kevin Cusick. Barn was on t		e Burbank to this site. Lee Cus y evidence of milk cow stanchi									
is gone. Roof and walls have	been covered with stee	l roofing. 10' x 10' room built ir	the NW corner.								
This room is insulated and walls covered. A steel residential door installed into this room from exterior.											
	row of 6x6 posts 9' O.C	. with 6x6 for beam in the cente	r of the barn. 2x8								
floor joists.											
		siding and steel roofing. Rafter									
shingles and steel roofing. Windows are 9"x12" four light. New concrete floor under barn.											
*PHYSICAL NOTES: Barn is	s in very good condition										
		*RESTRICTED: Y o	or N								
*UTM EASTING:											
*UTM NORTHING:											









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 24, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 24, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking SW, NE corner






PHOTOGRAPHER: Jim Stone ROLL NUMBER: 3

DATE OF PHOTO: October 24, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SE, NW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: PHOTO NUMBER: 4

First floor, looking CAMERA DIRECTION: South, posts and beam





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 24, 2012

**ROLL NUMBER:** PHOTO NUMBER:

5 First floor, looking NE, CAMERA DIRECTION: sliding door on East wall.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 24, 2012


**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking North,

CAMERA DIRECTION: hip rafter

(2) 1x6 bracing on each






PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 24, 2012

**ROLL NUMBER:** PHOTO NUMBER:

Hayloft, looking South,

CAMERA DIRECTION: rafters and bracing







### **HISTORY**

This farm located in the NE ¼ of the SW ¼ of Section 26, Fairview Township, Clay County was homesteaded by Nelson W.Cusick.

The 1894 Clay County Atlas lists Nelson W. Cusick as the owner.

The 1901, 1912, 1924,1937 and 1948 Clay County Atlas lists Wallace L. Cusick as the owner.

The 1956 Clay County Atlas lists L. E. Cusick as the owner.

#### The Following Information was Furnished by

Kevin Cusick, the present owner.

Nelson William Cusick homesteaded this farm. Nelson William Cusick was born Sept 6, 1835 at Tioga, New York. He married Anna Louise (Ladieu) in 1874 at Vermillion, South Dakota. He died January 21, 1889 at Vermillion, South Dakota.

His son, Wallace L. Cusick operated this farm after his parents death and became the owner. Wallace L. Cusick was born October 11, 1875 at Burbank, South Dakota. He married Emma Orel Russell on October 14, 1897 at Sioux City, Iowa. He died Jan 12, 1954 at Vermillion, South Dakota.

His son, Lawrence Eugene Cusick operated this farm after his parents death and became the owner. Lawrence Eugene Cusick was born November 7, 1922 at Vermillion, South Dakota. He married Mary Lee Riehle October 1, 1943 at Vermillion, South Dakota. Lawrence died May 18, 1996 at Vermillion, South Dakota.

His son, Kevin farmed with his father and now is owner of this farm.





Picture of first barn on this farm, in center back by windmill,
It has two dormers. Picture taken in 1901.
This barn burned down shortly after this, but don't know the year.





This is the second barn on this farm. Built after the first barn burned down.

Red rock foundation is still visable. Barn was taken down in \_\_\_\_\_because the roof was falling in. Foundation measures 46 feet wide and 67 feet long.

Barn was built in 1909. Date of picture is unknown.

