

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



SITE INFORMATION

*SURVEY DATE: February 5, 2013

*SURVEYOR: Jim Stone

*ADDRESS: 46083 303rd Street

*COUNTY: Clay

*CITY: Centerville

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 15 miles to 302nd Street, turn left (West) 1 mile to 461st Ave., turn South 1 mile to 303rd street, turn right (West) about ¼ mile, on the left (South) side, vacated place.

LEGAL DESCRIPTION: Lots 1 & 2, NE ¼, 4 – 94 – 52 Pleasant Valley Twp.

*QUARTER 1: NE 1/4

*QUARTER 2: _____

*TOWNSHIP: Pleasant Valley

*RANGE: 52

*SECTION: 4

ACRES: 148.10

OWNER CODE 1: P

OWNER CODE 2: _____

OWNER CODE 3: _____

OWNER NAME: Loann Kjeldseth & Jane sommer

OWNER ADDRESS: 45141 300th

OWNER CITY: Irene

OWNER STATE: South Dakota

OWNER ZIP: 570037

QUAD NAME: _____

HISTORIC SIGNIFICANCE

*DOE: _____

*DOE DATE: _____

REASON INELIGIBLE: _____

REGISTER NAME: _____

MULTIPLE PROPERTY NAME: _____

NOMINATION STATUS: _____

DATE LISTED: _____

REFERENCE NUMBER: _____

HISTORIC DISTRICT RATING: C or NC

PERIOD: _____

CATEGORY: _____

SIGNIFICANCE LEVEL 1: N S L

SIGNIFICANCE LEVEL 2: N S L

CRITERIA 1: A B C D

CRITERIA 2: A B C D

CRITERIA 3: A B C D

CRITERIA 4: A B C D

SIGNIFICANCE NOTES: _____

STRUCTURE DETAILS

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



SHPO ID: _____

*PROPERTY NAME: _____

OTHER NAME: _____

CURRENT FUNCTION: Vacant

FOUNDATION: Poured concrete

CURRENT SUBFUNCTION: Storage

Steel roofing over

ROOF MATERIAL: cedar shingles

HISTORIC FUNCTION: Livestock barn

ROOF SHAPE: Gable

HISTORIC SUBFUNCTION: Hay and grain storage

STRUCTURAL SYSTEM: Post frame

Western Feeder

STYLE: barn

OCCUPIED: No

TYPE: Livestock barn

4x6 and 6x6 posts,

with 2x6 girts 4' O.

C. and 12" vertical

board siding

ACCESSIBLE: ?

WALLS: _____

STORIES: 1

SIGNIFICANT PERSON: _____

*DATE OF CONSTRUCTION: Early 1900's

CULTURAL AFFILIATION: ?

ALTERED/MOVED NOTES: Original site. Steel roofing has been applied on the roof.

INTERIOR NOTES: Has two rows of 6x6 posts 20' high on each side of the center 24', with (2) 2x6's for
a beam to support the center of the rafters. Three double horse stalls and 7 milk cow stanchions are
still in place on the North side. Two 9'x6' granaries are still in place along center of the West wall.

OTHER NOTES: 4x6 and 6x6 posts with 2x6 girts, 4' O. C. and 1x12 vertical siding on exterior walls.
Windows are 10"x12" four light. Rafters are 2x6, 32" O. C. There is a feed bunk and a hay feed rack
above it along the North wall in the South area. The center area 24' wide by 50' long and is a hayloft
from the ground to the peak. It is 31' from the ground to the peak.

*PHYSICAL NOTES: Barn is in fair condition. Needs repairs on doors and windows. Some of the
battens are missing on the siding.

*UTM ZONE: _____

*RESTRICTED: Y or N

*UTM EASTING: _____

*UTM NORTHING: _____

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 5

CAMERA DIRECTION: First floor, South side,
looking NE, Feed bunk
and hay feed rack above

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 6

CAMERA DIRECTION: First floor, North side,
looking NE, seven milk
cow stanchions

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 7

CAMERA DIRECTION: First floor, center area,
looking SE, hay feed
rack and 6x6 posts 20'
high with bracing

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 5, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 8

CAMERA DIRECTION: First floor, looking SE,
6x6 post 20' high, (2)
2x6's for a beam to
support rafters and
bracing

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE

HISTORIC SITES SURVEY STRUCTURE FORM

