

<b>""SITE INFORMATION</b>								
*SURVEY DATE: March 10,	2014 *ADDRESS:	46116 Riverside Street						
*SURVEYOR: Jim Ston	<del></del>	Clay						
	*CITY:	Centerville						
LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 15-1/2 miles to Riverside Street, turn left (West) about 7/8 mile, on the right (North) side.								
LEGAL DESCRIPTION: W ½, NW ¼, E	exc 1.48 A, 27 –95 – 52 Rivers	side Twp.						
*QUARTER 1: <u>NW 1/4</u>	OWNER NAME:	Steven & Robin Hansen						
*QUARTER 2:	OWNER ADDRESS:	46140 Riverside Street						
*TOWNSHIP: Riverside	OWNER CITY:	Centerville						
*RANGE: <u>52</u>	OWNER STATE:	South Dakota						
*SECTION:27	OWNER ZIP:	57014						
ACRES: 78.01	QUAD NAME:							
OWNER CODE 1: P								
OWNER CODE 2:								
OWNER CODE 3:								
HISTORIC SIGNIFICANCE								
*DOE:	REGISTER NA	REGISTER NAME:						
*DOE DATE:		MULTIPLE PROPERTY NAME:						
REASON INELIGIBLE:								
		CATEGORY:						
NOMINATION STATUS:	SIGNIF	SIGNIFICANCE LEVEL 1: N S L						
DATE LISTED:	SIGNIF	FICANCE LEVEL 2: N S L						
REFERENCE NUMBER:								
HISTORIC DISTRICT RATING: C or	NC CRITE	RIA1: A B C D						
PERIOD:		RIA 2: A B C D						
		RIA 3: A B C D						
	CRITE	RIA 4: A B C D						
SIGNIFICANCE NOTES:								


#### STRUCTURE DETAILS



SHPO ID:								
*PROPERTY NAME:								
OTHER NAME:								
<b>CURRENT FUNCTION:</b>	FUNCTION: Vacant		FOUNDATION:		Native stone			
					Steel roofing over			
CURRENT SUBFUNCTION:	Vacant		ROOF MATERIAL:					
HISTORIC FUNCTION:	Livestock barn		ROOF SHAPE:					
HISTORIC SUBFUNCTION:	Hay and grain storage		STRUCTURAL SYSTEM:		Balloon framing			
					STYLE:	Gable roof barn		
OCCUPIED:	No				TYPE:	Livestock barn		
400F00IDLF-	Yes with		WALLO:			2x4 studs, 1x8 # 106		
ACCESSIBLE:	permission		WALLS:			drop siding		
OTODIEO	•	01		DEDOOL				
STORIES:		_	GNIFICANT			usia Anderson		
*DATE OF CONSTRUCTION:	1890 to 1910	CUL	TURAL AFF	ILIATION	i:	Swedish		
ALTERED/MOVED NOTES: Original site. 14' x 32' lean-to added on the East side. Foundation is								
native stone. It has been repaired with poured concrete in places. I can not see any mortar in the								
original foundation. Steel roofing has been applied on the roof over cedar shingles.								
INTERIOR NOTES. Two years		la OvC m	sata dud ba		Ove flaar	iniate for the boulet		
INTERIOR NOTES: Two rows of spaced double 2x6 posts, 4x4 beams and 2x6 floor joists for the hayloft								
floor. 6' x 8' granary and a 4' x 8' tack room are still in the SE corner. Most of the single horse stalls are								
still in place in the original barn and in the East lean-to.								
OTHER NOTES: 2X4 stud walls with 1x8 #106 drop siding on all four exterior walls and the East wall of								
the original barn. The 8" drop siding on the East wall of the original barn is almost new. Windows are 10" x 12" four light. Rafters are 2x4's with 2x4 horizontal bracing 4' O. C. The 2x4 studs, 2x4 rafters,								
2x4 bracing, 2x6 floor joists. 2x6 posts and 4x4 beams are all rough sawn cottonwood.								
2, 1 1 1 , 1 1 -								
*PHYSICAL								
	n poor condition.		*RE	STRICTE	D: Y o	r N		
*UTM EASTING:								
*UTM NORTHING:								



#### SKETCH MAP







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 10, 2014 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: March 10, 2014 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 10, 2014

**ROLL NUMBER: PHOTO NUMBER:** CAMERA DIRECTION:

Looking SW, NE corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 10, 2014 **ROLL NUMBER:** 

**PHOTO NUMBER:** CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 10, 2014

**ROLL NUMBER:** PHOTO NUMBER:

First floor, East lean-to, looking NW, single horse

CAMERA DIRECTION: stalls still in place.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 10, 2014

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, original barn, looking NW, double 2x6 posts, 4x4 beam and 2x6 floor joists and single horse stalls on West

CAMERA DIRECTION: wall.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 10, 2014

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, original barn, looking NE, replaced round posts, 4x4 beam

CAMERA DIRECTION: and 2x6 floor joists.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 10, 2014

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking NW, 2x4 rafters and 2x4 bracing

CAMERA DIRECTION: 4' O.C.






PHOTOGRAPHER: \_\_\_\_ DATE OF PHOTO: Jim Stone March 10, 2014 ROLL NUMBER: PHOTO NUMBER:

9

Hayloft, looking SE, 2x4 rafters, 2x4 bracing and

CAMERA DIRECTION: South gable wall





Farm & Home Publishers, Ltd. 35 CLAY CO., SD



#### **HISTORY**

This farm located in the W ½, NW ¼ of Section 27, Riverside Township, Clay County was homesteaded by John E. Shoberg or John E. Sjoberg.

The 1894, 1901 and 1912 Clay County Atlas lists Louisa Anderson (Mrs. J. G. Anderson) as the owner.

The 1924, 1937, 1948 and 1956 Clay County Atlas lists Oscar R. Holmquist as the owner.

Lovisa (Lousia) Regina (Shoberg) Anderson was the daughter of John E. Shoberg or (Sjoberg). Names were changed to be more Americanized. Lousia Anderson married John G. Anderson who was born Nov.12, 1841 and died July 11, 1928. They lived on the original John E. Shoberg homestead and raised 10 children there. Lousia (Shoberg) Anderson must have inherited the farm from her parents, as it was listed with her as the owner in the 1894, 1901 and 1912 Clay County Atlas. Their children were; J. Alfred Anderson, Gustaf A. Anderson, born Sept 20, 1872, Emma Otelie Anderson, born Mar. 1, 1874, Alma E. Anderson, born in 1879, Anna Margreta Anderson, born Sept. 19, 1881, Herman T. Anderson, born July 14, 1885, Lallie R. Anderson, born July 28, 1886, married Oscar Holmquist, and they became the owners of this farm, Mamie T. Anderson, was born Nov. 7, 1887. This is only eight children, two may have died at birth.

John Gustaf Anderson was known as (John G. Anderson) and was the oldest brother. His brothers were; Fritz, August, Anders Gustaf Anderson (the fifth brother), born Sept. 1853, Alfred Anderson, born about 1854. Sisters were; Brita Anderson, born about 1850 and Anna Anderson, born in 1852.