

"SITE INFORMATION									
*SURVEY DATE:June 5, 2	2013 *ADDRESS:	29765 458 th Ave.							
*SURVEYOR:Jim Ston	e *COUNTY:	Clay							
	*CITY:	Centerville							
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and									
South Dakota Highway 19, North18 miles to 299th Street, turn left, (West) about 4 miles to 458th Ave., turn									
right (North) 1- 1/4 miles, on the left (West) side.									
LEGAL DESCRIPTION: N ½, SE ¼, 1–95 – 53 Star Twp.									
*QUARTER 1: SE 1/4	OWNER NAME:	David L. Ostrem							
*QUARTER 2:	OWNER ADDRESS:								
*TOWNSHIP: Star	OWNER CITY:								
*RANGE: 53	OWNER STATE:	South Dakota							
*SECTION: 1	OWNER ZIP:	57014							
ACRES: 78.23	QUAD NAME:								
OWNER CODE 1: P									
OWNER CODE 2:									
OWNER CODE 3:									
HISTORIC SIGNIFICANCE									
*DOE: REGISTER NAME:									
*DOE: REGISTER NAME: *DOE DATE: MULTIPLE PROPERTY NAME:									
REASON INELIGIBLE:									
		CATEGORY:							
NOMINATION STATUS:	SIGNI	FICANCE LEVEL 1:	N	S	L				
DATE LISTED:		FICANCE LEVEL 2:	N	S	L				
REFERENCE NUMBER:									
HISTORIC DISTRICT RATING: C or	NC CRITE	RIA1: A B C	D						
PERIOD:	CRITE	RIA 2: A B C	D						
		RIA 3: A B C	D						
	CRITE	RIA 4: A B C	D						
SIGNIFICANCE NOTES:									

STRUCTURE DETAILS




SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Shop	FOUNDATI	ON:	Poured concrete Steel over cedar			
CURRENT SUBFUNCTION:	Machinery storage	ROOF MATERIAL:					
	Livestock barn	ROOF SHA					
HISTORIC SUBFUNCTION:				Balloon framing			
moronio dobi onorion.	Thay storage			Gambrel roof barn			
OCCUPIED:	Yes		PE:	Livestock barn			
33331 ILD.	103		·	2x6 studs, 1x6 #106			
				drop siding,			
ACCESSIBLE.	Yes with permission	WALLS:		horizontal steel			
ACCESSIBLE:	permission	WALLS.		roofing			
STORIES:	2	SIGNIFICANT PERSON:		Mads Jensen			
*DATE OF CONSTRUCTION:		CULTURAL AFFILIATION:		?			
DATE OF CONSTRUCTION.	<u> </u>	COLTORAL AFFILIATION.		r			
ALTERED/MOVED NOTES:	Original site All ev	idence of horse stalls and or n	nilk c	ow stanchions has			
ALTERED/MOVED NOTES: Original site. All evidence of horse stalls and or milk cow stanchions has been removed. Lower 8'-6" cut off the barn and barn was lowered down onto a new concrete floor.							
Hayloft floor removed at that time. Steel roofing has been installed over cedar shingles on the roof.							
16' x 13'- 6" overhead door installed in the East wall. Walls and ceiling are insulated and lined with steel							
roofing.							
INTERIOR NOTES: Owner described original floor plan, did not remember any actual measurements.							
See floor plan for about what the floor plan would have been. 4x4posts 10' O. C. supporting the hip are							
still in place.							
OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding on all four walls. $\frac{1}{2}$ " x 6" cedar lap siding was							
applied over the drop siding. The cedar siding was removed when the horizontal steel was applied on the							
walls. Rafters are 2x6's on the main barn. With ceiling lined, any rafter bracing is not visable.							
Steel roofing over ceder shingles							
*PHYSICAL NOTES: Barn is in very good condition.							
THOUGHE HOTES. Daile	Jili very good condi	uvii.					
*UTM ZONE:			Υo	r N			
*UTM EASTING:							
*UTM NORTHING:							



SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE HISTORIC SITES SURVEY STRUCTURE FORM

SKETCH MAP







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 5, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 5, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 5, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 5, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

5

First floor, looking NW, 4x6 posts supporting hip, note wall and

CAMERA DIRECTION: ceiling liner



PHOTOGRAPHER:


Jim Stone DATE OF PHOTO: June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SE, overhead door on East

CAMERA DIRECTION: wall.





P Farm & Home Publishers, Ltd. 39 CLAY CO., SD



HISTORY

This farm located in the SE ¼ of Section 1, Star Township, Clay County was homesteaded by Mads Jensen.

The 1894, 1901 and 1912 Clay County Atlas lists Mads Jensen as the owner.

The 1924 Clay County Atlas lists Carl Jensen as the owner.

The 1937 and 1948 Clay County Atlas lists T. O. Ostrem as the owner.

The 1956 Clay county Atlas lists Boyd Ostrem as the owner.