


"SITE INFORMATION												
*SURVEY DATE:	r 20, 2013	*ADDRESS:	*ADDRESS: 31305 465 th Ave									
*SURVEYOR:	Jim Stone	· · · · · · · · · · · · · · · · · · ·	*COUNTY:	-								
			*CITY:	Vermi	llion							
LOCATION DESCRIPTION: From Vermillion, from intersection of South Dakota Highway 50 bi-pass and												
University Road, (North) about 5 miles to intersection of University Road, 313th Street (East) and 465th Ave												
(South), turn right (South) about 200 yards, on the right (West) side.)												
LEGAL DESCRIPTION: Tract 2 Buck's Addn, NE ¼, Exc Lots 1 & 2, 30 – 93 – 51 Prairie Center Twp.												
LEGAL DESCRIPTION.	ITACL Z DUCK	S Addii, NE 74	, EXCLUIS I & Z	, 30 – 93	- 5	I FIC	allie	Cei	ilei i	wp.		
*QUARTER 1: NE 1	OWNER NAME: Hemminger Family Trust											
*QUARTER 2:		OWNER ADDRESS: 106 W. Main Street										
	Center		OWNER CITY:			Beresford						
*RANGE: 51	1	0	OWNER STATE: South Dakota									
*SECTION: 30	0		OWNER ZIP:	57004								
ACRES:19.	.43		QUAD NAME:									
OWNER CODE 1: P												
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNIFICANCE												
*DOE:			REGISTER NAME: MULTIPLE PROPERTY NAME:									
*DOE DATE:			MULTIPLE PR	OPERI	' NA	WE:						
REASON INELIGIBLE:												
				C	^TE	GOR	٧.					
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L									
DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L									
REFERENCE NUMBI			0.0.1	. 107 101				••		_		
HISTORIC DISTRICT RATIN			CRITE	ERIA 1:	Α	В	С	D				
			_	RIA 2:			_					
				ERIA 3:								
				RIA 4:								
SIGNIFICANCE NOTES:												


STRUCTURE DETAILS



SHPO ID:		_							
*PROPERTY NAME:									
OTHER NAME:									
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete						
CURRENT CURRUNCTION	Otamana	DOOF MATERIAL.	Steel roofing over						
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel roof						
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Gambrel roof barn						
OCCUPIED:	No Variable (4)	TYPE:	Livestock barn						
ACCESSIBLE:	Yes with permission	WALLS:	2x6 studs, 1x6 #106 drop siding						
ACCESSIBLE.	permission	WALLS.	urop siding						
STORIES:	2 5	SIGNIFICANT PERSON: Ma	ary L. Lukes						
*DATE OF CONSTRUCTION:		LTURAL AFFILIATION:	ary L. Lukes						
DATE OF CONSTRUCTION.	Larry 1900 S CO	ETORAL ATTILIATION.							
ALTERED/MOVED NOTES:	Original site West 12'	v 40' loan-to has boon added lat	tor The 25' v 40						
ALTERED/MOVED NOTES: Original site. West 12' x 40' lean-to has been added later. The 25' x 40 pole barn lean-to has been added recently. Roof has been covered with steel roofing over cedar shingles.									
A 4' wide stairway has been added at the North end to access the hayloft. North 11' of posts and beam Has been moved West 4' to allow room for added stairway.									
has been moved west 4 to a	now room for added Stan	way.							
INTERIOR NOTES: The cen	ter barn is the original ba	rn and any evidence of horse s	stalls or milk cow						
stanchions has been remove	d. One row of 4x4 posts	with a 4x6 beam supports 2x8 t	loor joists for the						
hayloft floor.									
OTHER NOTES: 2x6 stud w	alls with 1x6 # 106 drop s	siding on the original center bar	rn and the West 12' x						
40' lean-to. Rafters are 2x6's	with a 1x6 brace at the r	oof hip. 2x6 bracing from the to	op of the wall down to						
		evidence of a cupola. West add							
the original barn with 2x6 raft	ers. The East addition h	as 6x6 posts 7' O. C. with a 2x1	2 skirt board and 2x4						
		O. C. with 2x4 purlins 2' O. C.	The roof and walls						
are covered with steel roofing	<u>j.</u>								
*PHYSICAL NOTES: Barn is i	in fair condition.	*RESTRICTED: Y o	r N						
*UTM EASTING:	ii iaii oonalaani								
*UTM NORTHING:									
OTIVI NORTHING.									










SKETCH MAP



PHOTOGR





PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: November 20, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 20, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 20, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



Jim Stone November 20, 2013 ROLL NUMBER:
PHOTO NUMBER:
CAMERA DIRECTION:
Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 20, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, 4x4 posts, 4x6 beam and

CAMERA DIRECTION: 2x8 floor joists.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: November 20, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SE, 2x6 rafters with 1x6 brace at

CAMERA DIRECTION: hip.





PHOTOGRAPHER: **DATE OF PHOTO:**

Jim Stone November 20, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SE, 2x6 rafters, 2x6 stud wall in hayloft, 2x6 bracing from top of the wall down to hayloft floor, 4' O. C.

CAMERA DIRECTION:



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone November 20, 2013

ROLL NUMBER: PHOTO NUMBER:

East lean-to, looking North and up, mfg. truss rafters with 2x8 top chord and 2x6 bottom chord, with 2x4 purlins,

CAMERA DIRECTION: and steel roofing.





© Farm & Home Publishers, Ltd.

33

CLAY CO., SD



History

This farm located in the NE ¼ of Section 30, Prairie Center Township, Clay County was homesteaded by Isaac McCumber.

The 1894 Clay County Atlas lists Mary L. Lukes as the owner.

The 1901 and 1924 Clay County Atlas lists Mary L. Lukes & S. H. Parks as the owners.

The 1924 Clay County Atlas lists Albert Amundson as the owner.

The 1937 Clay County Atlas lists C. E. Paulson as the owner.

The 1948 Clay County Atlas lists D. E. Nelson as the owner.

The 1956 Clay County Atlas lists C. H. Peterson as the owner.