


""SITE INFORMATION				
*SURVEY DATE: June 26, 2013	*ADDRESS: 45450 299th Street			
*SURVEYOR: Jim Stone	*COUNTY: Clay			
-	*CITY: Irene			
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and				
South Dakota Highway 19, North 15 miles to 302 <sup>nd</sup> Street, turn left (West) about 7 miles, turn right (North)				
3 miles to 299th Street, turn left (West) about ¼ mile on the right (North) side.				
LEGAL DESCRIPTION: SE ¼, 9 – 95 – 53 Star Twp.				
*QUARTER 1: SE 1/4	OWNER NAME: Charles T. & Suzanne Stockland			
	NER ADDRESS: 45327 299th Street			
*TOWNSHIP: Star	OWNER CITY: Irene			
*RANGE: 53	OWNER STATE: South Dakota			
*SECTION: 9	OWNER ZIP: 57037			
ACRES: 163.89	QUAD NAME:			
OWNER CODE 1: P				
OWNER CODE 2:				
OWNER CODE 3:				
HISTORIC SIGNIFICANCE				
*DOE:	REGISTER NAME:			
*DOE DATE:	MULTIPLE PROPERTY NAME:			
REASON INELIGIBLE:				
MEAGON INCLIGIBLE.				
_	CATEGORY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L			
REFERENCE NUMBER:				
HISTORIC DISTRICT RATING: C or NC	CRITERIA 1: A B C D			
PERIOD:	CRITERIA 2: A B C D			
	CRITERIA 3: A B C D			
	CRITERIA 4: A B C D			
	····			
SIGNIFICANCE NOTES:				


#### STRUCTURE DETAILS



SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
CURRENT FUNCTION:	Calving barn	FOUNDATION:	Poured concrete	
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Cedar shingles	
HISTORIC FUNCTION:	Horse barn	ROOF SHAPE:	Gambrel roof	
HISTORIC SUBFUNCTION:	Hay and grain	storage STRUCTURAL SYSTEM:	Balloon framing	
		STYLE:	Gambrel roof barn	
OCCUPIED:	Yes	TYPE:	Horse barn	
			2x6 studs, sheathing	
ACCESSIBLE:	Yes with permission	WALLS:	& ½"x6" cedar lap siding	
AGGEGGIBEE.	permission	WALLO.	Sidilig	
STORIES:	2	SIGNIFICANT PERSON:	Media Babb	
*DATE OF CONSTRUCTION:	19-teens	CULTURAL AFFILIATION:	?	
ALTERED/MOVED NOTES: Original site. Most evidence of horse stalls has been removed.				
INTERIOR NOTES. Two same of SuS mosts and SuS have seen at the SuS Salate San the Land SuS				
INTERIOR NOTES: Two rows of 6x6 posts, and 6x6 beam support the 2x8 joists for the hayloft floor.				
9' x 12' granary are still in the NE corner. 10' x 12' granary still in place in the NE corner of the hayloft.				
OTHER NOTES. 2v6 stud wells shoothing and 1/2v62 saday languiding. Chaothing is having the languiding				
OTHER NOTES: 2x6 stud walls, sheathing and ½"x6" cedar lap siding. Sheathing is horizontal on three				
walls, but diagonal on the North gable end wall. Rafters are 2x6's with a 2x6 brace supporting the hip 4' O.				
C. (2) 1x6 braces on each hip, 2' O. C. Windows are 8" x 10" four light on the first floor and 8"x 10" four				
light over 8"x 10" four light in the hayloft. Very ornate cupola from the 19-teens.				
*PHYSICAL NOTES: Barn is in fair condition. Needs new roof.				
*UTM ZONE:		*RESTRICTED: Y o	r N	
*UTM EASTING:				
*UTM NORTHING:				











PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: June 26, 2013 PHOTO NUMBER:

CAMERA DIRECTION: June 26, 2013

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 26, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

**ROLL NUMBER:** PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

June 26, 2013

**ROLL NUMBER:** 

PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

ROLL NUMBER: **PHOTO NUMBER:** 

First floor, looking NE, 6x6 posts, 6x6 beam, 2x8 joists, note 9' x 12'

CAMERA DIRECTION: granary in NE corner



PHOTOGRAPHER: Jim Stone

DATE OF PHOTO: June 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NW, 6x6 posts, 6x6 beam and

CAMERA DIRECTION: 2x8 floor joists.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking NE, 12' x 9' granary in hayloft, CAMERA DIRECTION: note roof over granary.

PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013 **ROLL NUMBER:** 

**PHOTO NUMBER:** 

Hayloft, looking NW, 2x6 brace supporting hip, 4'

CAMERA DIRECTION: O. C.





PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

June 26, 2013


**ROLL NUMBER: PHOTO NUMBER:** 

9

Hayloft, looking NW, 2x6 brace supporting hip, 4' O. C. and (2) 1x6 bracing

CAMERA DIRECTION: on each hip.







#### **HISTORY**

This farm located in the SE ¼ of Section 9, Star Township, Clay County was homesteaded by Soloman Babb.

The 1894 Clay County Atlas lists H. R. and E. C. Babb as the owners.

The 1901 Clay county Atlas lists Elam C. Babb as the owner.

The 1912 Clay County atlas lists Media Babb as the owner.

The 1924 Clay County Atlas lists Elan C. Babb and John Kilbride as the owners.

The 1937 Clay County Atlas lists Henrietta R. Babb as the owner and C. Huth as the operator.

The 1948 and 1956 Clay County Atlas lists H. E. Babb as the owner.