


SITE INFORMATION

*SURVEY DATE: May 29	*ADDRESS: 45631 300th Street											
*SURVEYOR: Jim St	*COUNTY:	Clay										
		*CITY:	∕: Wakonda									
From the intersection of South Dakota Highway 50 bi-pass and South LOCATION DESCRIPTION: Dakota Dakota Highway 19, 15 miles North to 302 nd Street, turn left (West) 4 miles to 458 th Ave, turn right (North) 2												
miles to 300th Street, turn left (West) 1-3/4 miles on the left side.												
LEGAL DESCRIPTION: NW 1/4	23 – 95 – 53 Star T	wp										
*QUARTER 1: NW 1/4	QUARTER 1: NW 1/4 OWNER NAME:				Michael Huth							
*QUARTER 2:	VNER ADDRESS: 30417 455 th Ave.											
*TOWNSHIP: Star		OWNER CITY:										
*RANGE: 53		OWNER STATE:	South Dakota									
*SECTION: 23		OWNER ZIP: 570)73							
ACRES: <u>153.72</u>		QUAD NAME:										
OWNER CODE 1: P												
OWNER CODE 2: F S L	P											
OWNER CODE 3: F S L	Р											
HISTORIC SIGNIFICANCE												
*DOE:	REGISTER NAME:											
*DOE DATE:	MULTIPLE PROPERTY NAME:											
REASON INELIGIBLE:												
		CATEGORY:										
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L											
DATE LISTED: _		SIGNIFICANCE LEVEL 2: N S L										
REFERENCE NUMBER:												
HISTORIC DISTRICT RATING:	C or NC	CRITE	ERIA 1:	Α	В	С	D					
PERIOD: _			ERIA 2:									
			ERIA 3:									
		CRITE	ERIA 4:	Α	В	С	D					
SIGNIFICANCE NOTES:												



STRUCTURE DETAILS									
SHPO ID:									
*PROPERTY NAME:		•							
OTHER NAME:									
O THER TO MILE									
			Native rock						
CURRENT FUNCTION:	Vacant	FOUNDATION:	mortared						
CURRENT SUBFUNCTION:		ROOF MATERIAL:	Cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel						
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Gambrel roof barn						
OCCUPIED:	No	TYPE:	Livestock barn						
			2x6 & 2x10,						
400500IDI 5	Yes with	WALL 0	sheathing & ½" x						
ACCESSIBLE:	permission	WALLS:	6" cedar lap siding						
			•						
STORIES:		SIGNIFICANT PERSON:							
*DATE OF CONSTRUCTION:	<u>1915 to 1925</u> CU	LTURAL AFFILIATION:	?						
ALTERED/MOVED NOTES: Original site. Horse stalls and milk cow stanchions have been removed.									
INTERIOR NOTES. Contactive news Coloniate and Colonian Colonia Colonian Colonia Colonian Colonia Colonian Colonia Colo									
INTERIOR NOTES: Center two rows 6x6 posts and 6x8 beams. Outer two rows of 6x6 posts and 6x6									
beams in the North 28'. South 46' has four rows 6x6 posts and (4) 2x10's laminated for beams.									
2x6 wall with solid diagonal sheathing divides the North and South sections.									
OTHER NOTES: 2x6 stud walls 14' high with horizontal sheathing on the East and West sides. 2 x 10 stud walls with diagonal sheathing on the gable ends. Two rows 6x6 posts and 6x6 beams in the hayloft									
to support the hip of the roof. 6x6 rafter behind each post with (2) 2x10's bracing from the bottom of									
6x6 rafter down to bottom of 6x6 posts. Also a 2x6 brace from the bottom of the 6x6 rafter up to the top									
of the 6x6 post. 8"x10" four light windows over 8"x10" four light windows double hung for ventilation.									
*PHYSICAL NOTES: Metal cupola. Barn is in good condition. Doors on first floor need some repair									
and some windows need replacing. Cedar shingles on roof are in very good condition. ½ x6" cedar lap									
siding is in good condition, but should be painted.									
<u> </u>	<u>.</u>								









PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: March 7, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking SE, NW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 7, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking SW, NE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, 6x6 posts & (4) 2x10's

CAMERA DIRECTION: for beam



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, 2x6 wall, may have replaced 1 row of

CAMERA DIRECTION: posts and beam





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking

South, dividing wall &

CAMERA DIRECTION: curved manure track



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone

March 7, 2012

ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: _post and beam & granary

First floor, looking SE,





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking West, Feed alley, note stairs to

CAMERA DIRECTION: hayloft



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:

10

Hayloft, looking South, 6x6 post, 6x6 beam, 6x6

CAMERA DIRECTION: _rafter & bracing





PHOTOGRAPHER: _____ DATE OF PHOTO:

Jim Stone March 7, 2012

ROLL NUMBER: PHOTO NUMBER:


11 Hayloft, looking South, 2x10's bracing at bottom

of 6x6 post up to 6x6

CAMERA DIRECTION: rafter

* = REQUIRED FIELD





| STAR TOWNSHIP | SECTION 21 | 1. Hessman, Dougl | SECTION 32 | 1. Saner, Andrew 1 | SECTION 32 | 1. Saner, Andrew 1 | SECTION 33 | 1. Madsen, Martin | SECTION 35 | 1. Nelson, Heath 5 | SECTION 36 | 1. Wilking, Dillon 7 | SECTION 15 | 1. Davis, Gary 6

© Farm & Home Publishers. Ltd.

38

CI AV CO SD



HISTORY

This farm located in the NW 1/4 of Section 23, Star Township, Clay County was homesteaded by Benjamin Cusick.

The 1894, and 1901 Clay County Atlas lists Benjamin Cusick as the owner.

The 1912 Clay County Atlas lists B. S. Barton as the owner.

The 1924 Clay County Atlas lists G. F. Roach as the owner.

The 1937, 1948 and 1956 Clay County Atlas lists J. D. Fait as the owner.

