

""SITE INFORMATION				
*SURVEY DATE: June11, 2013	*ADDRESS: 45757 S D 46			
*SURVEYOR: Jim Stone	*COUNTY: Clay			
-	*CITY: Centerville			
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and				
South Dakota Highway 19, North 20 miles to South Dakota Highway 46, turn left (West) about 4 – 1/2 miles				
, on the left (South) side.				
LEGAL DESCRIPTION: N ½, NE ¼, 1–95 – 53 Star Twp.				
*QUARTER 1: NE 1/4	OWNER NAME: E. Dale & Betty Jo Johnson			
	NER ADDRESS: 45757 S D 46			
*TOWNSHIP: Star	OWNER CITY: Centerville			
	DWNER STATE: South Dakota			
*SECTION: 1	OWNER ZIP: 57014			
ACRES: 76.11	QUAD NAME:			
OWNER CODE 1: P				
OWNER CODE 2:				
OWNER CODE 3:				
HISTORIC SIGNIFICANCE				
HISTORIC SIGNII ICANCE				
*DOE:	REGISTER NAME:			
*DOE DATE:	MULTIPLE PROPERTY NAME:			
REASON INELIGIBLE:	-			
	CATEGORY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L			
REFERENCE NUMBER:				
HISTORIC DISTRICT RATING: C or NC	CRITERIA 1: A B C D			
PERIOD:	CRITERIA 2: A B C D			
	CRITERIA 3: A B C D			
	CRITERIA 4: A B C D			
SIGNIFICANCE NOTES:				


#### STRUCTURE DETAILS




SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete	
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Steel roofing over cedar shingles	
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel roof	
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing	
		STYLE:	Gambrel roof barn	
OCCUPIED:	Yes	TYPE:	Livestock barn	
	Yes with		2x6 studs, 1x6 #106	
ACCESSIBLE:	permission	WALLS:	drop siding	
STORIES:	2	SIGNIFICANT PERSON: N	like Kilbride barn	
*DATE OF CONSTRUCTION:		CULTURAL AFFILIATION:	?	
			·	
ALTERED/MOVED NOTES:	Original site. A	ny evidence milk cow stanchions has l	been removed.	
Steel roofing has been installed over cedar shingles on the roof. 9' x 7' overhead door installed in the				
East wall of the lean-to. Most of the 4"x24" four light windows have been replaced with 9"x12" four light				
vinyl windows.				
,				
INTERIOR NOTES: Two rows of 6"x6" posts, and 6x6 beams support the 2x8 joists for the hayloft floor.				
Four double horse stalls are still in place on the North wall. 4' wide stairs in the NE corner. Do not know				
what that area was used for, on the South wall. 40' hay feed rack built on the North wall of lean-to. 2x6 floor joists in the lean-to.				
OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding on all four walls of the barn. Wall between the				
barn and the lean-to is 2x6 with 1x8 shiplap. Rafters are 2x6's. 2x6 bracing from the hip down to the floor				
8' O. C. and 2x6 bracing at the hip 2' O. C. Original windows are 4"x24" four light. Most of the windows				
have been replaced with 9"x12" four light vinyl windows. Metal cupola still in place.				
*PHYSICAL NOTES: Barn is in good condition.				
*UTM ZONE:		*RESTRICTED: Y o	r N	
*UTM EASTING:			· ·•	
*UTM NORTHING:				




#### SKETCH MAP







#### SKETCH MAP



EAST ELEVATION

#### **PHOTOGR**





PHOTOGRAPHER: \_ DATE OF PHOTO:

Jim Stone June 11, 2013 ROLL NUMBER: PHOTO NUMBER:

:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: \_ DATE OF PHOTO:

Jim Stone June 11, 2013 ROLL NUMBER:

PHOTO NUMBER:

2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 11, 2013 PHOTO NUMBER:

PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: June 11, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NW, 4x6 post, 4x6 beam, 2x8 joists, horse stalls still in CAMERA DIRECTION: place on North wall.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, South lean-to, looking NW, hay feed

CAMERA DIRECTION: rack built on North wall.






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 11, 2013

**ROLL NUMBER:** PHOTO NUMBER:

Hayloft, looking SW, 2x6 rafters, 2x6 brace from CAMERA DIRECTION: hip down to floor 8' O. C.



PHOTOGRAPHER: Jim Stone


DATE OF PHOTO: \_\_\_\_\_ June 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking NE, wall and top over stairs to keep hay from falling

CAMERA DIRECTION: down on stairs.






PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

June 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking East, hayloft door, 2x6 bracing CAMERA DIRECTION: 2' O. C. at hip.







#### **HISTORY**

This farm located in the NE ¼ of Section 1 in Star Township, Clay County was homesteaded by Jacob J. Westre.

The 1894 Clay County Atlas lists D. M. Inman as the owner.

The 1901 Clay County Atlas lists Patrick Kilbride as the owner.

The 1912 Clay County Atlas lists Mike Kilbride as the owner.

The 1924 and 1937 Clay County Atlas lists Berdines Nelson as the owner.

The 1948 and 1956 Clay County Atlas lists Noble M. Nelson as the owner.

