


<b>"SITE INFORMATION</b>								
*SURVEY DATE: July 30, 2013		ADDRESS:	: 30635 456 <sup>th</sup> Ave.					
	Stone	*COUNTY:	Clay					
		*CITY:	Volin					
LOCATION DESCRIPTION: From	m Vermillion, intersectio	n of South D	akota Hig	hway	50 b	i-pas	s an	d
South Dakota Highway 19, North								
turn left, (South) about ¼ mile, on								
LEGAL DESCRIPTION: N 704' C	of S 1,200' of E 898', NE 1	l/4, 22 <b>–</b> 94 -	- 53 Beth	el Tw <sub>l</sub>	<b>)</b> .			
*QUARTER 1: NE 1/4		ER NAME:	Krishna K. Mastel & Christopher A Meyer					
*QUARTER 1: NE 1/4		ADDRESS:	30635 45	6 <sup>th</sup> Δν	Δ			
*TOWNSHIP: Bethel		-	Volin	<u> </u>	<u>.                                    </u>			
*RANGE: 53		ER STATE:	South Da	kota				
*SECTION: 22		-	57072					
ACRES: 13.68		AD NAME:	0.0					
OWNER CODE 1: P		· · · · · · · · · · · ·						
OWNER CODE 2:								
OWNER CODE 3:								
HISTORIC SIGNIFICANCE								
*DOE:	RE	GISTER NA	ME:					
*DOE DATE:		JLTIPLE PR	OPERTY I	NAME	: <u> </u>			
REASON INELIGIBLE:								
		CATEGORY:						
NOMINATION STATUS:		SIGNIF	FICANCE I	_EVEL	. 1:	N	S	L
		SIGNIF	FICANCE I	_EVEL	<b>2</b> :	N	S	L
REFERENCE NUMBER:	-							
HISTORIC DISTRICT RATING: (			RIA 1: A					
PERIOD:			RIA 2: A					
			RIA 3: A					
		CRITE	RIA 4: A	В	С	D		
CICNIFICANCE NOTES								
SIGNIFICANCE NOTES:								

#### STRUCTURE DETAILS



SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Vacant		FOUND	ATION:	Native stone, no mortar		
CURRENT SUBFUNCTION:			ROOF MAT	Steel roofing over cedar shingles			
HISTORIC FUNCTION:	Livestock barn		ROOF SHAPE:		Gable roof		
HISTORIC SUBFUNCTION:		orage S	TRUCTURAL S'	Balloon framing			
				Gable roof barn			
OCCUPIED:	No		STYLE: TYPE:		Western feeder barn		
ACCESSIBLE:	Yes with permission	w	WALLS:		2x6 studs, 1x8 #106 drop siding and embossed brick stessiding.		
STORIES	:2	SIGNIFICANT PERSON: N		: Nel	els C. & Hans M. Nelse		
*DATE OF CONSTRUCTION: Late 1800's CUI		CULTURA	L AFFILIATION	:	Danish		
ALTERED/MOVED NOTES: has been removed. Roof co	vered with 1-1/4"x2	26" galvanize	d corrugated ste	el roofin	nilk cow stanchions g over cedar shingles.	1	
Barn has been remodeled fo	r granaries in the c	enter barn ar	d the West lean	-to.			
INTERIOR NOTES: 2x6 stu							
barn is open 4x6's about 5' (		-	<u> </u>	•	lace at the North end.		
The hay feed rack for cows is							
OTHER NOTES: 2x6 stud	•					r	
walls. Rafters are 2x6's. W							
sawn cottonwood. 2x6's us			lled. Penciled n	ote on s	ide of granary in cente	<u>r</u>	
barn " Hans barn moved	March 1901", s	ee photos.					
***************************************							
*PHYSICAL NOTES: Barn is	in fair condition.		*RESTRICTE	D: Y o	r N		
*UTM EASTING:							









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 30, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

\* = REQUIRED FIELD

4





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 30, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 30, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 30, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 30, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NW, in East lean-to, hay feed rack, 4x4 open stud wall

CAMERA DIRECTION: on East of center barn.





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 30, 2013

ROLL NUMBER: \_\_\_\_\_

First floor, looking SW, East lean-to, single horse stalls still in place

6

CAMERA DIRECTION: at North end.





PHOTOGRAPHER: Jim Stone July 30, 2013 DATE OF PHOTO:

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NW into 18'x12' granary, 2x6

CAMERA DIRECTION: West wall of center barn.





Jim Stone PHOTOGRAPHER: July 30, 2013 DATE OF PHOTO:


**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft. looking SE, open

4x4 stud wall, 2x6

**CAMERA DIRECTION:** rafters.





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 30, 2013

**ROLL NUMBER:** PHOTO NUMBER:

Penciled note on side of granary, " Hans barn" can not read second line,

CAMERA DIRECTION: see next photo






PHOTOGRAPHER: Jim Stone July 30, 2013 DATE OF PHOTO:

**ROLL NUMBER: PHOTO NUMBER:** 

10

Penciled note on side of granary "moved \_\_\_\_-CAMERA DIRECTION: March, 1901"





CLAY CO., SD

1



#### **HISTORY**

This farm located in the NE ¼ of Section 22, Bethel Township, Clay County was homesteaded by Charles Nelson.

The 1894 Clay County Atlas lists Charles Nelson as the owner.

The 1901, 1912 and 1924 Clay County Atlas lists Nels C. & Hans M. Nelson as the owners. The farm was named "Morningside Farm" in the 1924 atlas.

The 1937 Clay County Atlas lists Carrie M. Nelson as the owner.

The 1948 and 1956 Clay County Atlas lists W. H. Beaty as the owner.

The following Is From The

#### Wakonda, S. D. Centennial Book 1885 – 1985

Hans M. and Mable Nelson Family

Hans M. Nelson (March 27, 1875 – April 3, 1963 was born in Clay county to Hans and Hannah Nelson who homesteaded four south, one east of and ½ mile south of Wakonda. Their sons, Hans married Mable Conrad (Feb. 11, 1885- May 17, 1940) and they continued to live on the farm and raised four children. Maynard Nelson (June 15, 1914). Pearl Nelson Sorenson (Aug. 26, 1915), Harlan Nelson (May 29, 1921) and Dorthy Nelson Babb (Jan. 11, 1927). Hans built onto the homestead house and then built a larger house in 1930 which was home to many people. As friends and relatives came from the "old country," Denmark, many of them lived with Hans and Mable until they could get started on their own. It was not unusual to have extra people to feed and Pearl remembers well stirring up a cake when they could see unexpected company coming down the long driveway.

Wayne Beaty, a great grandnephew of the homestead family, now owns this farm with his wife.