

SITE INFORMATION

*SURVEY DATE: Jult 2, 2012 *SURVEYOR: Jim Stone *ADDRESS: 45702 Jetly Park Street

R: Jim Stone

*CITY: Vermillion

*COUNTY: Clay

LOCATION DESCRIPTION: From intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, West about 5-3/4 miles to 459th Ave., turn left (South) about 200 feet and turn right (West), About 1 mile on the right (North) side.

LEGAL DESCRIPTION: NW ¼, EXC 11 A & EXC Lot H-2, 36 – 93 – 53 Meckling Twp.

*QUARTER 1:	NW 1/4		OWNER NAME: Melville & Ina E. Lars	son			
*QUARTER 2:	:		OWNER ADDRESS: 45702 Jetly Park Str	eet			
*TOWNSHIP:	: Meckling		OWNER CITY: Meckling				
*RANGE:			OWNER STATE: South Dakota				
*SECTION:	36		OWNER ZIP: <u>57069</u>				
ACRES:	CRES: 133.43		QUAD NAME:				
OWNER CODE 1:	Р						
OWNER CODE 2:	FSL	Ρ					
OWNER CODE 3: I	F S L	Ρ					
HISTORIC SIGNIE							
*DOE:			REGISTER NAME:				
*DOE DATE:							
			CATEGORY:				
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: 1	N S	L		
DATE	E LISTED:		SIGNIFICANCE LEVEL 2:	N S	L		
HISTORIC DISTRICT	RATING:	C or	or NC CRITERIA 1: A B C	D			
	PERIOD:		CRITERIA 2: A B C	D			
			CRITERIA 3: A B C	D			
			CRITERIA 4: A B C	D			
SIGNIFICANCE NOT	ES:						



STRUCTURE DETAILS			
		-	
*PROPERTY NAME: OTHER NAME:			
	Farm machinery		
CURRENT FUNCTION:	storage	FOUNDATION:	Poured concrete Asphalt over cedar
CURRENT SUBFUNCTION:	Shop	ROOF MATERIAL:	•
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Gable roof barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x6, 1x6 #106 drop siding
STORIES:	2	SIGNIFICANT PERSON:	Nels Larson
*DATE OF CONSTRUCTION:			Norwegian

ALTERED/MOVED NOTES: Original site. Roof shingled with asphalt shingles. All of the hayloft floor joists only have been raised to 14' except the East 8'. All of the horse stalls, milk cow stanchions and granary have been removed. A 17'x 12' sliding door added on the West wall. The East wall has been covered with steel roofing.


INTERIOR NOTES: <u>Had 6x6 posts and 6x6 beams to support hayloft floor, as per the 8' left on the East</u> end. Joists were 2x10.


OTHER NOTES: <u>Windows were 8"x10" four light. 2x6 stud walls 14' high. 1x6 #106 drop siding.</u> rafters and bracing are 2x6.

*PHYSICAL NOTES: <u>Barn is in excellent condition.</u>



SKETCH MAP





Jim Stone

July 2, 2012





PHOTOGRAPHER: July 2, 2012 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER: 1





PHOTOGRAPHER: DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER: 2 CAMERA DIRECTION: Looking NE, SW corner





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 2, 2012

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION: Looking NW, SE corner



 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 July 2, 2012
 PHOTO NUMBER:
 4

 CAMERA DIRECTION:
 Looking SW, NE corner





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 2, 2012

ROLL NUMBER: PHOTO NUMBER:

5 First floor, looking East, Hayloft section not raised

CAMERA DIRECTION: raised



PHOTOGRAPHER:	Jim Stone
DATE OF PHOTO:	July 2, 2012


ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: rafter bracing

6 First floor, looking East, rafter bracing

* = REQUIRED FIELD





* = REQUIRED FIELD

7



HISTORY

This section 36 was a School Section and could not be homesteaded. Any rents or sale on any part of it was for a county fund for rural schools.

The 1894, 1902 and 1912 Clay County Atlas lists Nels Larson as the owner.

The 1924, 1937, 1948 and 1956 Clay County Atlas lists George Larson as the owner.

The Following Information Is Furnished by

Melville Larson, the present owner.

Nels Larson bought this farm in 1891 for \$1.25 per acre. It was on a School Section. The house was built in 1893. The barn was built in 1913.

George Larson the son of Nels Larson farmed this land after his father. George and his wife Ivy had a son Melville.

Melville Larson farmed this land after his father. Melville and his wife Ina still live here.