

SITE INFORMATION

*SURVEY DATE: _July	23, 2012	*ADDRESS:	45774	1 314	i th St	reet			
*SURVEYOR: _Jim	*COUNTY:	: Clay							
		*CITY:	Meck	ling					
LOCATION DESCRIPTION:	The intersection ofSc	uth Dakota Highwa	ay 50 bi	-pas	s an	d Sc	outh l	Dako	ta
Highway 19, West 3-3/4 miles t	to 458 th Ave., turn rig	ht (North) about ½	mile to	314 ^t	^h Str	eet,	turn	left (West)
about 1/4 mile on the right (North	th) side.								
LEGAL DESCRIPTION: SE 1/2	4 25 - 93 - 53 Meck	ing Twp.							
***************************************						_			
*QUARTER 1: SE 1/4		OWNER NAME:	D. A. Olson & Sons LLC						
*QUARTER 2:		WNER ADDRESS:							
*TOWNSHIP: Mecklin	<u>g</u>	OWNER CITY:							
*RANGE: 53		OWNER STATE:	South	Dak	ota				
*SECTION: 25			57069						
ACRES: 163.16		QUAD NAME:							
OWNER CODE 1: P									
OWNER CODE 2:									
OWNER CODE 3:									
HISTORIC SIGNIFICANCE									
*DOE:		REGISTER NA	ME:						
*DOE DATE:		MULTIPLE PR		Y NA	ME:				
REASON INELIGIBLE:		-				-			
									
		-	С	ATE	GOF	RY:			
NOMINATION STATUS:		SIGNII	FICANC	E LE	VEL	. 1:	N	S	L
DATE LISTED:		SIGNII	FICANC	E LE	VEL	2:	N	S	L
REFERENCE NUMBER:		_							
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	Α	В	С	D		
PERIOD:		CRITE	RIA 2:	Α	В	С	D		
			RIA 3:	Α	В	С	D		
		CRITE	RIA 4:	Α	В	С	D		
SIGNIFICANCE NOTES:									

STRUCTURE DETAILS




SHPO ID:			
*PROPERTY NAME:			
OTHER NAME:			
	Farm machinery an		
CURRENT FUNCTION:	hay storage	FOUNDATION:	Poured concrete Steel roofing
			over cedar
CURRENT SUBFUNCTION:	Hay storage	ROOF MATERIAL:	shingles
HISTORIC FUNCTION:	Cattle feeder barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
			Livestock feeder
		STYLE:	barn
OCCUPIED:	Yes	TYPE:	Cattle feeder barn
ACCESSIBLE:	Yes with	WALLS.	2x6, 1x12 vertical
ACCESSIBLE:	permission	WALLS:	siding, steel
STORIES:	2	SIGNIFICANT PERSON:(Nielson) Nelson
*DATE OF CONSTRUCTION:	1910 to 1920	CULTURAL AFFILIATION:	Danish
ALTERED/MOVED NOTES:	Original site. App	ears to have a new poured concrete	e foundation and a
new concrete floor. Walls an	d roof have been co	vered with steel roofing. Doors and	d windows covered
with steel roofing. Four wind	lows have been repla	aced aluminum combination windo	ws. Two 12'x8' and
one 18'x14' overhead doors h			
		nd 24' between to support the cent	
		O.C. above the East 13' for a hayl	
O.C. on the West 13' for a hay and are open to the roof, exce		ge. The 24' high walls have 4' of bo	ards at the bottom
•	•	t, two windows close together with	A' to 6' hotwoon all
·		alls are 2x6, 4' O.C. with horizontal	
for the 1x12 vertical siding.	alis. The exterior w	ans are 2x6, 4 O.C. with horizontal	ZX4 Hallers 5 O.C.
Tor the 1x12 vertical slumg.			
*DUVCIONI NOTEC: Down !		This have with the amount of the reals	
		This barn with the ground to peak	center nayloff and
The two side haylofts could h	old over 150 tons of	loose nay.	
	_		
	_		
*UTM ZONE:		*RESTRICTED: Y o	r N
*UTM EASTING:			
*IITM NOPTHING:			

* = REQUIRED FIELD




SKETCH MAP





SKETCH MAP



PHOTOGR

* = REQUIRED FIELD





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	July 23, 2012	PHOTO NUMBER:	2
		CAMERA DIRECTION:	Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: 3
DATE OF PHOTO: July 23, 2012 PHOTO NUMBER: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2012 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 23, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, 2x6wall x 24' high, supports rafters, East

CAMERA DIRECTION: side



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 23, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, 2x6 wall 24' high supporting rafters,

CAMERA DIRECTION: West side





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 23, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, wall bracing to the CAMERA DIRECTION: hayloft floor, West side



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 23, 2012

ROLL NUMBER:

PHOTO NUMBER:

First floor, looking North grain chutes from the

CAMERA DIRECTION: hayloft.





Jim Stone July 23, 2012 PHOTOGRAPHER: DATE OF PHOTO:


ROLL NUMBER: PHOTO NUMBER:

Hayloft, West side,

looking North, hay or grain storage and wall

CAMERA DIRECTION: bracing





CLAY CO., SD



HISTORY

This farm located in the SE ¼ of Section 25, Meckling Township, Clay County was homesteaded by Joseph Hayes.

The 1894 Clay County Atlas lists H. Robinson as the owner.

The 1901 Clay County Atlas lists William E. Doyle as the owner.

The 1912 Clay County Atlas lists Thomas J. Steele as the owner.

The 1924 and 1937 Clay County Atlas lists Ella Steele as the owner. The 1937 lists Martin Knutson as the operator (renter).

The 1948 and 1956 Clay County Atlas lists J. A. Doyle as the owner.