

SITE INFORMATION


*SURVEY DATE: Nover	_ *ADDRESS:	SS: 46142 308 th Street							
*SURVEYOR: Jim S	*COUNTY:	Clay							
		*CITY:	Wakonda						
			'						
LOCATION DESCRIPTION: Fr	om the intersection	of South Dakota H	lighway	50 bi-p	ass a	and S	outh	l	
Dakota Highway 19, North 9 miles to 308th Street, turn left (West) 1-1/4 miles on the right (North) side.									
LEGAL DESCRIPTION: SW 1/4	, 27 – 94 – 52 Pleas	ant Valley Twp.							
*QUARTER 1: SW 1/4		OWNED NAME:	Duane A. & Michelle D. Johnson				son		
*QUARTER 2:	NER ADDRESS:								
*TOWNSHIP: Pleasant V		•	-						
*RANGE: 52		•	R CITY: <u>Vermillion</u> STATE: South Dakota						
*SECTION: 27		OWNER ZIP:							
ACRES: 150.82		•	57009						
OWNER CODE 1: P		QUAD NAME.							
OWNER CODE 2:									
OWNER CODE 3:									
O.M.E.R. 3032 5.									
HISTORIC SIGNIFICANCE									
*DOE:	REGISTER NAME:								
*DOE DATE:	MULTIPLE PROPERTY NAME:								
REASON INELIGIBLE:									
			CA	TEGO	RY:				
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L								
						L			
REFERENCE NUMBER:									
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	А В	С	D			
PERIOD:		CRITE	RIA 2:	А В	С	D			
		CRITE	RIA 3:	А В	С	D			
		CRITE	RIA 4:	А В	С	D			
SIGNIFICANCE NOTES:									

STRUCTURE DETAILS



SHPO ID:										
*PROPERTY NAME:										
OTHER NAME:										
CURRENT FUNCTION:	Cattle and calving barn	FOUNDATION:	Poured concrete foundation							
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Steel roofing over cedar shingles							
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel							
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing							
		 STYLE:	Gambrel roof barn							
OCCUPIED:	Yes	TYPE:	Livestock barn							
ACCESSIBLE:	Yes with permission	WALLS:	2x6 studs & 2x8 studs with sheathing and ½"x6" cedar drop siding							
	•									
STORIES:	2	SIGNIFICANT PERSON:	O. A. Abild							
*DATE OF CONSTRUCTION:	1910 to 1920 C	ULTURAL AFFILIATION: ½ Da	nish & ½ Norwegian							
ALTERED/MOVED NOTES: Original site. Most evidence of milk cow stanchions or horse stalls has been removed. Roof has been covered with steel roofing.										
INTERIOR NOTES: Has two rows of 6x6 posts with 6x8 for a beam. Floor joists are 2x8's. Solid										
		stalls were on the West side. 12'								
SE corner. 4x6 posts 12' O.C. in hayloft to support hip. 4x6 rafter behind each post, with (2) 2x10 bracing from the bottom of the center rafter down to the bottom of the 4x6 post. Only the center rafter and post have this (2) 2x10 bracing.										
OTHER NOTES: 2x6 stud walls on the East and West with horizontal sheathing, 2x8 stud walls with										
diagonal sheathing on the North and South and ½"x6" cedar lap siding. Rafters are 2x6's. 6 x 8 beams										
supporting floor joists have a special scarf joint. Windows are 8"x10" four light over 8"x10" four light.										
Has two very ornate metal cupola's.										
*PHYSICAL NOTES: Barn is in good condition. Very straight and plumb because of 2x8 stud walls on										
gable ends and the diagonal sheathing. Needs some repairs on doors and windows.										
*UTM ZONE:		*RESTRICTED: Y o	r N							
*UTM EASTING:		RESTRICTED. 1 0	ı 14							
*UTM NORTHING:										
5 : III 11011 I I III 10.										









PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: November 17, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: November 17, 2012 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 17, 2012 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: November 17, 2012

PHOTO NUMBER: 4

First floor, looking South, 6x6 posts, 6x8 beam and 2x10 floor CAMERA DIRECTION: joists





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: November 17, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, 2x6 solid wall dividing CAMERA DIRECTION: East 12' from rest of barn



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: November 17, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, 4x6 posts & 6x6 beam

CAMERA DIRECTION: supporting hip





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 17, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, 4x6 posts 6x6 beam & (2)

CAMERA DIRECTION: 1x6 bracing on hip



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone November 17, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, North gable end, 2x8studwall with

CAMERA DIRECTION: diagonal sheathing





© Farm & Home Publishers, Ltd.

3

CLAY CO., SD



HISTORY

This farm located in the SW ¼ of Section 27, Pleasant Valley township, Clay County was homesteaded by Ole Jacob Morvedt.

The 1894 and 1901 Clay County Atlas lists Lee & Prentis as the owners.

The 1912 and 1924 Clay County Atlas lists O. A. Abild as the owner.

The 1937 Clay County Atlas lists P. J. Bowman as the owner and E. Lindblom as the operator (renter).

The 1948 Clay County Atlas lists J. E. Bowman as the owner.

The 1956 Clay County Atlas lists F. E. Bowman as the owner.

The Following Information furnished by

Clay County Historical Society records

Lee & Prentis are listed as the owners in the 1901 Clay County Atlas. They had a large general merchandise store in Vermillion. They extended credit to local farmers and then during the 1890's had to re-possess several farms.

The 1912 and 1924 Clay County Atlas's lists O. A. Abild as the owner. This barn would have been built about this time.

