

```SITE INFORMATION

*SURVEY DATE: August 12, 2013 *SURVEYOR:

Jim Stone

*ADDRESS: 30520 458th Ave. *COUNTY: Clay *CITY: Wakonda

LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, North about 11 miles to 306th Street, turn left (West) about 4 miles to 458th Ave.,

turn right, (North) about 3/4 mile, on the right (East) side.

LEGAL DESCRIPTION: NE ¹/₄, NW 1/4, 18 – 94 – 52 Pleasant Valley Twp.

*QUARTER 1:	NW1/4	OWNER NAME:	Donald	1 H.	& Ja	nice	D. L	yso		
*QUARTER 2:		OWNER ADDRESS:	30520	458 ^t	^h Ave	e.				
*TOWNSHIP:	Pleasant Valley	OWNER CITY:	Wakon	Ida						
*RANGE:	52	OWNER STATE:	South	Dak	ota					
*SECTION:	18	OWNER ZIP:	57073							
ACRES:	37.45	QUAD NAME:								
OWNER CODE 1:	Р									
OWNER CODE 2:										
OWNER CODE 3:										
HISTORIC SIGN	IFICANCE									
*D	OE:	REGISTER NA	ME:							
	TE:									
			C	ΑΤΕ	GOF	RY:				
NOMINATIO	N STATUS:	SIGNI	FICANC	ELE	EVEL	. 1:	Ν	S	L	
	TE LISTED:		FICANC	E LE	EVEL	2:	Ν	S	L	
REFERENCI	E NUMBER:									
	CT RATING: C or		ERIA 1:	Α	в	С	D			
	PERIOD:	CRITE	ERIA 2:	Α	в	С	D			
			ERIA 3:	Α	в	С	D			
		CRITE	ERIA 4:	Α	в	С	D			
SIGNIFICANCE NO	TES:									

STRUCTURE DETAILS

* = REQUIRED FIELD



SHPO ID:			
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Machinery storage	FOUNDATION:	Poured concrete
CURRENT SUBFUNCTION:	Calving barn	ROOF MATERIAL:	Steel roofing over cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable roof
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Western feeder barn barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x6 studs, and 1x6 #106 drop siding
STORIES:	2	SIGNIFICANT PERSON:	Olaf Skonhovd
*DATE OF CONSTRUCTION:	1915 - 1920	CULTURAL AFFILIATION:	?

ALTERED/MOVED NOTES: Original site. Roof covered with steel roofing over cedar shingles. 14' x 48' lean-to added on the East side later. 16' x 16' overhead installed in the West wall for large machinery storage. The 1x6 drop siding was removed from the lower 8' on the east wall and replaced with 1x10 shiplap when lean-to was added. 1x6 #106 drop siding still in place above shiplap on this wall.

 INTERIOR NOTES:
 Two rows of 4x6 posts with 4x6's for beams support 2x6 rafters. Double 2x6 posts

 and 2x6 bracing also support rafters. (see drawing elevation)
 Three of the four double horse stalls still in

 place on the North side.
 10 milk cow stanchions are still in place on the South side.


 OTHER NOTES:
 2x6 stud walls with 1x6 #106 drop siding. Center 16' of original barn was hayloft, 16' x

 32' and 24' from the ground to the peak. Windows were 9" x12" four light and 4"x24" four light.

*PHYSICAL				
NOTES:	Barn is in good condition.	*RESTRICTED:	Y or	Ν
*UTM EASTING:				
*UTM NORTHING:				




SKETCH MAP




PHOTOGR

N



* = REQUIRED FIELD





SKETCH MAP

FIRST FLOOR

PHOTOGR





Jim Stone PHOTOGRAPHER: **ROLL NUMBER:** August 12, 2013 DATE OF PHOTO: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner

1



PHOTOGRAPHER: August 12, 2013 DATE OF PHOTO:

ROLL NUMBER: 2 PHOTO NUMBER: CAMERA DIRECTION: Looking NW, SE corner






 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 August 12, 2013
 PHOTO NUMBER:
 3

 CAMERA DIRECTION:
 Looking SW, NE corner



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	August 12, 2013	PHOTO NUMBER:	4
		CAMERA DIRECTION:	Looking SE, NW corner






PHOTOGRAPHER:Jim StoneDATE OF PHOTO:August 12, 2013

ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 5 Looking SW & up, in East lean-to, 2x6 rafters and 2x6 rafter bracing. note shiplap on wall with CAMERA DIRECTION: drop siding above.



PHOTOGRAPHER:Jim StoneDATE OF PHOTO:August 12, 2013

ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 6 First floor, looking SE in original barn horse stall CAMERA DIRECTION: on North side.

* = REQUIRED FIELD






PHOTOGRAPHER: _____ DATE OF PHOTO: Jim Stone August 12, 2013 ROLL NUMBER: PHOTO NUMBER:

7
 looki

First floor, looking SE, 4x6 posts 8' O. C.,1x6 bracing supporting rafters.

CAMERA DIRECTION: rafters.





© Farm & Home Publishers, Ltd.

31

CLAY CO., SD



History

This farm located in the NW ¼ of Section 18, Bethel Township, Clay County was homesteaded by Ole Hovelson.

The 1894, 1901 and 1912 Clay County Atlas lists Olaf Skonhovd as the owner.

The1924 Clay County Atlas lists Christina Ostrem as the owner.

The 1937 Clay County Atlas lists C. Johnson as the owner.

The 1948 and 1956 Clay County Atlas lists Hans Lyso as the owner.