

SIT	E IN	FOI	RMA	١T١	ON


*SURVEY D	ATE: A	pril 7, 20	013	*ADDRESS	5: 46711 298 th Street							
*SURVEYOR: J		m Stone	е	*COUNTY	Clay	Clay						
				*CITY	Bere	sfor	t					
LOCATION DESCR	IPTION: F	rom Ver	million, Inters	ection of South	Dakota l	High	way	bi-p	ass a	and		
South Dakota High	way 19, Nort	th 10 mi	les to 307th th \$	Street, turn left (\	West) 1/	/2 mi	le to	Plea	asant	Vall	еу	
Ave., turn right (No	rth) about ¾	mile or	the left (Wes	:) side.								
LEGAL DESCRIPTI	ON: <u>NW 1</u>	/ ₄ , Exc.	N 250' of S 770	of W 350'of E	1,220', 2	22 –	94 –	52 I	Pleas	ant \	Valley	
Twp.												
*QUARTER 1:	NW 1/4				Westergaard Family Trust							
*QUARTER 2:			OWI	OWNER ADDRESS:								
*TOWNSHIP:	Pleasant \	Valley		OWNER CITY:			Burbank					
*RANGE:	52		(OWNER STATE:								
*SECTION:	22			OWNER ZIP:	57010							
ACRES:	156.47			QUAD NAME:								
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGN	IFICANCE											
				DECISTED N	. N.4 .							
*DOE:				REGISTER NAME: MULTIPLE PROPERTY NAME:								
*DOE DATE: REASON INELIGIBLE:				MULTIPLE PR	COPERI	T IN	4IVI C	_				
REASON INELIGIB	LC:											
					(:ATF	GOF	۶γ٠				
NOMINATION STATUS:				CATEGORY: SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:				— SIGNIEICANCE LEVEL 2: N S I								
REFERENCE				0.011						Ū	_	
HISTORIC DISTRIC		C or	NC:	CRITI	ERIA 1:	Δ	В	С	D			
					ERIA 2:							
					ERIA 3:							
				_	ERIA 4:							
				J			_		_			
SIGNIFICANCE NOTES:												

STRUCTURE DETAILS




SHPO ID:		<u></u>						
*PROPERTY NAME:								
OTHER NAME:								
CURRENT FUNCTION:	Calving barn	FOUNDATION:	Poured concrete					
CURRENT CURFUNCTION.	Ct	DOOF MATERIAL.	Steel over cedar					
CURRENT SUBFUNCTION:	Straw storage ROOF MATERIAL: Livestock barn ROOF SHAPE:		shingles					
HISTORIC FUNCTION:	Livestock barn	Gambrel						
HISTORIC SUBFUNCTION:	Hay and grain storage		Balloon framing					
		_	Gambrel roof barn					
OCCUPIED:	Yes	TYPE:	Livestock barn					
			2x6 studs, 1x8 sheathing and					
			½"x6" cedar lap					
	Yes with		siding & some 8"					
ACCESSIBLE:	permission	WALLS:	poured concrete					
STORIES:			Ole O. Ellefson					
*DATE OF CONSTRUCTION:	<u>1913</u> C	ULTURAL AFFILIATION:	?					
-		ence of horse stalls has been re						
been covered with steel roofing. 24' addition on North added later. South end remodeled into a milking								
parlor. 14'x14' milk room added on the West side. North end remodeled for swine. Metal cupola is								
gone.								
INTERIOR NOTES: The original barn has two rows of 6x6 posts and 6x6 for a beam. 2x8 floor joists								
that run South to North. The addition on the North has 6x6 posts with 6x6 beams and 2x8 floor joists								
that run East to West. A 15' tall tank about 7' in diameter has been installed on the first floor and is								
about 7' into the hayloft. It stored grain for the dairy cows.								
OTHER NOTES: In the North 24' x 32' addition and the hayloft gable ends are 2x6 stud walls with 1x8								
sheathing and ½"x6" cedar lap siding. The South 32'x32' original barn has 8" poured concrete walls.								
The North concrete wall was removed when the North addition was added. Rafters are 2x6's. Two 1x6's bracing on each hip in hayloft. A 2x6 brace from center of lower rafter down to floor. Windows are								
8"x10" four light with some 8"x10" four light over 8"x10" four light for ventilation. "Pleasant Dell Farm"								
painted on large hayloft door.								
*PHYSICAL NOTES: Barn is in good condition.								
*IITM ZONE.		*RESTRICTED: Y o	ar N					
*UTM ZONE:			IN IN					
*UTM EASTING:								
*UTM NORTHING:								







SKETCH MAP



PHOTOGR





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April 7, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: April 7, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April 7, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April 7, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: April 7, 2013

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW, 6x6 posts, 6x6 beam and 2x8 floor joists, running





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: April 7, 2013

ROLL NUMBER:

PHOTO NUMBER: 6

First floor, looking SW, (9) milk cow stanchions

CAMERA DIRECTION: on South wall





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 7, 2013 ROLL NUMBER: PHOTO NUMBER:

7

First floor, North side looking SW, 6x6 posts, 6x6 beam and 2x8 floor joists running East to West

CAMERA DIRECTION: West.



PHOTOGRAPHER: ____ DATE OF PHOTO: ___

Jim Stone April 7, 2013 ROLL NUMBER: PHOTO NUMBER:

8

Hayloft, looking NW, double 1x6' bracing on hip, note 2x6 diagonal

CAMERA DIRECTION: bracing.

* = REQUIRED FIELD





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: April 7, 2013


ROLL NUMBER: PHOTO NUMBER:

9

Hayloft, looking SE, double 1x6's bracing each hip, 2x6 diagonal

CAMERA DIRECTION: brace down to floor.





O Farm & Home Publishers, Ltd.

31

CLAY CO., SD



HISTORY

This farm located in the NW ¼ of Section 22, Pleasant Valley Township, Clay County was homesteaded by Peter Larson Christiansen.

The 1894 Clay County Atlas lists William Meyer as the owner.

The 1901 Clay County atlas lists Hall Anton Christoferson as the owner.

The 1912 Clay County Atlas lists Ole O. Ellefson as the owner.



The 1924, 1937 and 1948 Clay County Atlas lists Oscar S. Ellefson as the owner.

The 1956 Clay County Atlas lists J. F. Blasche as the owner.