

SITE INFORMATION

*SURVEY DATE: Febr	uary 12, 2013	*ADDRESS:	46175	302	nd St	treet						
*SURVEYOR: Jim \$	Stone	*COUNTY:	Clay									
		*CITY:	Cente	rvill	е							
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and												
South Dakota Highway 19, (North) 15 miles to 302 nd Street, turn left (West), about 1/4 mile on the left												
(South) side.												
LEGAL DESCRIPTION: NE¼, Exc. Lot H 2 & Cty Rd, 34 – 95 – 52 Riverside Twp.												
*QUARTER 1: NE 1/4		OWNER NAME:			Dorsie Lou Jensen, Etal							
*QUARTER 2:		OWNER NAME. OWNER ADDRESS:			45752 302 nd Street							
*TOWNSHIP: Riverside		•			Wakonda							
*RANGE: 52		-			South Dakota							
*SECTION: 34		OWNER ZIP: 57073										
ACRES: 155.23		QUAD NAME:	0.0.0									
OWNER CODE 1: P		<u>-</u>										
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNIFICANCE												
*DOE:	REGISTER NAME:											
*DOE DATE:	MULTIPLE PROPERTY NAME:											
REASON INELIGIBLE:			J									
	_											
			С	ATE	GOF	RY:						
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N S L										
DATE LISTED:		SIGNIFICANCE LEVEL 2: N S L										
REFERENCE NUMBER:												
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	Α	В	С	D					
PERIOD:		CRITE	RIA 2:	Α	В	С	D					
		CRITE	RIA 3:	Α	В	С	D					
		CRITE	RIA 4:	Α	В	С	D					
SIGNIFICANCE NOTES:												


STRUCTURE DETAILS




SHPO ID:		_								
*PROPERTY NAME:										
OTHER NAME:										
CURRENT FUNCTION:	CURRENT FUNCTION: Cattle in the summer		ON: Poured concrete							
			Asphalt shingles							
CURRENT SUBFUNCTION:	Storago	ROOF MATERI	over cedar IAL: shingles							
HISTORIC FUNCTION:	Storage Livestock barn	_ ROOF SHA								
HISTORIC SUBFUNCTION:		_	-							
HISTORIC SUBFUNCTION.	Hay & grain storage	STRUCTURAL SYSTEM: Balloon framin Gothic round r								
		STY	'LE: barn							
OCCUPIED:	Yes	TY	PE: Livestock barn							
			2x6 studs, 1x8							
ACCECCIDI E.	Yes with	WALLC.	sheathing and steel							
ACCESSIBLE:	permission	WALLS:	roofing.							
STORIES.	2	CICNIFICANT DEDCOM	Occasional Albin Johnson							
STORIES:	About	SIGNIFICANT PERSON:	Oscar and Albin Johnson							
*DATE OF CONSTRUCTION:		JLTURAL AFFILIATION:	?							
ALTERED/MOVED NOTES:	Original site. Any evide	ence of milk cow stanchions	s has been removed.							
Horse stalls were in the West	side and all except part	of a single and a double ho	orse stall have been							
removed. Siding has been re	moved when steel roofi	ng was applied on the walls	s. Granary was removed							
from the NW corner and a do			·							
		,								
			_							
INTERIOR NOTES: Has a 2x										
and 6x6 beams in the West si			One row 6x6 posts and a							
6x6 beam in the East side and		<u> </u>								
OTHER NOTES: Walls are 2x6 with 1x8 sheathing and steel roofing. Rafters are 5 plies of 1x12 x 6'6"										
cedar laminated and cut to roof arc on the outside. These rafters are 8' O. C. except 5' O. C. from gable										
ends. Horizontal 2x4 purlins			re 2' O. C. 2x6x 5'							
horizontals purlins are betwe	en the last rafter and the	e gable ends.								
*PHYSICAL NOTES: Barn is	s in fair condition. Roof	is leaking and rotting out th	ne hayloft floor.							
*UTM ZONF·		*RESTRICTED:	Y or N							
*UTM EASTING:			. 5							
*UTM NORTHING:										
5 m 45 k m 46 k										




SKETCH MAP







SKETCH MAP



WEST ELEVATION

PHOTOGR

" = RECHIRED FIELD





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 12, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 12, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner






PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 12, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 12, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 12, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, West side,

looking NE, two horse Stalls still in West side





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 12, 2013


ROLL NUMBER: PHOTO NUMBER:

6

First floor, East side, looking SW, posts and beam, (2) 2x6 beam and 2x6 solid wall, note

CAMERA DIRECTION: missing posts.





PHOTOGRAPHER:


Jim Stone DATE OF PHOTO: February 12, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SE, 1x12 rafters 8' O.C., 2x4 horizontal purlins 2'O. C. and vertical three ply

CAMERA DIRECTION: rafters 2. O. C.





PHOTOGRAPHER:

Jim Stone

DATE OF PHOTO: February 12, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking East, rafters and East gable

CAMERA DIRECTION: end





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: February 12, 2013

ROLL NUMBER: PHOTO NUMBER:

9

Hayloft, looking NE, 12' x 14' granary in the NE corner of hayloft

CAMERA DIRECTION: corner of hayloft.





PHOTOGRAPHER: Jim Stone February 12, 2013 DATE OF PHOTO:


ROLL NUMBER: PHOTO NUMBER:

10

Hayloft, looking North, 2x10 vertical bracing, 10' O. C., strengthening the

CAMERA DIRECTION: gable ends.





P Farm & Home Publishers, Ltd

35

CLAY CO., SD



HISTORY

This farm located in the NE ¼ of Section 34, Riverside Township, Clay County was homesteaded by Richard P. Brookaw.

The 1894 Clay County Atlas lists A. Hallam as the owner.

The 1901 Clay County Atlas lists Marvid (Spelling?) Carlson as the owner

The 1912 Clay County Atlas lists J. R. Johnson as the owner.

The 1924 and 1937 Clay County Atlas lists Oscar I. & Ablid E. Johnson as the owners.

The 1948 and 1956 Clay County Atlas lists Albin E. Johnson as the owner.