


#### **SITE INFORMATION**

*SURVEY DATE: Febru	*ADDRESS: 46185 307 <sup>th</sup> Street										
*SURVEYOR: _Jim St	*COUNTY:	Clay									
		*CITY:	Wakonda								
LOCATION DESCRIPTION: <u>Fr</u>								9			
10 miles North to 307th Street, tu	ırn left (West) aboı	ut ¼ mile, turn left (	South) ir	nto fa	arms	tea	d.				
LEGAL DESCRIPTION: <u>E ½ N</u>	E 1/4 EXC Lot H2, 2	7 – 94 – 52, Pleasan	nt Valley	Twp.	•						
*QUARTER 1: NE 1/4		Ron Hesla									
*QUARTER 2:	WNER ADDRESS:	6: 46185 307 <sup>th</sup> Street									
*TOWNSHIP: Pleasant Va	ılley				onda						
*RANGE: 52	<del></del>	OWNER STATE: South Dakota									
*SECTION: 27		OWNER ZIP:									
ACRES: 115		QUAD NAME:									
OWNER CODE 1: P											
OWNER CODE 2: F S L	Р										
OWNER CODE 3: F S L	P										
HISTORIC SIGNIFICANCE											
*DOE:	REGISTER NAME:										
*DOE DATE:	_ MULTIPLE PR	OPERTY	' NAI	ME:							
REASON INELIGIBLE:	_	_									
		_									
		CATEGORY:									
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L SIGNIFICANCE LEVEL 2: N S L							_			
DATE LISTED:		_ SIGNII	FICANCE	LEV	VEL	2:	N	S	L		
REFERENCE NUMBER:			-DIA 4	_	_	_	_				
HISTORIC DISTRICT RATING:			ERIA 1:								
PERIOD:		<del>_</del>	RIA 2:								
			ERIA 3:								
		CRITE	ERIA 4:	А	В	Ü	ט				
SIGNIFICANCE NOTES:											
SIGNIFICANCE NOTES:											



STRUCTURE DETAILS									
SHPO ID:									
*PROPERTY NAME:	Ron Hesla harn								
OTHER NAME:	Non riesia barri								
OTHER HAME.									
CURRENT FUNCTION:	Machinery storage	FOUNDATION:	Poured concrete						
	macrimory crorage		Asphalt shingles						
			over cedar						
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:							
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gothic round						
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Gothic round roof						
OCCUPIED:	Yes	TYPE:	Livestock barn						
	<b>Y</b> 1.1		2x6 and 2x8 with						
ACCESSIBLE:	Yes with permission	WALLS	sheathing and ½" x 6" cedar siding						
ACCESSIBLE.	permission	WALLS.	o cedar sidilig						
STORIES:	2 S	IGNIFICANT PERSON:	Peter S. Hesla						
*DATE OF CONSTRUCTION:			-						
DATE OF CONSTRUCTION:	1920 to 1930 COI	_TURAL AFFILIATION:	Norwegian						
ALTERED/MOVED NOTES: Original site. Horse stalls and stanchions removed. About ½ of the South end of hayloft has been removed. All of the posts and beams have been removed except the last two rows at the North end.									
INTERIOR NOTES: 6x6 posts and 6x6 beams running East and West. 2x8 floor joists running North and South (the long way). Can not tell how many rows of posts and beams supported the hayloft floor,									
because all but two rows at the North end have been removed. I can see where a row of horse stalls									
were at the North end.									
OTHER NOTES: 2x6 stud walls 10' tall on the East and West sides with horizontal sheathing. 2x8 stud									
walls on the North and South (gable ends) with diagonal sheathing. Sheathing was applied at a 45									
degree angle from the outside walls up to the center of the wall. Poured concrete foundation wall is									
2' – 4"above the ground level with the 10' walls on top. Metal cupola in center on roof. ½" x 6" cedar									
siding on all walls. Rafters are 5 ply's of ¾" x full 4" bent and nailed, appear to have been built on site. ¾" x 12" sheathing boards on the roof. 8"x10" four light over 8"x10" four windows double hung.									
*PHYSICAL NOTES: Barn is in very good condition. Some bracing is required on the South end where									
where the hayloft floor has be	een removed. 2 or 3 cable	es running from the East to We	est walls with a turn-						
buckle would solve the proble	em.								









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 18, 2012

**ROLL NUMBER:** PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

February 18, 2012

**ROLL NUMBER:** 

**PHOTO NUMBER:** 

CAMERA DIRECTION: Looking SW, NE corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: February 18, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Looking SE, NW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 18, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor looking South, note floor joists run

CAMERA DIRECTION: length of barn





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 18, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor looking North.

Note scarf joint on 6x6





PHOTOGRAPHER: DATE OF PHOTO: February 18, 2012

Jim Stone

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: \_five ply round rafter

Hayloft, 3/4" x full 4"






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 18, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Hayloft looking North




PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 18, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Hayloft looking South





PLEASANT VALLEY TOWNSHIP SECTION 2

County of Clay 13
 SECTION 6
 Wolfswinkel, Sands
 SECTION 8

Peterson, Sterling 6
 Knudson, Dennis 6

SECTION 19
1. Rohrer, Larry 6
2. Mews, Michael 5
SECTION 23 1. Huot, Clifford 11 SECTION 26 1. Sample Jr.

SECTION 29
1. Pleasant Valley
Lutheran Church 5
SECTION 39 1. Woehl, Time SECTION 31 1. Muller, Rich SECTION 32 1. Free

SECTION 35
1. Dimond, Patricia 8
2. American State Bank 8
3. Wibben, Cristeen 12
SECTION 35
1. Christensen, Scott 6

© Farm & Home Publishers, Ltd.

30

CLAY CO., SD



### **HISTORY**

This farm located in the NE ¼ of Section 27, Pleasant Valley Township, Clay County was homesteaded by Victory Loses or Losee.

The 1894 Clay County Atlas lists W. H. Goodburn as the owner.

The 1901 and 1912 Clay County Atlas lists Melvin A. Vaughn as the owner.

The 1925, 1937, 1948 and 1956 Clay County Atlas lists Peter E. Hesla as the owner.

