


SITE INFORMATION

*SURVEY DATE	*ADDRESS: 31726 Meckling Road											
*SURVEYOR: Jim Stone				*COUNTY								
	*CITY	: Vermillion										
LOCATION DESCRIPTION: From Vermillion West on South Dakota Highway 50 about 1 mile, turn												
left (South) on South Dakota Highway 19, about 250' turn right (West) on Timber Road. Fallow Timber											_	
Road about 4-3/4 miles, turn Right (North) on Meckling Road, about ¼ mile on the right (East) side.											_	
LEGAL DESCRIPTION: W 500' of S 660' of NW ¼, NW ¼, 13 – 92 – 53 Norway Twp.											_	
												_
					Dahaa		٠		C A	1	_	
*QUARTER 1: NW 1/4				OWNER NAME:	Rebecca C. & Lars G. Aga, LE - Marion Kryger							
*QUARTER 2:				WNER ADDRESS: 31726 Meckling Road					_			
				OWNER CITY:						_		
*RANGE:				OWNER STATE:	South Dakota					_		
*SECTION:				OWNER ZIP:						_		
ACRES:	6.86			QUAD NAME:								
OWNER CODE 1:	•											
OWNER CODE 2: F	S L	Р										
OWNER CODE 3: F	S L	Р										
HISTORIC SIGNIFIC	JANCE											
*DOE:				REGISTER NAME:								
*DOE DATE:				MULTIPLE PR	ROPERT	Y NA	AME	: _				
REASON INELIGIBLE:												
					C	CATE	GOI	RY:				
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L									
DATE LISTED:				SIGNI	FICANO	ELE	EVEL	2:	N	S	L	
REFERENCE NU	_											
HISTORIC DISTRICT R	ATING:	C or	NC		ERIA 1:							
P	ERIOD:				ERIA 2:							
					ERIA 3:							
				CRITI	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NOTES:												
												_



STRUCTURE DETAILS									
SHPO ID:									
*PROPERTY NAME:		_							
OTHER NAME:									
	Farm machinery								
CURRENT FUNCTION:	storage and shop	FOUNDATION:	Poured concrete						
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Steel						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel						
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Gambrel roof barn						
OCCUPIED:	Yes	TYPE:	Livestock barn						
			2x6, sheathing &						
ACCECCIDI E	Yes with	MALL C.	original pressed						
ACCESSIBLE:	permission	WALLS:	brick steel roofing						
0700150			D 1 1/						
STORIES:	2	SIGNIFICANT PERSON:	Peter Kryger						
*DATE OF CONSTRUCTION:	1936 C	ULTURAL AFFILIATION:	Norwegian						
ALTERED/MOVED NOTES: _		s covered with steel roofing. All	•						
		. Barn has been remodeled into							
building and shop. The 2x6 walls 11' high, so the owner used floor joists to brace the rafters at 16' high.									
18'x16' double sliding door was added to the North gable wall for large machinery access. 16'x 46' lean-									
to was added on the East side	e in April 1978.								
INTERIOR NOTES: Had 6v6	nosts and 6v6 heams t	o support havioft floor loists y	were 2v8 All of the						
INTERIOR NOTES: Had 6x6 posts and 6x6 beams to support hayloft floor. Joists were 2x8. All of the									
2x6's for studs, rafters and bracing, 2x8 floor joists, 6x6 posts and 6x6 beams were rough sawn									
cottonwood.									
OTHER NOTES: Windows are 9"x12" four light. Metal cupola. Barn was built from salvaged									
materials from the original barn (see picture). Siding is pressed brick steel siding that was applied when									
the barn was built.									
	, ,	n. A very good idea to continue	the use of an old						
barn for today's agriculture needs.									









Jim Stone PHOTOGRAPHER: DATE OF PHOTO: June 21, 2012

ROLL NUMBER: PHOTO NUMBER: Looking SE, NW

CAMERA DIRECTION: _ corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 21, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: June 21, 2012 PHOTO NUMBER: 4
First floor, looking

South, rafter bracing for CAMERA DIRECTION: raised ceiling





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

Looking SE, East wall, original stud wall and

CAMERA DIRECTION: added rafter bracing



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

Looking up in to the SE of bracing in hip and

CAMERA DIRECTION: raised ceiling





PHOTOGRAPHER: ? ROLL NUMBER: DATE OF PHOTO: 1912 PHOTO NUMBER: 6
Original barn, s

Original barn, salvaged material was used to build the new barn in

CAMERA DIRECTION: 1936.

Gedy Rolling How Sunderson & Mrs. D. B. Bunderson W. B. Bunderson Who Sunderson wife (Lalding son His Sunderson Who Sunderson Williams on House Revenue of the Revenue of t

PHOTOGRAPHER: ? ROLL NUMBER: DATE OF PHOTO: 1912 PHOTO NUMBER: 7
Back of photo #6, note

CAMERA DIRECTION: date 1912



HISTORY

This farm located in the NW ¼ of Section 13, Norway Township, Clay County was homesteaded by Ole Larson.

The 1894 Clay County atlas lists Hans Gunderson as the owner.

The 1901, 1912 and 1924 Clay County Atlas lists Hans Gunderson as the owner.

The 1937 Clay County Atlas lists Peter Kryger as the owner.

The 1948 and 1956 Clay County Atlas lists A. W. Kryger as the owner.

The Following Information Was Furnished by

Marion Kryger, who grew up here and later bought the farm and farmed it.

Marion Kryger was the youngest of six children. His parents were Mr. and Mrs. August Kryger. Marion's mother died when Marion was 10 months old. His aunt and uncle Mr. and Mrs. Peter Kryger raised Marion. They later adopted him.

Vernon McKee and Walter Kaeberle who were neighbors built this barn in 1936, from salvaged materials of the original barn on this farm. This barn was built on the same foundation as the original barn.

.Peter Kryger hired Vernon McKee (A nephew and Walter Kaeberle to build this barn using salvaged material from the original barn (see picture #6) in 1936.