

```SITE INFORMATION

*SURVEY DATE: June 3, 2013

*SURVEYOR: Jim Stone

*ADDRESS: 29731 Frog Creek Road *COUNTY: Clay *CITY: Centerville

LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 15 miles to 302nd Street, turn left, (West) about 3 miles, turn right

North) 4-3/4 miles on the left (West) side.

LEGAL DESCRIPTION: Martz Tract 1, NE ¼, 6–95 – 52 Riverside Twp.

*QUARTER 1:	NE 1/4	OWNER NAME:	Royce J.	Martz	2				
*QUARTER 2:		OWNER ADDRESS:	29731 Fr	og Cr	eek r	road			
*TOWNSHIP:	Riverside	OWNER CITY:	Centervi	lle					
*RANGE:	52	OWNER STATE:	South Da	akota					
*SECTION:	6	OWNER ZIP:	57014						
ACRES:	8.27	QUAD NAME:							
OWNER CODE 1:	Р								
OWNER CODE 2:									
OWNER CODE 3:									
HISTORIC SIGN	IFICANCE								
*DOE:		REGISTER NA	ME:						
*DOE DATE:			OPERTY I	NAME	: _				
REASON INELIGIB	LE:								
			CAT	EGO	RY:				
NOMINATION STATUS:		SIGNI	FICANCE	LEVEI	L 1:	Ν	S	L	
DATE LISTED:		SIGNI	FICANCE	LEVEI	_ 2:	Ν	S	L	
	E NUMBER:								
HISTORIC DISTRIC	TRATING: C o	r NC CRITE	ERIA 1: A	В	С	D			
	PERIOD:	CRITE	ERIA 2: A	В	С	D			
		CRITE	ERIA 3: A	В	С	D			
		CRITE	ERIA 4: A	В	С	D			
SIGNIFICANCE NO	TES:								
STRUCTURE DE	ETAILS								

* = REQUIRED FIELD




SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete				
CURRENT SUBFUNCTION:	Vacant	ROOF MATERIAL:	Cedar shingles				
HISTORIC FUNCTION:	Livestock ba	rn ROOF SHAPE:	Gable				
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing				
		STYLE:	Gable roof barn				
OCCUPIED:	Yes	TYPE:	Livestock barn				
	Yes with		2x6 studs, 1x6 T&G sheathing on first floor, 12" vertical				
ACCESSIBLE:	permission	WALLS:	siding				
	•		v				
STORIES:	2	SIGNIFICANT PERSON:					
*DATE OF CONSTRUCTION:	1890's	CULTURAL AFFILIATION:	?				
ALTERED/MOVED NOTES:	Original site.	Wood cupola removed. Any evidence of	milk cow stanchions				
or horse stalls has been removed.							
INTERIOR NOTES: Two rows of 4x6 posts and 6x6 beams. 2x8 floor joists for hayloft floor.							
All evidence of horse stalls or milk cow stanchions has been removed.							

OTHER NOTES: 2x6 stud walls with 1x6 T&G horizontal sheathing on all four walls, but only the first floor. 12" vertical siding with battens. Horizontal purlins about 3' O. C. space the vertical siding out even with the first floor. Rafters are 2x6. Two rows of 2x6 posts with a 2x6 beam support the center of the rafters. 2x6 posts in the hayloft are 12'-14'-14' O. C. 4"x24" four light windows. *PHYSICAL NOTES: Barn is in poor condition.

*UTM ZONE: ______ *RESTRICTED: Y or N *UTM EASTING: ______ *UTM NORTHING: _____



SKETCH MAP







* = REQUIRED FIELD










PHOTOGRAPHER:	Jim Stone		
DATE OF PHOTO:	June 3, 2013		

ROLL NUMBER: PHOTO NUMBER:

5 First floor, looking SW, 4x6 posts, 6x6 beam & 2x8 floor joists

CAMERA DIRECTION: 2x8 floor joists







PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone June 3, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking up and NW, 2x6 rafters and 2x6 post and 2x6 beam supporting center of


7

CAMERA DIRECTION: rafters.



* = REQUIRED FIELD





© Farm & Home Publishers, Ltd.

35

CLAY CO., SD



HISTORY

This farm located in the NE ¼ of Section 6, Riverside Township, Clay County was homesteaded by Charles E. Prentiss.

The 1894 and 1901 Clay County Atlas lists R. M. Varnum as the owner.

The 1912, 1924, 1937, 1948 and 1956 Clay County atlas lists James Varnum as the owner.

