


""SITE INFORMATION				
*SURVEY DATE: July 27, 2	2013 *ADDRESS: 45850 306 th Street			
*SURVEYOR: Jim Ston				
	*CITY: Wakonda			
LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and				
South Dakota Highway 19, North about11 miles to 306th Street, turn left (West) about 3-1/2 miles, on the				
right, (North) side.				
LEGAL DESCRIPTION: W 350' of S 840' Exc H-1 & H-2 in SW 1/4, 18 – 94 – 52 Pleasant Valley Twp				
*QUARTER 1: SW 1/4	OWNER NAME: Nickolas Schwebach			
*QUARTER 2:	OWNER ADDRESS: 45850 306 th Street			
*TOWNSHIP: Pleasant Valley	OWNER CITY: Wakonda			
*RANGE: 52	OWNER STATE: South Dakota			
*SECTION:18	OWNER ZIP: <u>57073</u>			
ACRES: <u>6.71</u>	QUAD NAME:			
OWNER CODE 1: P				
OWNER CODE 2:				
OWNER CODE 3:				
HISTORIC SIGNIFICANCE				
*DOE:	REGISTER NAME:			
*DOE DATE:	MULTIPLE PROPERTY NAME.			
REASON INELIGIBLE:				
	CATEGORY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L			
REFERENCE NUMBER:				
HISTORIC DISTRICT RATING: C or				
PERIOD:				
	CRITERIA 3: A B C D			
	CRITERIA 4: A B C D			
SIGNIFICANCE NOTES:				
OCCUR TO ANOL HOTEO.				

STRUCTURE DETAILS



SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
CURRENT FUNCTION	Vacant	FOUNDATION	Native Rock and	
CURRENT FUNCTION:	vacant	FOUNDATION	poured concrete Steel roofing over	
CURRENT SUBFUNCTION:	Lumber storage	ROOF MATERIAL		
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE		
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM	Balloon framing	
	, ,	STYLE		
OCCUPIED:	No	TYPE		
			2x4 studs, 1x8 #106	
			drop siding and	
ACCESSIBLE.	Yes with	MALLS.	assorted steel	
ACCESSIBLE:	permission	WALLS:	roofing.	
STORIES:	2	SIGNIFICANT PERSON:	Edward Mart	
*DATE OF CONSTRUCTION:	Late 1800's	CULTURAL AFFILIATION:	?	
ALTERED/MOVED NOTES: Original site. Any evidence of horse stalls has been removed. Racks built for				
lumber storage. Roof has been covered with steel roofing. Covered addition out to silo on the South side				
added later. Some of the native rock foundation has been repaired with poured concrete.				
INTERIOR NOTES. One your	of AvA monto and A	v.4 baam ta aummant baylaft flaan m	autially names and The	
INTERIOR NOTES: One row of 4x4 posts and 4x4 beam to support hayloft floor, partially removed. The				
hayloft floor joists were 2x6's. The East wall of center barn is open 2x4 studs with feed trough and milk cow stanchions still in place in the East lean-to. The East part of the center barn had milk cow stanchions, but				
are removed. The West wall of the center barn is 2x4 studs with sheathing up to hayloft floor.				
OTHER NOTES: 2x4 stud walls, 1x8 #106 drop siding on all four walls. Rafters are 2x4's. Windows are				
9" x12"four light. All of the 2x4 studs, 2x4 rafters and 2x6 floor joists are rough sawn cottonwood.				
Both lean-to's on the East and West sides appear to have been built at the same as the barn.				
*PHYSICAL NOTES: Barn is in poor condition.				
	•			
*IITM ZONE:		*DECTRICTED: V	au N	
*UTM ZONE:		*RESTRICTED: Y	OI N	
*UTM EASTING:				
*UTM NORTHING:				










PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 26, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, in center barn, parts of 4x4 posts and 4x4 beam, CAMERA DIRECTION: racks for lumber storage



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 26, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NW, 2x4 rafters, open 2x4 stud

CAMERA DIRECTION: walls in hayloft.





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 26, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW, (7) milk cow stanchions still in place in East lean-

CAMERA DIRECTION: to.





CLAY CO., SD

© Farm & Home Publishers, Ltd.



HISTORY

This farm located in the SE ¼ of Section 18, Pleasant Valley Township, Clay County was homesteaded by Walter Palmer.

The 1894 Clay County Atlas lists Edward Mart as the owner.

The 1912 and 1924 Clay County Atlas lists George F. Groves as the owner.

The 1937 Clay County Atlas lists Northwestern Life Insurance Co. as the owner and Hans & Oren Lewison as the operators (renters).

The 1948 and 1956 Clay County Atlas lists C. M. Olson as the owner.

