

SITE INFORMATION

*SURVEY D	ATE: Aug. 10, 20	12	*ADDRESS: _ 30514 469 th Ave.											
*SURVEYOR: Jim Stone			*COUNTY:	Clay										
			*CITY: Beresford											
LOCATION DESCR	IPTION: South D	Dakota Highway 5), East two mile	es to Gr	eenf	ield	Roa	d, tu	rn le	it				
(North), 12-1/2 mile	es to 306 th Street, to	urn right (East) 1 i	nile to 469 th Av	e., turn	left	(Nor	th) a	bout	7/8 th	mile				
on the right (East)	side.													
LEGAL DESCRIPTI	ION: N 1/4 NW 1/4	13 _ 94_ 51 Garf	ield Twn											
LEGAL DEGOTTI II	14 /2, 1417 /4,	, 10 04 01 Out	icia i wp.											
*QUARTER 1:	NW 1/4		WNER NAME:	Charles J. Jensen										
*QUARTER 2:		OWNE	OWNER ADDRESS:				30514 469 th Ave.							
*TOWNSHIP:	Greenwood	_	OWNER CITY:				Beresford							
*RANGE:	51	OV	VNER STATE:	South Dakota										
*SECTION:	13	_	OWNER ZIP:	57004										
	79.86	_	QUAD NAME:											
OWNER CODE 1:	Р													
OWNER CODE 2:														
OWNER CODE 3:														
HISTORIC SIGN	IFICANCE													
*DOE:			REGISTER NA	ME:										
*DOE DATE:														
REASON INELIGIBLE:														
		-												
			CATEGORY:											
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L											
DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L											
REFERENCE	E NUMBER:													
HISTORIC DISTRIC	CT RATING: C o	r NC	CRITE	RIA 1:	Α	В	С	D						
	PERIOD:		CRITE	RIA 2:	Α	В	С	D						
			CRITE	RIA 3:	Α	В	С	D						
			CRITE	RIA 4:	Α	В	С	D						
SIGNIFICANCE NO	TFS:													
S.S.M. ISANOL NO														


STRUCTURE DETAILS



SHPO ID:										
*PROPERTY NAME:		<u>-</u> -								
OTHER NAME:										
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete							
			Asphalt shingles							
CURRENT CURRUNCTION.	Ct	DOOF MATERIAL.	over cedar							
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:								
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Round gothic							
HISTORIC SUBFUNCTION:	Hay and grain stora	ge STRUCTURAL SYSTEM:	Balloon framing							
		STYLE:	Round gothic roof barn							
OCCUPIED:	Voc	TYPE:								
00001 ILD.	103	1112.	Brick walls 8' high,							
			2x6 walls in hay							
			loft gable ends w/							
ACCECCIDI E	Yes with	WALL C.	shtg. & ½"x6"							
ACCESSIBLE:	permission	WALLS:	cedar lap siding							
STORIES:	2	SIGNIFICANT PERSON: R	ichard Jensen							
*DATE OF CONSTRUCTION:	1941 ?	CULTURAL AFFILIATION:	Danish							
										
ALTERED/MOVED NOTES:	Original site. All b	out one horse stall and milk cow sta	anchions removed.							
7' x 34' lean-to added on the North side. Some of the 4x6 posts have been replaced with pipe posts.										
			р.ро роско							
INTERIOR NOTES: Has thre	e rows 4x6 posts and	d (3) 2x10's for beam. 2x10 floor jo	ists. Two 8' x 16'							
and 4'x8' granaries is still in p	place in hayloft. 8"x	10" (3 wide and 2 high) six light wi	ndows on first floor							
and 4" x 24" four light window	ws in hayloft.									
OTHER NOTES: Walls are 1	2" x 5" x 8" brick 8' h	nigh with 2x6 walls with sheathing	and ½"x6" cedar lap							
siding on the hayloft gable en	nds. Metal cupola or	roof. Enclosed walkway from silo	on the North into							
barn. 12' x 16 milk room in th	e SW corner, had a l	arge milk cooler which is gone								
*PHYSICAL NOTES: Barn is	s in very good condi	ion.								
*UTM ZONE:		*RESTRICTED: Y o	r N							
*UTM EASTING:										
*UTM NORTHING:										

* = REQUIRED FIELD









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: Aug. 10, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: Aug. 10, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: Aug. 10, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: Aug. 10, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: ___ Jim Stone


Aug. 10, 2012

ROLL NUMBER: PHOTO NUMBER:

5

First floor, looking West, post & beam and horse

CAMERA DIRECTION: stall



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: Aug. 10, 2012

ROLL NUMBER: PHOTO NUMBER:

Hay loft, looking SE, corner of granaries on

CAMERA DIRECTION: South wall.






PHOTOGRAPHER: DATE OF PHOTO: Aug. 10, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER: 7

Hayloft, looking West,
CAMERA DIRECTION: granaries on South wall






PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 10, 2012 PHOTOGRAPHER:

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking East, 5

CAMERA DIRECTION: ply rafters







HISTORY

This farm located in the N ½ of the NW ¼ in Section, Garfield township, clay County was homesteaded by Erik Svedborg.

The 1894, 1901, 1912 and 1924 Clay County Atlas lists Nis Stenholt as the owner.

The 1937 Clay County Atlas lists Richard Jensen as the owner.

The 1948 Clay County Atlas lists P. L. O'Connor as the owner.

The 1956 Clay County Atlas lists Dick Jensen as the owner.

