

SITE INFORMATION

*SURVEY DATE:	May 7, 20	13	*ADDRESS:	29831	29831 University Road						
*SURVEYOR: Jim Stone			*COUNTY:	′: Clay							
			*CITY:	Cente	ervil	le					
LOCATION DESCRIPTION:	From Ver	million, interse	ction of South [Dakota I	High	way	50 b	i-pas	s an	d	
University Road, North 19-3/4	miles, pa	st 299 th Street,	on the right (Ea	st) side) .						
LEGAL DESCRIPTION: NW	1/4, 8 – 9	95 – 51 Glenwo	od Twp.								
*QUARTER 1: NE 1/4		c	Susan & Robert P. Walsh								
*QUARTER 2:				RESS: 47844 County road 1 B					,,,,		
*TOWNSHIP: Glenwoo	nd	01111	Elk Point								
*RANGE: 51		0	South Dakota								
*SECTION: 8		_	57025								
ACRES: 157.89	_		QUAD NAME:								
OWNER CODE 1: P											
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGNIFICANCI	E										
*DOF:	_		REGISTER NA	ME-							
*DOE: *DOE DATE:											
*DOE DATE: REASON INELIGIBLE:				O. L.			_				
		-									
				C	ATE	GOF	RY:				
NOMINATION STATUS	•		SIGNII	FICANC	E LI	EVEL	. 1:	N	S	L	
DATE LISTED		_	SIGNII	FICANC	E LI	EVEL	2:	N	S	L	
REFERENCE NUMBER	:										
HISTORIC DISTRICT RATING	C or	NC	CRITE	RIA 1:	Α	В	С	D			
PERIOD			CRITE	RIA 2:	Α	В	С	D			
			CRITE	RIA 3:	Α	В	С	D			
			CRITE	RIA 4:	Α	В	С	D			
SIGNIFICANCE NOTES:											


STRUCTURE DETAILS



SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION: Vacant			FOUNDA	Poured concrete			
				Steel over cedar			
CURRENT SUBFUNCTION:	Vacant		ROOF MATE	shingles			
HISTORIC FUNCTION:	Livestock barn		ROOF SH	IAPE:	Gable		
HISTORIC SUBFUNCTION:	Hay and grain sto	rage	STRUCTURAL SYS	STEM:	Balloon framing		
			S	Gable roof barn			
OCCUPIED:	Yes		-	Horse barn			
					2x4& 2x6 studs, 1x6		
ACCESSIBLE:	Yes with permission		WALLS:		#106 drop siding,		
ACCESSIBLE.	permission		WALLS.		some steel		
0700150	•	•	GNIFICANT PERSON:	•	. Vistan Batanaan		
					n Victor Peterson		
*DATE OF CONSTRUCTION:	CONSTRUCTION: 1920's CULTUR				Swedish		
ALTERED/MOVED NOTES:	Original site.						
Lean-to added on the North.	1-1/4" x 26" corrug	ated st	eel roofing applied vert	ically c	on north wall.		
Cupola is gone. 1-1/4" x 26" o	orrugated galvaniz	ed ste	el roofing applied on the	e North	slope of the roof		
including the lean-to.							
NITERIOR NOTES TI		_			- 1 (1 1 1 1		
INTERIOR NOTES: The orig			•		•		
2x6's for the hayloft floor. Five							
cow stalls are still in place. A pen are still in place in the lea		і ріасе	. A 6 x 14 granary, nay	reed r	acks and a 10 x 14		
OTHER NOTES: 2x4 stud w		Ov6 etu	d walls in the original h	arn wi	th 1v6 #106 drop		
siding. Rafters are 2x6's on				•	•		
down to floor, 4' O. C. 6x6 sil							
except two 8"x10" four light of			9"X 12" four light on th	e East	waii.		
*PHYSICAL NOTES: Barn is	s in poor condition.	•					
*UTM ZONE:			*RESTRICTED:	Υn	r N		
				. 0			
*UTM EASTING:							
*UTM NORTHING:							

* = REQUIRED FIELD









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 7, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 7, 2013

ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May 7, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May 7, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 7, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking South, stalls on South wall, may have been for

CAMERA DIRECTION: young horses or mules.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 7, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, double horse stall on

CAMERA DIRECTION: North wall





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 7, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking West, track rail for manure

CAMERA DIRECTION: bucket



PHOTOGRAPHER: DATE OF PHOTO:

May 7, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, initials carved in the wall

CAMERA DIRECTION: of the granary.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 7, 2013

ROLL NUMBER: PHOTO NUMBER:

Looking SW in North lean-to, note hay feed rack & 1x6 drop siding on North wall of original

CAMERA DIRECTION: barn



PHOTOGRAPHER: **DATE OF PHOTO:**

Jim Stone May 7, 2013

ROLL NUMBER: PHOTO NUMBER:

10

Hayloft, looking SW, 2x6 rafters and 2x6 brace 4' O. C. from top of wall

CAMERA DIRECTION: down to floor.





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone May 7, 2013

ROLL NUMBER: **PHOTO NUMBER:**

Hayloft, looking West, 2x6 rafters and hole

CAMERA DIRECTION: where cupola was.





© Farm & Home Publishers, Ltd. 23 CLAY CO., SD



HISTORY

This farm located in the NW ¼ of Section 8, Glenwood Township, Clay County, was homesteaded by Aaron Noble.

The 1894 and 1901 Clay County atlas lists S. M. Peterson as the owner. Name was Swen Mangus Peterson as per granddaughter Cheryl Walsh.

The 1912, 1924, 1937, 1948 and 1956 Clay County atlas lists S. V. Peterson as the owner, but the 1948 Clay County Atlas lists S. Victor Peterson as the owner. Name was Swen Victor Peterson as per granddaughter Cheryl Walsh. Swen Victor Peterson raised and trained horses and mules.

