

```SITE INFORMATION

*SURVEY DATE: _____ *SURVEYOR:

<u>May 29, 2013</u> Jim Stone *ADDRESS: <u>30904 460th Ave.</u> *COUNTY: <u>Clay</u> *CITY: <u>Vermillion</u>

LOCATION DESCRIPTION:From Vermillion, the intersection of South Dakota Highway 50 bi-pass andSouth Dakota Highway 19, North 8 miles to 309th Street, turn left, (West) about 2-1/2 miles to 460th Ave.,

turn left (South) about 1/8 mile on the left (East) side.

LEGAL DESCRIPTION: Lot 2, NW ¼, 4– 93 – 52 Spirit Mound Twp.

*QUARTER 1:	NW 1/4	OWNER NAME:	Stanley M. Peterso	n		
*QUARTER 2:		OWNER ADDRESS:	804 Carlton Circle			
*TOWNSHIP:	Spirit Mound	OWNER CITY:	Vermillion			
	52	OWNER STATE:				
*SECTION:	4	OWNER ZIP:	57069			
ACRES:	71.01	QUAD NAME:				
OWNER CODE 1:	Р					
OWNER CODE 2:						
OWNER CODE 3:						
HISTORIC SIGN						
	IFICANCL					
	OE:		ME:			
*DOE DA	TE:	MULTIPLE PR	OPERTY NAME:			
REASON INELIGIB	JLE:					
			CATEGORY:	-		
NOMINATION STATUS:			FICANCE LEVEL 1:			
DATE LISTED:		SIGNI	FICANCE LEVEL 2:	Ν	S	L
	E NUMBER:					
HISTORIC DISTRIC	CT RATING: C or		ERIA1: A B C			
	PERIOD:		ERIA 2: A B C			
			ERIA 3: A B C			
		CRITE	ERIA 4: A B C	D		
SIGNIFICANCE NO	TES:					
STRUCTURE DE	FTAILS					



SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
CURRENT FUNCTION:	Vacant	FOUNDA	TION:	Poured concrete
CURRENT SUBFUNCTION:	Storage	ROOF MATE	RIAL:	Steel roofing over cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SH	IAPE:	Gambrel roof
HISTORIC SUBFUNCTION:	Hay and grain storage	je STRUCTURAL SYS	STEM:	Balloon framing
		S	TYLE:	Gambrel roof barn
OCCUPIED:	Yes	-	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:		2x6 studs, 1x6 #106 drop siding
STORIES:	2	SIGNIFICANT PERSON:	Sa	amuel Peterson
*DATE OF CONSTRUCTION:	Early 1900's	CULTURAL AFFILIATION:		Norwegian

ALTERED/MOVED NOTES: <u>Original site.</u> Steel roofing over the cedar shingles. 18' x 40' lean-to added on the East side. A 34' x 60' addition, built in 1962, on the South end. It has 8" concrete block walls

7' high on a 12" high poured concrete foundation for 8' walls. This addition was for dairy cows. There is a feed trough on each side of the feed alley with milk cow stanchions on the East and West sides. Feed alley

is extended to the silo just south of the addition. This building replaced a clay tile building built in the early 1900's, that a storm destroyed in 1962.

INTERIOR NOTES: Three rows of 4x6 posts and 4x6 beams. 2x8 floor joists for the hayloft floor.

One double horse stall is still in place. Appears to have had 5 double horse stalls on the West side. Feed trough in the feed alley for cows on the East side. 18' x 40' lean-to has a 10' x 10' milk room in the SW corner. The balance of the lean-to appears to have been used as a loafing barn.

OTHER NOTES: 2x6 studs with 1x6 #106 drop siding on the original barn and the lean-to. 2x6 rafters

with 4x6 posts 10' O. C. in the hayloft and a 4x6 beam to support the hip. 2x6 rafters on the lean-to.


2x6 rafters and 2x8 joists in the South addition. Double in swing doors for the hayloft door.

9"x12" four light windows on the first floor and four 4"x24" four light windows in the hayloft.

*PHYSICAL NOTES: Barn is in poor condition. The 34' x 60' addition is in good condition.


*UTM ZONE:	*RESTRICTED:	Y	or	Ν
*UTM EASTING:				
*UTM NORTHING:				





* = REQUIRED FIELD






* = REQUIRED FIELD














PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 29, 2013




CAMERA DIRECTION: <u>gran</u>ary in NE corner.

5 First floor, looking NE, feed trough in feed alley,




May 29, 2013





PHOTOGRAPHER: _____ DATE OF PHOTO: ROLL NUMBER: PHOTO NUMBER:

First floor in South addition, looking SE, concrete feed trough and framing for milk cow stanchions on East side.






PHOTOGRAPHER: DATE OF PHOTO:	Jim Stone May 29, 2013	CAMERA DIRECTION	9 Hayloft, looking North, double inswinging doors for hayloft doors
		CAMERA DIRECTION:	doors.
PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	May 29, 2013	PHOTO NUMBER:	10 Hayloft, looking SW into
			attic of the South

6' O. C. supporting the CAMERA DIRECTION: center of rafters.

addition, note 4x4 posts







HISTORY

This farm, located in the N¹/₂ of the NW ¹/₄ of Section 4, in Spirit Mound Township, was homesteaded, by Osman I. Mortvedt.

- The 1894 Clay County Atlas lists B. J. Mortvedt as the owner.
- The 1901 Clay County Atlas lists Mrs. B. J. Mortvedt as the owner.

The 1912 and 1924 Clay County Atlas lists Samuel Peterson as the owner.

The 1937 Clay County Atlas lists C. E. Prentis as the owner.

The 1948 Clay County Atlas lists R. P. Munger as the owner.

The 1956 Clay county atlas lists S. B. Munger as the owner.

