

SITE INFORMATION

*SURVEY DATE: July 2, 2	2012 *ADDRESS	45719 Jetly Park Street			
*SURVEYOR: Jim Sto	one *COUNTY	Clay			
	*CITY	: Vermillion			
	m intersection of South Dakota Higl				
	es to 459 th Ave., turn left (South) ab	out 200 feet and turn right (West),			
About 3/4 mile on the left (South)	side.				
·		NW ¼, NE ¼, SW ¼ & E ½, NE ¼, NW			
1/4, SW 1/4 & Sealy Tract 1, 36 – 93	– 53 Meckling Twp.				


*QUARTER 1: SW 1/4		John F. & Agnes F. Sealy			
*QUARTER 2:		45719 Jetly Park Street			
*TOWNSHIP: Meckling		: Vermillion			
*RANGE: <u>53</u>	OWNER STATE:				
*SECTION: 36	OWNER ZIP:	57069			
ACRES: 131.35 OWNER CODE 1: P	QUAD NAME:				
	n.				
	P				
OWNER CODE 3: F S L F	P				
HISTORIC SIGNIFICANCE					
*DOE:	DECISTED N	AME.			
*DOE: REGISTER NAME: *DOE DATE: MULTIPLE PROPERTY NAM					
REASON INELIGIBLE:	WIGETIFEE FF	OF ENTITIONIE.			
REASON INCLIGIBLE.					
		CATEGORY:			
NOMINATION STATUS:	SIGN	FICANCE LEVEL 1: N S L			
DATE LISTED:		FICANCE LEVEL 2: N S L			
REFERENCE NUMBER:		TOANGE ELVEE 2. N O E			
HISTORIC DISTRICT RATING: 0		ERIA 1: A B C D			
		ERIA 2: A B C D			
1 21(10).		ERIA 3: A B C D			
		ERIA 4: A B C D			
	Skiii.	ENIA T. A B O B			
SIGNIFICANCE NOTES: Sophia Demann					
_					



STRUCTURE DETAILS				
SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
3111 <u>21111</u> 31112.				
CURRENT FUNCTION:	Farm machinery shop	FOUNDATION:	Poured concrete	
CURRENT SUBFUNCTION:	Auto repair	ROOF MATERIAL:	Asphalt over cedar shingles	
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel	
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing	
		STYLE:	Gambrel roof barn	
OCCUPIED:	Yes		Livestock barn	
	Yes with		2x6, 1x6 #106 drop	
ACCESSIBLE:	permission	WALLS:	siding	
STORIES:	: 2 S	SIGNIFICANT PERSON:	Sophia Demann	
*DATE OF CONSTRUCTION:		LTURAL AFFILIATION:	German	
ALTERED/MOVED NOTES: Original site. Hayloft floor raised to 14'. All stanchions, horse stalls and				
granary have been removed. Walls and Ceiling have been insulated and lined. 16'x12' overhead door				
installed in the North wall. 32' x 32' addition added to the South side with a gable roof. South wall of				
original barn partially removed to make a 32' x 64' shop. 18' x 32' lean-to added to the East side.				
INTERIOR NOTES: Had 6x6 posts and 6x6 beams to support hayloft floor. Joists were 2x10.				
The 6x6 posts and 6x6 beams were rough sawn.				
OTHER NOTES: Windows were 8"x10" four light. 2x6 stud walls with 1x6 #106 drop siding. Rafters and				
Bracing are 2x6. Rafter bracing left intact when floor joists were raised to 14'. Shop is heated with a				
large wood burning stove. West addition is used as shop also.				
*PHYSICAL NOTES: Barn is in very good condition.				



SKETCH MAP







PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 2, 2012

ROLL NUMBER:
PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: _____
DATE OF PHOTO:

Jim Stone July 2, 2012 ROLL NUMBER:

PHOTO NUMBER:

Looking NW, SE corner,

32'x32' addition on the

CAMERA DIRECTION: South

* = REQUIRED FIELD





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 2, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 2, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 2, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking South, original 6x6 beam with 6x6 beam used as a

CAMERA DIRECTION: post



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: July 2, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, CAMERA DIRECTION: original rafter bracing.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 2, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking South,

CAMERA DIRECTION: lower rafter bracing



PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone July 2, 2012

ROLL NUMBER:


PHOTO NUMBER:

CAMERA DIRECTION: upper/ hip rafter bracing

Hayloft, looking South,



MECKLING TWP





HISTORY

This farm located in the SE ¼ of Section 35, Meckling Township, Clay County was homesteaded by Fredrick Branson.

The 1894 and 1901 Clay County Atlas lists Albert M. Edgerton as the owner.

The 1912 and 1924 Clay County Atlas lists Fred L. Demann as the owner.

The 1937 Clay County Atlas lists Albert M. Edgerton as the owner.

The 1948 and 1956 Clay County Atlas lists Caroline Sealey as the owner.

Sophia Demann purchased the Bergland farm SE ¼ of Section 36 in Meckling Township in 1909 and the SW ¼ of Section 36 in Meckling Township in 1915. The SW ¼ in Section 36 is now the John Sealy place.

Fred and Sophia Demann had two children Caroline and Delores. Caroline married Fred Sealy. John Sealy is the son of Caroline and Fred.

Delores married Carl Berland Sr. Their children are Madalenn, Carl Jr (Dutches) and Melvin.

