

SITE INFORMATION

* = REQUIRED FIELD

*SURVEY DATE: November 4, 2012

*ADDRESS: 46824 Burbank Road

*SURVEYOR: Jim Stone

*CITY: Burbank

*COUNTY: Clay

LOCATION DESCRIPTION: From intersection of Main Street and Dakota Street in Vermillion, South about ¹/₄ mile to Burbank Road, turn left (East), fallow This road about 3-1/4 miles, turn right (South) at address 466824 Burbank Road.

LEGAL DESCRIPTION: Olson Tract 1, NE ¹/₄, 28 – 92 – 51 Fairview Twp.

*QUARTER 1:	NE 1/4		0\	WNER NAME:	Steve	Matt	es					
*QUARTER 2:			OWNE	R ADDRESS:	46653	Burl	bank	roa	d			
*TOWNSHIP:	Fairview		C	WNER CITY:	Burba	nk						
*RANGE:	51		OM	NER STATE:	South	Dak	ota					
*SECTION:	28			OWNER ZIP:	57010							
ACRES:	5.34			QUAD NAME:								
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGN												
*D(DE:			REGISTER NA	ME:							
*DOE DA	TE:			MULTIPLE PR	OPERT	Y NA	ME:					
REASON INELIGIB												
					С	ATE	GOF	łY:				
NOMINATIO	N STATUS:			SIGNI	FICANC	ELE	VEL	. 1:	Ν	S	L	
				SIGNI	FICANC	ELE	VEL	. 2:	Ν	S	L	
REFERENCE												
HISTORIC DISTRIC	T RATING:	C or	NC	CRITE	ERIA 1:	Α	В	С	D			
	PERIOD:			CRITE	ERIA 2:	Α	В	С	D			
				CRITE	ERIA 3:	Α	В	С	D			
				CRITE	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NO	TES:											
STRUCTURE DE	TAILS											



SHPO ID:			
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete foundation
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Steel roofing over cedar shingles
HISTORIC FUNCTION:		ROOF SHAPE:	
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Gambrel roof barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x6 stud with 1x6 #106 drop siding
STORIES:	2	SIGNIFICANT PERSON: <u>Star</u>	nley J. Ketchem
*DATE OF CONSTRUCTION:	About 1900 to 1910	CULTURAL AFFILIATION:	?

ALTERED/MOVED NOTES: Original site. Milk cow stanchions have been removed. Lean-to's added to the North and East sides. North side of roof on original barn has been covered with steel roofing.


INTERIOR NOTES: <u>Has one row of 2x6 studs in 8' from North wall of original barn, 12' in, one row 8x8</u> beam and 6x6 posts and in 7' from The South wall one row of 6x6 beam and 4x6 posts. 2x8 floor joists. 2x10 floor joists with 2x10 planks for floor in the main barn.

OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding. Rafters are 2x6 with sheathing and cedar shingles. Steel over cedar shingles on the North side of main barn. Lean-to's have 2x8 rafters 4' O.C. with 2x4 purlins 2' O.C. and steel roofing. All of the 2x6's, 2x8's,2x10's, 4x6's, 6x6's and 8x8's are rough sawn cottonwood. 2x6 studs, 2x6 plates and 2x8 rafters in additions are milled lumber. Very elaborate wood cupola. 8"x10" four light windows in original barn. 9"x12" four light windows in additions. *PHYSICAL NOTES: Barn is in fair condition. Needs some rafters and roof sheathing replaced and new roofing on South side of original barn. Roof has leaked enough to start rotting out the hayloft floor below the worse holes. Has a double pinwheel barn quilt on the East gable end. Mrs. Steve Mattes picked out the pattern and the colors. Her sister painted it as a wedding present.


*UTM ZONE:	*RESTRICTED:	Y	or	Ν
*UTM EASTING:				
*UTM NORTHING:				



SKETCH MAP







WEST ELEVATION

* = REQUIRED FIELD

4





PHOTOGRAPHER:Jim StoneROLL NDATE OF PHOTO:November 4, 2012PHOTO N

 ROLL NUMBER:

 PHOTO NUMBER:

 1

 CAMERA DIRECTION:

 Looking NE, SW corner




PHOTOGRAPHER: Jim Stone DATE OF PHOTO: November 4, 2012


ROLL NUMBER: PHOTO NUMBER: 2 CAMERA DIRECTION: Looking NW, SE corner






PHOTOGRAPHER: Jim Stone **ROLL NUMBER:** DATE OF PHOTO: November 4, 2012 PHOTO NUMBER: 3







PHOTOGRAPHER: DATE OF PHOTO: November 4, 2012

ROLL NUMBER: PHOTO NUMBER: 4 CAMERA DIRECTION: Looking SE, NW corner






PHOTOGRAPHER: DATE OF PHOTO: November 4, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

5 First floor, looking East, North addition, 2x8 rafters, 2x4 purlins and

CAMERA DIRECTION: steel roofing



CAMERA DIRECTION: posts





PHOTOGRAPHER: Jim Stone November 4, 2012 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION:

7 First floor, original barn, looking NW, double horse stall




PHOTOGRAPHER: DATE OF PHOTO: November 4, 2012

ROLL NUMBER: PHOTO NUMBER:

8 First floor, original barn, looking East, 2x6 stud CAMERA DIRECTION: wall in 8' from North wall

* = REQUIRED FIELD






PHOTOGRAPHER:	Jim Stone	
DATE OF PHOTO:	November 4, 2012	

ROLL NUMBER: PHOTO NUMBER:

9 Hay loft, looking East, 4x6 posts and (2) 2x6's for beam to support hip CAMERA DIRECTION: and 2x6 bracing 8' O.C.





* = REQUIRED FIELD

10



HISTORY

This farm located in the NE ¼ of Section 28, Fairview Township, Clay County was homesteaded by Jerome Garyend.

The 1894 Clay County Atlas lists H. J. Ufford as the owner.

The 1901, 1912, 1924 1937 and 1948 Clay County Atlas lists Stanley J. Ketchem as the owner.

The 1956 Clay County atlas lists B. K. Olson as the owner.

Doris Olson (a widow) sold the building site to the present owners.

