

SITE INFORMATION

*SURVEY DATE: Febru	uary 2, 2012	*ADDRESS:	31228 S	D Hig	hway	<i>/</i> 19		
*SURVEYOR: _Jim S	Stone	*COUNTY:	Clay					
			Vermilli					
LOCATION DESCRIPTION: <u>F</u> 4 – ¾ miles, on the right (East)	aida	of Highway 50 bi-						
LEGAL DESCRIPTION: Brem	er Tract 1, SW ¼, NI	E ¼, Exc. Lot H1, 23	3 - 93 - 52	2, Spir	it Mc	ound	Twp.	
*QUARTER 1: <u>NE 1/4</u>		OWNER NAME:	William F	Ranne	y III			
*QUARTER 2:		WNER ADDRESS:	31228 SE) High	way	19		
*TOWNSHIP: Spirit Mour		OWNER CITY:	Vermillio	n				
*RANGE: <u>52</u>		OWNER STATE:	South Da	akota				
*SECTION: 23		OWNER ZIP:	57069					
ACRES: 9		QUAD NAME:						
OWNER CODE 1: P								
OWNER CODE 2: F S L								
OWNER CODE 3: F S L	Р							
HISTORIC SIGNIFICANCE								
*DOE:		REGISTER NA	ME:					
*DOE DATE:								
REASON INELIGIBLE:								
		<u>-</u>						
			_	rEGO				
NOMINATION STATUS:			FICANCE					_
DATE LISTED:		SIGNII	FICANCE	LEVEL	_ 2:	N	S	L
REFERENCE NUMBER:		-						
HISTORIC DISTRICT RATING:	C or NC		RIA 1: A		С	D		
PERIOD:		=	RIA 2: A		С	D		
			RIA 3: A		С	D		
		CRITE	RIA 4: A	В	С	D		
SIGNIFICANCE NOTES: Rese	earch by William Ra	nney III. He has fo	und that tl	ne low	a His	storic	: Soc	eiety
classifies this style of barn as a	-	-						
Horse stalls are perpendicular								
Most barns have the stalls perp								




STRUCTURE DETAILS			
SHPO ID:			
*PROPERTY NAME:	Stephen Oleson barn		
OTHER NAME:			
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete
CURRENT SUBFUNCTION:		ROOF MATERIAL:	Cedar shingles
HISTORIC FUNCTION:	Livestock barn & dairy barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	
HISTORIC SUBFUNCTION.	nay storage	STRUCTURAL STSTEM. STYLE:	
		SITLE.	English Livestock
OCCUPIED:	Yes	TYPE:	_
			2x6 with 1x6 #106
ACCESSIBLE:	Yes	WALLS:	drop siding
ATAP: = 4	•	OLONIELO ANT DEDOCAL CO	
STORIES:	2 Early	SIGNIFICANT PERSON: Stepl	nen Oleson
*DATE OF CONSTRUCTION:		CULTURAL AFFILIATION: No	orwegian
ALTERED/MOVED NOTES:	Original site. Original	y had a rock foundation with 6x0	S sill. Foundation
-		on. Many of the original rock we	
		has been poured with gutters fo	
		noved. 14' x 28' lean to built late	
		or have been painted white for a	
		or hayloft floor. 2x6 walls 12' on	
1x6 #106 wood siding. Lean	to has 2x6 walls 7' hig	h on the West with sheathing an	d ½ x 8" cedar siding.
OTHER NOTES: 8" x 10" for	ur light windows. One	of these four light windows is ar	gled in the North
gable to look like a diamond	window.		
*PHYSICAL NOTES: Barn	is in good condition. V	Vindows are gone and doors nee	d repair.
Owner is thinking about insta	Illing steel roofing on r	oof. Cedar wood shingles do no	t leak yet but are
starting to look rough.			
*UTM ZONE:		*RESTRICTED: Y	or N



*UTM EASTING:	

SKETCH MAP







PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: February 2, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 2, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 2, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: February 2, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: In lean to, looking NE





PHOTOGRAPHER: DATE OF PHOTO: February 2, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: In lean to, looking SE



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: February 2, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: First floor, looking NE





PHOTOGRAPHER: Jim Stone ROLL NUMBER: 7

DATE OF PHOTO: February 2, 2012 PHOTO NUMBER: 7

CAMERA DIRECTION: First floor, looking SW



PHOTOGRAPHER: Jim Stone ROLL NUMBER: BHOTO NUMBER: B CAMERA DIRECTION: Hayloft, looking North






PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: February 2, 2012 PHOTO NUMBER:

CAMERA DIRECTION: Hayloft, looking North





SPIRIT MOUND **SECTION 2**

1. Allen, SECTION 3 SECTION 6

1. Poeschi, Jerome 9 **SECTION 10** 1. Blatchford, Larry 8 SECTION 11 1. Gilbertson, Roge

SECTION 15

1. Vogel, Scot 10

2. Armstrong, Mary 7

3. Brodsky, Curtis 5

SECTION 22 SECTION 23 Ranney III, William 9 2. Nau, Patricia 6 SECTION 24 SECTION 26 **SECTION 27** Morey, Michael 15
 SECTION 30
 Becker, Marlin 6 SECTION 31 Bosse, Jessi
 Bye, Brook 8 1. Johnson SECTION 35 SECTION 36

1. McCart, Darlene 10

© Farm & Home Publishers, Ltd.

36

CLAY CO., SD



HISTORY

This farm located in the NE ¼ of section 23, Spirit Mound Township, Clay County was homesteaded by Stephen Oleson.

The 1894 and 1912 Clay County Atlas lists Stephen Oleson as the owner.

The 1924 Clay County Atlas lists Essle Bliegel Meyer as the owner.

The 1937 Clay County Atlas lists Federal Land Bank as the owner.

The 1948 and 1956 Clay County Atlas lists L. P. Trudeau as the owner.

Stephen Oleson was born to Ole and Christine Oleson on Dec. 27, 1818 in Voss, Norway in the Bergen Stift area on the farm Slen. His wife, Ingeborg was born at Vlnik, Norway on Sept. 14, 1828. They were married in the early 1850's and to this union a son: Ole was born Dec 13, 1855.

In 1857, they sailed for America and settled in Kendell County, II., where three children were born. They re-settled in Benton County, Iowa where two more children were born.

Coming finally to Dakota Territory in 1868 they homesteaded in Spirit Mound Township where the last two children, bringing the total to eight, were born. Ole grew into an adventurous spirit the spring of 1873, at the age of 18, to enlist in General Custer's 7th Calvary. They were headquartered in Yankton at this time. Later he joined the Black Hills River Boat Co. as a steam boatman, working on the steamboat between Sioux City, Iowa and Bismarck, North Dakota.

Name was changed from Oleson to Olson. Date of change is unknown.

Source - Research by William Ranney III