

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SITE INFORMATION

*SURVEY DATE: March 7, 2013 *ADDRESS: 31015 470th Ave.
*SURVEYOR: Jim Stone *COUNTY: Clay
*CITY: Beresford

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 East 2 miles to Greenfield road, Turn left (North) 7-1/2 miles to 311th Street, turn right (East) 2 miles to 470th Ave, turn left (North) about 7/8 mile, on the left (West) side

LEGAL DESCRIPTION: Blackburn Tract 1 in NE ¼, NE ¼, 12 – 93 – 51 Prairie Center Twp.

*QUARTER 1: NE 1/4
*QUARTER 2: _____
*TOWNSHIP: Prairie Center
*RANGE: 51
*SECTION: 12
ACRES: 4.6

OWNER NAME: Terry L. Corner
OWNER ADDRESS: P. O. Box 1315
OWNER CITY: Valrico
OWNER STATE: Florida
OWNER ZIP: 33595
QUAD NAME: _____

OWNER CODE 1: P
OWNER CODE 2: _____
OWNER CODE 3: _____

HISTORIC SIGNIFICANCE

*DOE: _____
*DOE DATE: _____
REASON INELIGIBLE: _____

REGISTER NAME: _____
MULTIPLE PROPERTY NAME: _____

NOMINATION STATUS: _____
DATE LISTED: _____
REFERENCE NUMBER: _____
HISTORIC DISTRICT RATING: C or NC
PERIOD: _____

CATEGORY: _____
SIGNIFICANCE LEVEL 1: N S L
SIGNIFICANCE LEVEL 2: N S L

CRITERIA 1: A B C D
CRITERIA 2: A B C D
CRITERIA 3: A B C D
CRITERIA 4: A B C D

SIGNIFICANCE NOTES: _____

STRUCTURE DETAILS

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SHPO ID: _____
 *PROPERTY NAME: _____
 OTHER NAME: _____

CURRENT FUNCTION:	<u>Horse shelter</u>	FOUNDATION:	<u>Poured concrete</u>
CURRENT SUBFUNCTION:	<u>Vacant</u>	ROOF MATERIAL:	<u>Steel roofing over cedar shingles</u>
HISTORIC FUNCTION:	<u>Livestock barn</u>	ROOF SHAPE:	<u>Gable</u>
HISTORIC SUBFUNCTION:	<u>Hay storage</u>	STRUCTURAL SYSTEM:	<u>Balloon framing</u> <u>Western feeder</u>
		STYLE:	<u>barn</u>
OCCUPIED:	<u>Yes</u>	TYPE:	<u>Livestock barn</u> <u>2x4 & 2x6 studs,</u> <u>1x6 #106 drop</u> <u>siding</u>
ACCESSIBLE:	<u>Yes with permission</u>	WALLS:	

STORIES: 2 SIGNIFICANT PERSON: Swen B. Swenson
 *DATE OF CONSTRUCTION: About 1910 CULTURAL AFFILIATION: Swedish

ALTERED/MOVED NOTES: Original site. Any evidence of horse stalls and milk cow stanchions has been removed. Roof has been covered with steel roofing. Any posts and beams in the center part of barn has been removed.

INTERIOR NOTES: Double 4x6's have been added in the center part of the barn to support the center of the floor joists. A 10" pole has been added perpendicular under the double 4x6's. This pole is supported on each end with 10" poles in the wall on each side of the center part of the barn. The floor joists for the hayloft floor are 2x8's.

OTHER NOTES: 2x4 stud walls on the North and South walls and 2x6 stud walls on the North and South walls of the center part of the barn and 2x6 stud walls the East and West gable end walls with 1x6 #106 drop siding. The rafters are 2x6's. The windows are 8"x10" four light. All of the 2x4 studs, 2x6 studs and rafters and 2x8 floor joists are rough sawn cottonwood.


*PHYSICAL NOTES: Barn is in good condition. Needs some siding repair.

*UTM ZONE: _____ *RESTRICTED: Y or N
 *UTM EASTING: _____
 *UTM NORTHING: _____

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**

SKETCH MAP



* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 5

CAMERA DIRECTION: First floor, looking NW, double 4x6's and 10" beam supporting the center of the 4x6's.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 6

CAMERA DIRECTION: Hayloft, looking NW, 93" high, 2x6 wall in hayloft.

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 7


CAMERA DIRECTION: Hayloft, looking SW,
South 93" stud wall in
hayloft .

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



T-93-N PRAIRIE CENTER DIRECTORY R-51-W

(Residents - Owners or Renters)



* = REQUIRED FIELD

HISTORY

This farm located in the NE ¼ of Section 12, Prairie Center Township, Clay County was homesteaded by Henry Staley.

The 1894 Clay County atlas lists S. B. Benson as the owner.

The 1901 and 1912 Clay County Atlas lists Swen B. Swenson as the owner. Swen B. Swenson homesteaded the NW1/4 of Section 12. He must have sold that and bought the NE ¼ of Section 12.

The 1924 and 1937 Clay County Atlas lists Swen W. Swenson as the owner.

The 1948 and 1956 Clay county Atlas lists Lyman Swenson as the owner.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**

