

SITE INFORMATION

*SURVEY DATE: February 5, 2013 *ADDRESS: 30248 Colfax Ave. *SURVEYOR: Jim Stone *COUNTY: Clay

*CITY: Centervile

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 15 miles to 302nd Street, turn right (East) 1/2 mile to Colfax Ave., turn South about ¹/₂

mile, on the East side. LEGAL DESCRIPTION: Lot 2 Adamson's Addn, W ½, NE ¼ & W ½, SE 1/4, 35 – 95 – 52 Riverside Twp.

*QUARTER 1:	SE ¼ & NE 1/4	OWNER NAME:	Sharon Deeb
*QUARTER 2:		OWNER ADDRESS:	30248 Colfax Ave.
*TOWNSHIP:	Riverside	OWNER CITY:	Centerville
*RANGE:	52	OWNER STATE:	South Dakota
*SECTION:	35	OWNER ZIP:	57014
ACRES:	56.20	QUAD NAME:	
OWNER CODE 1:	Р		
OWNER CODE 2:			

HISTORIC SIGNIFICANCE

OWNER CODE 3:

*DOE:	REGISTER NAME:
*DOE DATE:	MULTIPLE PROPERTY NAME:
REASON INELIGIBLE:	
	CATEGORY:
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L
REFERENCE NUMBER:	_
HISTORIC DISTRICT RATING: C or NC	CRITERIA 1: A B C D

PERIOD:

CRITERIA 2: A B C D CRITERIA 3: A B C D CRITERIA 4: A B C D

SIGNIFICANCE NOTES:

STRUCTURE DETAILS

* = REQUIRED FIELD



Horse barn	_ FOUNDA	TION:	
Storage	_ ROOF MATE	RIAL:	Steel roofing over cedar shingles
Livestock barn	ROOF SH	IAPE:	Gable
Hay and grain storage	STRUCTURAL SYS	STEM:	Balloon framing
	_		Western Feeder
	S	TYLE:	barn
Yes	-	TYPE:	Livestock barn
			2x4 studs, 1x6 #106
			drop siding & steel
permission	WALLS:		roofing
2	SIGNIFICANT PERSON:	Th	neo Kron
Late 1800,s Cl	JLTURAL AFFILIATION:		?
	Livestock barn Hay and grain storage Yes ? Yes with permission 2	StorageROOF MATELivestock barnROOF SHHay and grain storageSTRUCTURAL SYSYesS? Yes with permissionWALLS:2SIGNIFICANT PERSON:	StorageROOF MATERIAL:Livestock barnROOF SHAPE:Hay and grain storageSTRUCTURAL SYSTEM:YesSTYLE:Yes withTYPE:? Yes withWALLS:2SIGNIFICANT PERSON:

ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions has been removed. Foundation has been repaired with some poured concrete. Wood cupola was rotted out. Replaced with two metal cupalo's from another barn when steel was put on the roof. Walls are covered with steel roofing. Milk room in the SW corner of the center of barn has been remodeled into a tack room.

INTERIOR NOTES: Has two rows of spaced 2x6 posts, with 4x6's for a beam, a 2x6 solid wall in 16' from the North wall and a 2x6 solid wall in 15' from the South wall. Floor joists are 2x6's. Milk cow stanchions were on the North side in the center part of the barn. Horse stalls were on the South side of the center part of the barn. The North side was open for livestock and the South side has 10" poles 9' O. C. with a 10" pole for a beam and is open between poles.

OTHER NOTES: <u>2x6 stud walls with 1x6 #106 drop siding and steel roofing. Roof covered with steel</u> roofing. Windows appear to have been replaced with house windows. Rafters are 2x6. 2x6 open stud

walls extend into hayloft up to rafters supporting the rafters with a 2x6 beam. All of the studs are 20"


O. C. but the rafters are 24" O. C.

*PHYSICAL NOTES: Barn is in very good condition.


*UTM ZONE:	*RESTRICTED:	Y or N	N
*UTM EASTING:			
*UTM NORTHING:			




SKETCH MAP



WEST ELEVATION







PHOTOGR

* = REQUIRED FIELD

* = REQUIRED FIELD

4






 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 February 5, 2013
 PHOTO NUMBER:

February 5, 2013





PHOTOGRAPHER: ____ DATE OF PHOTO:

 ROLL NUMBER:

 PHOTO NUMBER:
 2

 CAMERA DIRECTION:
 Looking NW, SE corner










PHOTOGRAPHER: _____ DATE OF PHOTO: Jim Stone February 5, 2013 ROLL NUMBER: PHOTO NUMBER:

```
5
```

First floor, South lean-to, looking SW, note 10" posts and 10" round beam supporting roof CAMERA DIRECTION: and hayloft floor.



* = REQUIRED FIELD






PHOTOGRAPHER: Jim Stone February 5, 2013 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER:

First floor, remodeled milk room into a tack room in the SW corner of the center of barn,

7




CAMERA DIRECTION: looking SW

8 Hayloft, looking East, CAMERA DIRECTION: gable end and rafters.



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	February 5, 2013	PHOTO NUMBER:	9 Howleft looking NE 9'
			Hayloft, looking NE, 8' wall supporting center of rafters, studs are 20" O. C. and rafters are 24" O.
		CAMERA DIRECTION:	





PLEASANT VALLEY TWP.

© Farm & Home Publishers, Ltd.

35

CLAY CO., SD



HISTORY

This farm located in the W ¹/₂ of the NE ¹/₄ and the W ¹/₂ of the SE ¹/₄ in Section 35, Riverside Township, Clay County was homesteaded by Ellen Nelseen.

The 1894 Clay County Atlas lists Oscar Vronsteldt and Theodore Kron as the owners.

The 1910 Clay County Atlas lists Theodore Kron as the owners.

The 1912 and 1924 Clay County Atlas lists Emil Kron as the owner.

The 1937 Clay County Atlas lists Emil Kron and J. Gobsk as the owners.

The 1948 and 1956 Clay County Atlas lists L. L. Anderson as the owner.

* = REQUIRED FIELD

