

SITE INFORMATION

*SURVEY DATE: January 18, 2013

*ADDRESS: 46562 312th Street

*COUNTY: Clay

*SURVEYOR: Jim Stone

*CITY: Vermillion

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50, East 2 miles to Greenfield Road, turn left (North) 5-1/2 miles to 312th Street turn left (West), about 2-1/3 miles, on the right (North) side.

LEGAL DESCRIPTION: SW 1/4, SE 1/4, Exc. Lots H 1 & H 2, 17–93 – 51 Prairie Center Twp.

*QUARTER 1:	SW 1/4	OWNER NAME:	Matthe	ew E	. Ols	on				
*QUARTER 2:	SE 1/4	OWNER ADDRESS:	46562	312 ^t	th Str	eet				
*TOWNSHIP:	Prairie Center	OWNER CITY:	Vermil	llion						
*RANGE:	51	OWNER STATE:	South	Dak	ota					
*SECTION:	17	OWNER ZIP:	57069							
ACRES:	38.50	QUAD NAME:								
OWNER CODE 1:	Р									
OWNER CODE 2:										
OWNER CODE 3:										
HISTORIC SIGN	IFICANCE									
*D0	OE:	REGISTER NA	AME:							
*DOE DA	TE:	MULTIPLE PR	OPERT	Y N/	AME:	:				
REASON INELIGIB	LE:									
			С	ATE	GOF	RY:				
NOMINATIO	N STATUS:	SIGNI	FICANC	ELE	EVEL	. 1:	Ν	S	L	
DA	TE LISTED:	SIGNI	FICANC	ELE	EVEL	. 2:	Ν	S	L	
REFERENCE	NUMBER:									
HISTORIC DISTRIC	TRATING: C or	NC CRITE	ERIA 1:	Α	В	С	D			
	PERIOD:	CRITE	ERIA 2:	Α	В	С	D			
		CRITE	ERIA 3:	Α	В	С	D			
		CRITE	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NO	TEQ.									
SIGNIFICANCE NO	123:									
STRUCTURE DE	TAILS									



SHPO ID:			
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Machinery storage	FOUNDATION:	Poured concrete foundation
CURRENT SUBFUNCTION:	Machinery storage	ROOF MATERIAL:	Asphalt shingles over cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Western feeder barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x6 & 2x4 studs, sheathing & ½"x6" cedar lap siding
			· · · · · · · · · · · · · · · · · · ·
STORIES:	2	SIGNIFICANT PERSON:	Theo Anker
*DATE OF CONSTRUCTION:	1910 to 1920	CULTURAL AFFILIATION:	?

ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions or horse stalls has been removed in the center of barn. Hayloft floor has been removed except the North 8'. A lot of bracing added to re-enforce rafters after removing hayloft floor. Large 17' x 13' sliding doors added on the South wall to allow large machinery into barn. 44' x 29' pole barn lean-to added on the East side.

INTERIOR NOTES: <u>Had two rows of 6x6 posts, with 6x6's for beams</u>. Floor joists are 2x8's for hayloft floor. Three single horse stalls and cattle shelter still in place on the West lean-to.

OTHER NOTES: 2x6 stud walls with 1/2"x6" drop siding. The 7' West wall is 2x4 studs. The 2x6


studs on the 18' wall on the West wall of the center barn are 2' O.C. with 1x10 shiplap on the first floor.

The studs are double in hayloft and 4' O. C. on the same West wall. Rafters are 2x6's with 2x6 bracing. 2 x 8 floor joists that were removed have been used as bracing to re-enforce the rafters, after the hayloft floor was removed. Windows are 9" x 12" four light. Metal cupola is still in place.

*PHYSICAL NOTES: <u>Barn is in good condition.</u>

*UTM ZONE:	*RESTRICTED:	Y or	N
*UTM EASTING:			
*UTM NORTHING:			






SKETCH MAP



SKETCH MAP



SOUTH ELEVATION

PHOTOGR





Jim Stone PHOTOGRAPHER: DATE OF PHOTO: January 18, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner


1



PHOTOGRAPHER: DATE OF PHOTO: January 18, 2013

2 **PHOTO NUMBER:** CAMERA DIRECTION: Looking NW, SE corner









PHOTOGRAPHER: _____ DATE OF PHOTO: Jim Stone January 18, 2013 ROLL NUMBER: PHOTO NUMBER:

5 First floor, West lean-to, looking South, one of the single horse stalls on

CAMERA DIRECTION: South wall.




PHOTOGRAPHER: Jim Stone DATE OF PHOTO: January 18, 2013

ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 6 First floor, looking up, double 2x6 studs on the West wall of center of barn and 2x6 original bracing and 2x8 added CAMERA DIRECTION: bracing.





PHOTOGRAPHER:	Jim Stone		
DATE OF PHOTO:	January 18, 2013		


ROLL NUMBER: PHOTO NUMBER:

First floor, looking up, 2x8 cross bracing to reenforce rafters after removing havloft floor.

7

CAMERA DIRECTION: removing hayloft floor.





33

CLAY CO., SD

© Farm & Home Publishers, Ltd.



HISTORY

This farm located in the SE ¼ of Section 17, Prairie Center Township, Clay County was homesteaded by August Nyman.

The 1894 Clay County Atlas lists H. G. & M. H. Anderson as the owners.

1901 and 1912 Clay County Atlas lists Theo. Anker as the owner.

The 1924, 1937, 1948 and 1956 Clay county Atlas lists B. K. Jaeger as the owner.