""SITE INFORMATION




OHE IN ORMATION										
*SURVEY DATE: De	ecember 18, 2013	*ADDRESS: _30717 University Road								
*SURVEYOR: Jir	m Stone	*COUNTY:								
		*CITY:	Vermillio	n						
LOCATION DESCRIPTION: Fr	om Vermillion, South	Dakota Highwa	y 50 East a	bout 4 n	niles to	o 469) th Ave	е.,		
turn left (North) about 1/2 mile to 317 th Street, turn right (East) about ½ mile on the left (North) side.										
•				•	-					
LEGAL DESCRIPTION: Lyckholm Tract 1 in NE 1/4, NE ¼, 30 – 94 – 51 Garfield Twp.										
*QUARTER 1: <u>NE 1/4</u>		OWNER NAME: Scott H. & Sandra Kern Mollman								
*QUARTER 2:	OWN	NER ADDRESS: 30717 University road								
*TOWNSHIP: Garfield		OWNER CITY:	NER CITY: Vermillion							
*RANGE: <u>51</u>	O'	WNER STATE:	E: South Dakota							
*SECTION: 30		OWNER ZIP:	OWNER ZIP: 57069							
ACRES: 8.44		QUAD NAME:								
OWNER CODE 1: P										
OWNER CODE 2:										
OWNER CODE 3:										
HISTORIC SIGNIFICANCE										
HISTORIC SIGNIFICANCE										
*DOE:		REGISTER NAME:								
*DOE DATE:		MULTIPLE PROPERTY NAME:								
REASON INELIGIBLE:										
		CATEGORY:								
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:		SIGNII	FICANCE L	EVEL 2:	N	S	L			
REFERENCE NUMBER:										
HISTORIC DISTRICT RATING:		_	RIA 1: A	_						
PERIOD:			RIA 2: A							
			RIA 3: A							
		CRITE	RIA 4: A	ВС	D					
SIGNIFICANCE NOTES:										

STRUCTURE DETAILS



SHPO ID:		_						
*PROPERTY NAME:								
OTHER NAME:								
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete					
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Cedar shingles					
	Ear corn and grain							
HISTORIC FUNCTION:	storage	ROOF SHAPE:	Gable roof					
LISTODIC SUBEUNCTION.	Livestock shelter and	STRUCTURAL SVSTEM.	Dallaan framing					
HISTORIC SUBFUNCTION:	machinery storage	STRUCTURAL SYSTEM:	Gable roof double					
		STYLE:						
		OTTEE.	Double corncrib with					
OCCUPIED:	Yes	TYPE:	granary above					
			2x6 studs, and 1x8					
	Yes with		shiplap & 1/2"x 6"					
ACCESSIBLE:	permission	WALLS:	cedar lap siding.					
STORIES:	:2	SIGNIFICANT PERSON:						
*DATE OF CONSTRUCTION:	: 1915 to 1925 CU	LTURAL AFFILIATION:						
ALTERED/MOVED NOTES:	Original site West 14's	(32) lean-te added later Anoth	or 12' v 32' loan-to					
ALTERED/MOVED NOTES: Original site. West 14' x 32' lean-to added later. Another 12' x 32' lean-to								
was added later yet on the West side of the first lean-to. Concrete foundations are stair stepped down to The West to the slope of the land. Walls in the overhead granary have been removed. Can not tell if it was								
•			i. Can not ten ii it was					
one large granary or was divided into separate granaries.								
INTERIOR NOTES: Two 10'	x 8' and one 12' x 8' grar	nary on the East side. One 14'	x 8' and one 18' x 8'					
ear corncribs on the West side. The corncribs have 2x6 studs with 1x6's spaced on both the East and								
West walls. The floors have 2x 10 floor joists 2' O. C. supported on about 2' high concrete foundations.								
OTHER NOTES: 2x6 stud walls with 1x8 shiplap and ½" x 6" cedar lap siding on the exterior walls. The								
first lean-to has 2x4 walls, 1x8 shiplap and ½" x 6" cedar lap siding. The second lean-to has 2x4 studs,								
1x8 shiplap and 1-1/4"x 26" galvanized, corrugated steel roofing applied horizontally. The interior walls								
are lined with planks up about 3'. This may have been shelter for swine. The rafters are all 2x6. 3" x 12" x 14' bridge plank 2' O. C. are floor joists above the drive alley support a 10' x 32' granary is above.								
*PHYSICAL								
NOTES: Structur	re is in fair condition.	*RESTRICTED: Y o	r N					
*UTM EASTING:								









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 18, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 18, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: December 18, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 18, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 18, 2013**

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW at corncribs on the West side, 2x6 studs, 1x6 boards spaced & 2x10 joists supporting the

CAMERA DIRECTION: floor.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone **December 18, 2013**

ROLL NUMBER: PHOTO NUMBER:

Second floor, looking NW, into granary above drive alley, 1x8 shiplap has been removed from

CAMERA DIRECTION: the side walls.





21

© Farm & Home Publishers, Ltd.



HISTORY

This farm located in the NE ¼ of the NE ¼ of Section 30, Garfield Township, Clay County was homesteaded by Hans Anderson. He homesteaded 40 acres.

The 1894 Clay County Atlas lists Hans Anderson as the owner.

The 1901 Clay County Atlas lists Wallace Cusick as the owner.

The 1912 Clay County Atlas lists Theodore Anker as the owner.

The 1924 Clay County Atlas lists John Norder as the owner.

The 1937 Clay County Atlas lists Alfreda & J. L. Samuelson as the owners.

The 1948 Clay County Atlas lists A. Samuelson as the owner.

The 1956 Clay County Atlas lists A. Lykholm as the owner.