

SITE INFORMATION

| *SURVEY D | ATE: Octol | 2012 | *ADDRESS: 46852 Burbank Road | | | | | | | | | |
|----------------------|--|----------------------------|------------------------------|----------------------------------|-------------------|-------|------|-------|--------|-------|-----|--|
| *SURVEYOR: Jim Stone | | | | *COUNTY | Clay | | | | | | | |
| | | | | *CITY | : Burb | ank | | | | | | |
| | | | | | | | | | | | | |
| LOCATION DESCR | IPTION: F | rom int | ersection of | Main Street and D | akota S | treet | in V | erm | illion | . Soı | uth | |
| | About ¼ mile to Burbank Road, turn left (East), fallow This road about 5 miles, turn Left (North) at | | | | | | | | | | | |
| address 46852 Bu | rbank Road. | | | | | | | | | | | |
| | | | | | | | | | | | | |
| LEGAL DESCRIPTI | ON: Macy | Tract 1 | of NW ¼, NE | 1 1/4 & NE 1/4, NW 1/4 | 4, 35 – 9 | 2 – 5 | 51 F | airvi | ew T | wp. | | |
| | | | | | | | | | | | | |
| *QUARTER 1: | NW 1/4 | /4 OWNER NAME: Kevin Lynch | | | | | | | | | | |
| *QUARTER 2: | | | | WNER ADDRESS: 46852 Burbank road | | | | | | | | |
| *TOWNSHIP: | Fairview | | | | NED CITY: Burbank | | | | | | | |
| *RANGE: | 51 | | | OWNER STATE: | | | | | | | | |
| *SECTION: | 35 | | | | P: 57010 | | | | | | | |
| ACRES: | 9.82 | | | QUAD NAME: | | | | | | | | |
| OWNER CODE 1: | P | | | QUAD NAME. | | | | | | | | |
| OWNER CODE 2: | • | | | | | | | | | | | |
| OWNER CODE 3: | | | | | | | | | | | | |
| OWNER CODE O. | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HISTORIC SIGN | <u>IFICANCE</u> | | | | | | | | | | | |
| *DOE: | | | | REGISTER NAME: | | | | | | | | |
| *DOE DATE: | | | | MULTIPLE PROPERTY NAME: | | | | | | | | |
| REASON INELIGIBLE: | | | | | | | | | | | | |
| | - | | | | | | | | | | | |
| | | | | CATEGORY: | | | | | | | | |
| NOMINATIO | N STATUS: | | | SIGNIFICANCE LEVEL 1: N S L | | | | | | | | |
| DA | TE LISTED: | | | SIGN | IFICANO | E LE | VEL | 2: | N | S | L | |
| REFERENCE | NUMBER: | | | | | | | | | | | |
| HISTORIC DISTRIC | T RATING: | C or | NC | CRIT | ERIA 1: | Α | В | С | D | | | |
| | PERIOD: | | | CRIT | ERIA 2: | Α | В | С | D | | | |
| | | | | | ERIA 3: | Α | В | С | D | | | |
| | | | | CRIT | ERIA 4: | Α | В | С | D | | | |
| SIGNIFICANCE NO | TES: | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |


STRUCTURE DETAILS




| SHPO ID: | | _ | | | | | | | | | | |
|--|------------------------------|---|---|--|--|--|--|--|--|--|--|--|
| *PROPERTY NAME: | | | | | | | | | | | | |
| OTHER NAME: | | | | | | | | | | | | |
| CURRENT FUNCTION: | Storage | FOUNDATION: | | | | | | | | | | |
| CURRENT SUBFUNCTION: | Storage | ROOF MATERIAL: | Steel roofing over cedar shingles | | | | | | | | | |
| HISTORIC FUNCTION: | Livestock barn | ROOF SHAPE: | Gambrel | | | | | | | | | |
| HISTORIC SUBFUNCTION: | Hay and grain storage | STRUCTURAL SYSTEM: | Balloon framing | | | | | | | | | |
| | | STYLE: | Gambrel roof barn | | | | | | | | | |
| OCCUPIED: | Yes | TYPE: | Livestock barn | | | | | | | | | |
| ACCESSIBLE: | Yes with permission | WALLS: | 2x6 stud with 1x8 sheathing and 1/2"x6" cedar lap siding. | | | | | | | | | |
| STORIES: | 2 | SIGNIFICANT PERSON: | Wallace L. Cusick | | | | | | | | | |
| *DATE OF CONSTRUCTION: | | | | | | | | | | | | |
| ALTERED/MOVED NOTES: Original site. Roof covered with steel roofing. | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| INTERIOR NOTES: Has two | rows of 6x6 posts 10' C |). C. with 6x8 beams. 2x10 floo | r joists. All of the | | | | | | | | | |
| 2x6's, 2x10's, 2x12's, 6x6's, 6 | 6x8's and ¾" roof sheat | ning lumber is rough sawn cott | onwood. Granaries | | | | | | | | | |
| | still in place. Five doub | le horse stalls and one single h | orse stall are still | | | | | | | | | |
| in place. OTHER NOTES: 2x6 stud w | alls with 1x8 sheathing | (sheathing is actually 1x8 red page 1 | ainted siding that | | | | | | | | | |
| has been salvaged and applie | ed backwards) and ½"x6 | 6" cedar lap siding. Rafters are | 2x6 with (2) 1x6 | | | | | | | | | |
| braces at the hip. A 2x12 bra | ce, 4'-6'-8'-4'-8'-4'-6' O.0 | c. from South end, runs from the | e center of top rafter | | | | | | | | | |
| down to the floor. 1x6 braces | s tie this 2x12 brace to t | he rafters at three points. It cre r has three 9"x12" four light wir | ates ½ of a Shawver | | | | | | | | | |
| *PHYSICAL NOTES: Barn is | s in good condition. Ha | s a lot of water stains from the | roof leaking before | | | | | | | | | |
| the new steel roof was applied. | | | | | | | | | | | | |
| •• | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | or N | | | | | | | | | |
| *UTM EASTING: | | | | | | | | | | | | |
| *UTM NORTHING: | | | | | | | | | | | | |




SKETCH MAP







SKETCH MAP



SOUTH ELEVATION

PHOTOGR





ROLL NUMBER: PHOTOGRAPHER: Jim Stone October 24, 2012 DATE OF PHOTO:

PHOTO NUMBER: CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

October 24, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner






PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: October 24, 2012 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 24, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: October 24, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW, granary in SW corner

CAMERA DIRECTION: and stairs to hayloft



PHOTOGRAPHER: DATE OF PHOTO: October 24, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SE, granary in SE corner, note water stains on joists and granary wall from roof leaking before

CAMERA DIRECTION: the new roof.





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 24, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, posts and beam and CAMERA DIRECTION: horse stalls on East wall.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 24, 2012

ROLL NUMBER:

PHOTO NUMBER:

Hayloft, looking North,

2x12 bracing, almost ½

CAMERA DIRECTION: of Shawver truss.

* = REQUIRED FIELD





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 24, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, 2x12 brace and leat-to CAMERA DIRECTION: framing on West side.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 24, 2012


ROLL NUMBER: PHOTO NUMBER:

10

Hayloft, looking North, gable end, sheathing is 1x8 recyled siding painted red and applied

CAMERA DIRECTION: face side in.







HISTORY

This farm located in the NW ¼ and the NE ¼ of the NW ¼ of Section 35, Fairview, Township, Clay County was homesteaded by Jesse Fisher.

The 1894 and 1901 Clay County Atlas lists Caroline Maynard as the owner.

The 1912 Clay County Atlas lists F. H. Maynard as the owner.

The 1924, 1937 and 1948 Clay County Atlas lists Wallace L. Cusick as the owner.

The 1956 Clay County Atlas lists Laverne Macy as the owner.

The Following Information Courtesy of

Clay County Historical Society

Wallace L. Cusick was born October 11, 1875 at Burbank, South Dakota. His parents were Nelson William Cusick and Anna Louise (Ladieu). They homesteaded in Section 26, less that a ½ mile from this farm.

Farm was bought by Wallace Cusick. He built this barn in 1927. He had a sawmill on his farm, which was just over a 1/2 mile northwest of this farm. He cut the cottonwood logs on his farm, which was the original homestead and sawed the lumber for this barn.

His daughter LaVerne Belle, who married Arthur Solomon Macy February 12, 1919, rented this farm from Wallace and then later bought the farm.

